The Union Switch & Signal Co. Swissvale, Pa.

1907

Electro-Pneumatic Catalogue

### A CATALOGUE AND PRICE LIST

OF

### Interlocking and Signaling Devices

MADE BY

# THE UNION SWITCH & SIGNAL CO.

OF PITTSBURGH, PA.

Owners of the Westinghouse System of Electro-Pneumatic Block Signaling and Interlocking.

Also Designers, Manufacturers and Erectors of Pneumatic, Electro-Pneumatic, Electric, Electro-mechanical, and Purely Mechanical Appliances for Railway Protection.

Automatic, Semi-automatic and Manually Operated Block Signals.

Electro-Pneumatic, Electric and Mechanical Interlockings to suit conditions.

Plans and Estimates on Application.

General Offices and Works SWISSVALE, PA.

New York Central Bldg. Chicago Monadnock Bldg. St. Louis Frisco Bldg. The Union Switch & Signal Company's Publishing Department, Swissvale, Pa. Werner Press, Akron, Ohio


### ELECTRO-PNEUMATIC CATALOGUE

#### PREFACE

HIS Catalogue covers the latest designs of Electro-Pneumatic Appliances for interlocking and block signaling. Switch fittings, such as detector bars, rods, etc., common to all interlocking systems, will be found in our Mechanical Catalogues, while appliances used for the Automatic Control of both Electro-Pneumatic and Electric Signals are listed in our Catalogues covering such articles.

#### ORDERS

In ordering material from this Catalogue, the plate and figure number should be given in all cases. Also such other information as may be called for in the notes or lists.



THE ELECTRO-PNEUMATIC INTERLOCKING MACHINE Horizontal Roller Type


#### Horizontal Roller Type

In ordering Electro-Pneumatic Interlocking Machines, a signaled track plan should be furnished, drawn to the scale of not over one hundred feet to the inch. This plan must show the location of the tower and the relation of the front of the machine to the track, and also the route or routes to be governed by each signal. It must also indicate the switches which are to be controlled by one lever, unless it is preferred to leave this to our judgment. If any special mechanical locking or electric appliances are required which would not ordinarily be included, full information concerning these must accompany the order. List prices shown on this page are based on machine cases being made of oak, and do not include track models, or special attachments for electric detector circuits, for which special quotations will be furnished, on application, to cover the particular layout of tracks.

The front of a machine is that part occupied by a man when operating the levers.

Order by Plate, Figure and Instructions Given Above

	CAPAC	ITY OF	MACHINE	PRINCIPAL DIM	IENSIONS	Draw'g	LIST	PRICE
Fig.	I,evers	Lock'g Bars	Combin't'n Grooves	Length   Width (Outside of Case)	Height to Center of Levers	C-2826 Letter	Per Lever	Per Space
I	2	2	22	1' 3" 2' 11 1/4"	0' 105/16"	A	156 00	51 00
2	5	20	22	2' 0" 3' 6%	3' 27/8"	В	156 00	51 00
3	II	20	22	2' 2" 3' 67%"	3' 276"	В	156 00	51 00
4	17	20	22	4' 6" 3' 676"	3 2/8	В	156 00	51 00
4a	17	30	28	4' 6" 4' I'16"	3' 278" 3' 278"	C	156 00	51 00
4b	17	30	35	4' 6" 4' 5"	3' 27/8"	D	156 00	51 00
5	23	20	22	E' 0" 2' 676"	3 2/8	В	156 00	51 00
5a	23	30	28	5' 9" 4' 1116"	3' 27/8"	C	156 00	51 00
5b	23	30	35	5' 9" 4' 5"	3' 27/8"	D	156 00	51 00
6	29	30	28	7' 0" 4' 11/16"	3' 27/8"	C	156 00	51 00
6a	29	30	35	7' 0" 4' 5"	3' 27/8"	D	156 00	51 00
7	35	30	28	8' 3" 4' 11/16"	3' 27/8"	C	156 00	51 00
7a	35	30	35	8' 3" 4' 5"	3 21/8	D	156 00	51 00
8	47	36	28	10' 9''4' 378"	3' 276"	E	171 00	54 00
8a	47	48	28	10' 9" 4' 1078"	3' 27/8"	F	171 00	54 00
9	59	48	28	13' 3" 4' 10%"	3' 278" 3' 278"	F	171 00	54 00
9a	59	60	28	13' 3" 5' 41/8"	3' 27/8"	G	171 00	54 00
10	71	60	28	15' 9" 5' 418"	3' 278" 3' 278"	G	171 00	54 00
Ioa	71	72	35	15' 0" 6' 118"	3' I 1/8"	H	171 00	54 00
II	83	60	28	18' 3" 5' 41/8"	3' 27/8"	G	171 00	54 00
ııа	83	72	35	18' 3" 6' 11/8"	3' 1½" 3' 2½"	H	171 00	54 00
12	95	60	28	20' 9" 5' 418"	3' 27/8"	G	171 00	54 00
12a	95	72	35	20' 0' 0 I 18	3 1-6	H	171 00	54 00
13	107	60	28	23 3 5 4%	3' 27'8'' 3' 11'8''	G	171 00	54 00
13a	107	72	35	23 3 0 1-9	3' 118"	H	171 00	54 00
14	119	72	35	25 0 0 156	4 1 70	H	186 00	57 0
14a	119	108	35	25 4 1/ 0%	5 1 70	H	186 00	57 00
15	131	72	35	28' 3" 6' 118"	4 17R	I	0.0	57 00
15a	131	108	35	28' 3" 7' 65%" 30' 9" 6' 11%"	3' 118"	H	186 00	57 00
16	143	72	35		1 1 70	I	186 00	31
16a	143	108	35	30' 9" 7' 658" 33' 3" 6' 116"	5 178	H		21
17	155	72	35	133 4 10 150	3' 118"	I	186 00	31
17a	155	108	35	33' 3" 7' 65%" 35' 9" 6' 11%"	3' 11/8"	H	186 00	20
18	167	72	35 -		3' 118"	I	186 00	31
18a	167	108	35	35' 9" 7' 65%"	3' 118"	I	186 00	57 00
19	179	108	35	38' 3" 7' 65%" 40' 9" 7' 65%"	3' 118"	I	186 00	57 O
20	191	108	35	40' 9" 7' 65'8" 43' 3" 7' 65'8"	3' 118"	Ī	186 00	57 0
21	203	108	35	43' 3" 7' 658" 45' 9" 7' 658"	3' 11/8"	I	202 00	
22	215	100	35	45' 9" 7' 65%"	3 178	1	202 00	000



THE ELECTRO-PNEUMATIC INTERLOCKING MACHINE
Horizontal Roller Type, Details

#### Horizontal Roller Type, Details

The front of a machine is that part occupied by a man when operating the levers.

#### Order by Plate and Figure

rig.  Leg only, as shown, for machine having one 15-way or one 18-way locking bracket.  Ia as above, for machine having one 10-way locking bracket.  Ib as above, for machine having two 12-way locking brackets.  Ic as above, for machine having two 15-way locking brackets.  Id as above, for machine having two 18-way locking brackets.  Id as above, for machine having two 18-way locking brackets.  Ie as above, for machine having three 18-way locking brackets.  24 00  Right Hand Channel Bar only, as shown, for machine having one 15-way locking bracket and 28 groove	
one 18-way locking bracket. 14 70  Ia as above, for machine having one Io-way locking bracket. 10 00  Ib as above, for machine having two 12-way locking brackets 16 00  Ic as above, for machine having two 15-way locking brackets. 19 00  Id as above, for machine having two 18-way locking brackets. 24 00  Ie as above, for machine having three 18-way locking brackets. 32 50  Right Hand Channel Bar only, as shown, for machine	
as above, for machine having one Io-way locking bracket. Io oo  Ib as above, for machine having two 12-way locking brackets I6 oo  Ic as above, for machine having two 15-way locking brackets. I9 oo  Id as above, for machine having two 18-way locking brackets. 24 oo  Ie as above, for machine having three I8-way locking brackets. 32 50  Right Hand Channel Bar only, as shown, for machine	
locking bracket. 10 00  Ib as above, for machine having two 12-way locking brackets 16 00  Ic as above, for machine having two 15-way locking brackets. 19 00  Id as above, for machine having two 18-way locking brackets. 24 00  Ie as above, for machine having three 18-way locking brackets. 32 50  Right Hand Channel Bar only, as shown, for machine	
1b as above, for machine having two 12-way locking brackets	
locking brackets	
as above, for machine having two 15-way locking brackets	
locking brackets	
as above, for machine having two 18-way locking brackets. 24 00  1e as above, for machine having three 18-way locking brackets. 32 50  2 Right Hand Channel Bar only, as shown, for machine	
locking brackets. 24 00  1e as above, for machine having three 18-way locking brackets. 32 50  2 Right Hand Channel Bar only, as shown, for machine	
as above, for machine having three 18-way locking brackets	
locking brackets	
locking brackets	
2 Right Hand Channel Bar only, as shown, for machine	
having one 15-way locking bracket and 28 groove	
Harring one -) may received	
combination plate 12 00	
2a as above, for machine having one 10-way	
locking bracket and 22 groove combination plate 11 70	
2b as above, for machine having one 15-way	
Tocking official and 33 gravit	
as above, for machine having one 18-way	
locking bracket and 28 groove combination plate. 12 00	
2d as above, for machine having two 12-way	
locking brackets and 28 groove combination plate. 15 30	
2e as above, for machine having two 15-way	
locking brackets and 28 groove combination plate 15 60	
2f as above, for machine having two 18-way	
locking brackets and 35 groove combination plate. 16 50	

#### Horizontal Roller Type, Details

#### Order by Plate and Figure

		I,ist Price	
Fig.			
2g	Right Hand Channel Bar only, for machine having three 18-way locking brackets and 35 groove combination plate.	22 60	
3	Left Hand Channel Bar only, as shown, for machine having one 15-way locking bracket and 28 groove		
	combination plate	12 00	13
за	as above, for machine having one 10-way		
	locking bracket and 22 groove combination plate.	11 70	
3b	as above, for machine having one 15-way		
	locking bracket and 35 groove combination plate.	I2 00	
3c	as above, for machine having one 18-way		
	locking bracket and 28 groove combination plate.	12 00	
3d	as above, for machine having two 12-way		
	locking brackets and 28 groove combination plate.	15 30	
зе	as above, for machine having two 15-way	(-	
	locking brackets and 28 groove combination plate.	15 60	
3f	as above, for machine having two 18-way	+6 -0	
-	locking brackets and 35 groove combination plate. as above, for machine having three 18-way	16 50	
3g	locking brackets and 35 groove combination plate.	22 60	
4	Front Plate only, as shown, for 11 lever section	41 40	
The same	as above, for 17 lever section	54 60	
4a 4b	Right Hand Front Plate only, for 11 lever section	42 60	
40 40	as above, for 17 lever section	55 50	
4d	Left Hand Front Plate only, for II lever section	42 60	
40	as above, for 17 lever section	55 50	

#### Horizontal Roller Type, Details

#### Order by Plate and Figure

		List Price	
Fig.	Front Plate only, for 5 lever machine	20 00	
4g	as above, for II lever machine	41 40	1
4h	as above, for 15 lever machine	49 40	
4j	as above, for 17 lever machine	54 60	
5	Back Plate only, as shown, for II lever machine	35 50	
5a	as above, for 5 lever machine	20 80	
5b	as above, for 15 lever machine	56 60	
5c	as above, for 17 lever machine	54 40	
5d	as above, for II lever section	39 00	
5e	as above, for 17 lever section	56 00	
5f	Right Hand Back Plate only, for 11 lever section	38 40	
58	as above, for 17 lever section	53 00	
5h	Left Hand Back Plate only, for II lever section	38 40	
5j	as above, for 17 lever section	53 00	
6	Intermediate Bearing only, as shown, with lugs for		
	11 lever machine	9 60	
6a	as above, for 5 lever machine	6 20	
6b	as above, for 15 lever machine	12 50	
6c	as above, for 17 lever machine	13 90	
6d	as above, without lugs, for II lever machine.	8 20	
6e	as above, for 17 lever machine	12 20	
7	Moulding, as shown, 30" long	10 00	
7a	as above, 15" long	5 90	
7b	as above, 20" long	7 90	
8	Back Bearing Plate, as shown, for II lever machine.	3 10	
8a	as above, for 5 lever machine	I 62	
8b	as above, for 15 lever machine	4 20	
8c	as above, for 17 lever machine	4 60	

#### Horizontal Roller Type, Details


#### Order by Plate and Figure

Pig.		List Price	
8d	Back Bearing Plate, for 11 lever section	3 12	
8e	as above, for 17 lever section	4 66	
8f	Right Hand Back Bearing Plate, for II lever section.	3 00	
.8g	as above, for 17 lever section	4 50	
8h	Left Hand Back Bearing Plate, for II lever section.	3 30	
8j	as above, for 17 lever section	4 80	
9	Combination Plate, 28 groove, as shown, for 11 lever		
	machine	36 90	
9a	as above, for 15 lever machine	49 20	
9b	as above, for 17 lever machine	53 80	
9c	Combination Plate, 35 groove, for 11 lever machine.	44 80	
9d	as above, for 17 lever machine	66 20	
9e	Combination Plate, 22 groove, for 5 lever machine	15 80	
9f	as above, for II lever machine	31 70	
IO	Bracket, as shown, for supporting case, for machine		
	having channel bars Figs. 2, 2d, 2e, 2f and 2g	5 00	
Ioa	as above, for machine having channel bar		
	Fig. 2a	3 30	
10p	as above, for machine having channel bar		
	Fig. 2b	5 70	
IOC	as above, for machine having channel bar		
	Fig. 2c	5 70	
II	Tie Bar, as shown, for 11 lever machine	2 20	
IIa	as above, for 15 lever machine	2 30	
IIb	as above, for 17 lever machine	2 40	
12	Intermediate Bearing Plate, as shown, for II lever		
	machine	4 90	
12a	as above, for 5 lever machine	2 50	

Horizontal Roller Type, Details

#### Order by Plate and Figure

		List Price
Fig.		
12b	Intermediate Bearing Plate, for 15 lever machine	6 50
12C	as above, for 17 lever machine	6 80
12d	as above, for II lever section	5 30
12e	as above, for 17 lever section	9 70
12f	Right Hand Intermediate Bearing Plate for II lever	
	section	5 22
12g	as above, for 17 lever section	9 70
12h	Left Hand Intermediate Bearing Plate, for II lever	
	section	5 26
12j	as above, for 17 lever section	9 70
13	Locking Bracket only, 15-way, as shown, for 30 bars.	2 10
13a	as above, complete, with cover and machine	
	screws, (1-13, 1-14, Plate 0803), (8-85, 2-82, Plate	
	0807)	2 60
13b	Locking Bracket only, 10-way, for 20 bars	I 90
13c	as above, complete, with cover and machine	
	screws, (1-13b, 1-14a, Plate 0803), (6-85, 2-82, Plate	
	0807)	2 30
13d	Locking Bracket only, 12-way, for 24 bars	2 00
13e	as above, complete, with cover and machine	
	screws, (1-13d, 1-14b, Plate 0803), (6-85, 2-82, Plate	
	0807)	2 42
13f	Locking Bracket only, 18-way, for 36 bars	2 24
13g	as above, complete, with cover and machine	
	screws, (1-13f, 1-14c, Plate 0803), (8-85, 2-82, Plate	
	0807)	2 72
14	Cover, as shown, for 15-way locking bracket	34
14a	as above, for 10-way locking bracket	26
14b	as above, for 12-way locking bracket	28
14c	as above, for 18-way locking bracket	36
15	Bracket, as shown, for supporting back panel of case	3 66
16	Angle Bar, as shown, for 5 lever machine	I 00
16a	as above, for II-lever machine	2 00
16b	as above, for 15 lever machine.	2 10
	as above, for 17 lever machine	2 60



THE ELECTRO-PNEUMATIC INTERLOCKING MACHINE
Details Applicable to the Horizontal or Vertical Roller Type

### Details Applicable to the Horizontal or Vertical Roller Type

The front of a machine is that part occupied by a man when operating the levers.

### Order by Plate and Figure

		Lis! Pric	t e
Fig.			
I	Long Switch Lever, complete, with arm, latch, handle, washer, machine screw for handle, bearing, number plate, and screw for fastening lever to shaft (1-3, 1-5a, 1-12, 1-11, 1-13, 1-9a, 1-15a, Plate 0805),	14	40
70	Long Signal Lever, complete, as above, (1-3, 1-5c, 1-12,		
ıa	1-11, 1-13, 1-9a, 1-15a, Plate 0805) Short Switch Lever, complete, as above, (1-4, 1-6a.	14	40
2	1-12, 1-11, 1-13, 1-9a, 1-15a, Plate 0805) Short Signal Lever, complete, as above, (1-4, 1-6c, 1-12,	14	20
2a	1-11, 1-13, 1-9a, 1-15a, Plate 0805)	14	20
2	Long Switch or Signal Lever Arm.		10
3 4 5 5 8	Short Switch or Signal Lever Arm.		00
A	Latch only, for long switch lever	4	90
देव	Latch, for long switch lever, complete, with spring,		
79	(I-5, I-8a, Plate 0805.)	5	22
(5b	Latch only, for long signal lever	3	10
5c	Latch, for long signal lever, complete, with spring.		
3-	(1-5b, 1-8a, Plate 0805)	3	40
6	Latch only, for short switch lever	4	90
(6a)	Latch, for short switch lever, complete, with spring,		
1	(1-6, 1-8a, Plate 0805)	5	20
√6b	Latch only, for short signal lever,	4	90
6c	Latch, for short signal lever, complete, with spring,		
	(r.6b r.8a Plate 080s)	-5	20
7	Escutcheon Pin, No. 12x1/4", for fastening spring Fig.		
	8 to latch and lever. Price per hundred	I	00
8	Spring only, for latch		22
8a	as above, complete, with escutcheon pins, (1-8,		21
	2-7, Plate 0805)		24
9	Bearing only, for lever handle		90
9a	Bearing, for lever handle, complete, with machine screw, (1-9, 1-10, Plate 0805).	I	80
10	Machine Screw, No. 4-40x13/16", for fastening bearing Fig. 9 to lever arm. Price per hundred	3	00
II	Washer for lever handle Fig. 12		IO
12	Lever Handle, complete, with sleeve	1	80
13	Machine Screw and Nut, $\frac{5}{16}$ "x 2- $\frac{5}{16}$ ", for fastening lever handle to lever arm. Price per hundred	8	00
14	Flat Head Machine Screw, No. 4-40x 4", for fastening		We to be
	number plate to lever. Price per hundred	I	00
15	Number Plate only, for lever. Specify number		40
15a	as above, complete, with screw, (1-15, 1-14,		
	Plate 0805)		42

Details Applicable to the Horizontal or Vertical Roller Type

#### Order by Plate and Figure

		List Price	
		Tire	
Fig.			
16	Blank Number Plate for spare space, complete, with		
	screw, nut, and spring for fastening to front plate		
~	of machine	80	
(17)	Switch Lever Quadrant	2 70	
(18)	Signal Lever Quadrant.	2 70	
19	Crank only, for signal lever circuit controller.	52	
19a	as above, complete, with bearing, machine		
	screw and nut, (1-19, 1-21, 1-20, Plate 0805)	I 60	
19h	Crank only, for signal lever circuit controller at the		
	joint of sections	70	
19c	as above, complete, with bearings, and pivot		
	screws, (1-19b, 1-21a, 1-21b, 2-20a, Plate 0805).	1 50	
20	Machine Screw and Nut, No. 10-32x11/16" for bearing		
	Fig. 21	18	
20a	Fig. 21. Pivot Screw, 5/16"-32x1/2" for bearings Figs. 21a and		
	21b	04	
21	Bearing for crank Fig. 19	80	
2Ia	R. H. Bearing for crank Fig. 19b	40	
21b	L. H. Bearing for crank Fig. 19b	40	1 3 1
22	Circuit Controller Base only, for II lever section	7 60	
22a	as above, for 17 lever section	10 90	
22b	Circuit Controller Base for II lever section, complete,		
	with spacers, contact springs, screws for contact		
	springs, terminal posts and battery strip, (1-22,		
	5-28, 6-23, 6-24, 6-25, 8-26, I-27, Plate 0805)	14 00	1
22C	Circuit Controller Base for 17 lever section, complete,		
	as above, (1-22a, 8-28, 9-23, 9-24, 9-25, 11-26		
	I-27a, Plate 0805)	30 20	
23	Back Contact Spring for circuit controller	80	
24	Front Contact Spring for circuit controller	16	
25	Machine Screw, No. 8-32x38", for fastening contact		
26	spring Fig. 24 to circuit controller base	02	
20	Binding Post, complete, with washers and nuts, for		
27	circuit controller base	IO	
27	Battery Strip, for 11 lever section	.60	
27a 28	as above, for 17 lever section.	80	
29	Spacer, for circuit controller base.	20	
29	Lever Shaft, complete, as shown, with bushings, for		
200	machine having one 10-way locking bracket	3 70	
29a	as above, for machine having one 15-way	280	
29b	locking bracket	3 80	
291)	as above, for machine having one 18-way	4 00	
29C	locking bracketLever Shaft, complete, with three bushings for machine	4 00	THE REAL PROPERTY.
-90	having two 12-way locking brackets	6 50	
29d	as above, for machine having two 15-way	6 50	
-3.	locking brackets.	6 80	3 3 3 3
	Totaling Dideketo	0 00	

Details Applicable to the Horizontal or Vertical Roller Type

#### Order by Plate and Figure

		List Price	
Fig.			
29e	Lever Shaft, complete, as above, for machine having two 18-way locking brackets	6 90	
29f	Lever shaft, complete, with four bushings, for ma- chine having three 18-way locking brackets	7 00	
31	Locking Bar Driver complete, with cap, screws, and set screw	1 00	
32	Machine Screw, No. 10-32x1", for fastening cap to locking bar driver. Price per hundred	2 00	
33	Set Screw, No. 10-32x7/16", for locking bar driver. Price per hundred	2 00	
34	Longitudinal Locking Bar with rack, 1/2"x 1/4". Specify length when ordering. Price per foot	20	
34a	as above, without rack, \( \frac{5}{8}'' \times \frac{1}{4}'' \). Specify length when ordering. Price per foot	16	
35	ordering. Price per foot	16	
36	Trunnion for intermediate shaft bearing	90	
36a 36b	as above, with tapped ends Suspended Trunnion, used at the junction of inter-	I 00	
	mediate shaft bearings	94	
37 38	Track Model Bracket Machine Screw, No. 10-32x¾", for couplings Figs. 39	2 50	
39	and 60. Price per hundred	1 00	
39a	for lever and contact roller shaftsas above, complete, with machine screws and	94	
40	set screw, (1-39, 1-38, 2-41, 1-40, Plate 0805) Set Screw, No. 10-32x7/16", for coupling Fig. 39. Price	I 02	
41	per hundred Machine Screw, No. 4-40x3g", for track model driver	5 00	
43	Fig. 39. Price per nundred	1 00	
43a	groove horizontal spring combination plate as above, for machine having 28-groove	5 80	
43b	horizontal spring combination plate	6 00	
430	horizontal spring combination plate	7 00	
44	Contact Band for contact roller	04	
45 45a	Circuit Shifter Driver only	I 12	
46	set screw, (1-45, 1-38, 1-46, Plate 0805) Set Screw, No. 10-32x7/16", for circuit shifter driver.	I 20	
	Price per hundred	5 00	

Details Applicable to the Horizontal or Vertical Roller Type


#### Order by Plate and Figure

Fig. Set Screw, No. 10–32x7/16", for coupling Fig. 60. Price per hundred.  48 Contact Roller, complete, with machine screw and bushing for fastening to circuit shifter 100 contact Band, for circuit shifter 100 contact Band, for circuit shifter 100 contact Band, for circuit shifter 100 contact band, (1-50, 1-48, 1-49, Plate 0805) 40 contact band, (1-51, 1-53, 1-54, 1-52, Plate 0805) 40 contact band, (1-51, 1-53, 1-54, 1-52, Plate 0805) 40 contact band band band band band band band band				
Set Screw, No. 10–32x7/16", for coupling Fig. 60. Price per hundred.  Contact Roller, complete, with machine screw and bushing for fastening to circuit shifter.  Octroit Shifter only, for switch lever.  Spring Guide, for toggle joint Fig. 51a.  Toggle Joint, for circuit shifter, complete, with spring guide, spring, pivot, machine screw and nut.  (1-51, 1-53, 1-54, 1-52, Plate 0805).  Machine Screw and Nut, No. 6–32x1/2", for toggle joint Fig. 51a.  Pivot for toggle joint Fig. 51a.  Double Circuit Shifter Bracket  Machine Screw, No. 12–32x5/6", for fastening support Fig. 57 to combination plate. Price per hundred.  Support for combination plate, for machine with horizontal spring combination, complete, with machine screws, (1-56, 1-58, Plate 0805).  Machine Screw, No. 12–32x7/6", for fastening support Fig. 57 to channel bar. Price per hundred.  Machine Screw, No. 12–32x7/6", for fastening support Fig. 57, to channel bar. Price per hundred.  Machine Screw, No. 12–32x7/6", for fastening support Fig. 57, to channel bar. Price per hundred.  Support for combination plate, for machine with horizontal spring combination, complete, with machine screws, (1-50, 1-58, Plate 0805).  Machine Screw, No. 12–32x7/6", for fastening support Fig. 57, to channel bar. Price per hundred.  Solution of the per hundred of the pe				
per hundred.  Contact Roller, complete, with machine screw and bushing for fastening to circuit shifter.  General Band, for circuit shifter.  Circuit Shifter only, for switch lever.  as above, complete, with contact roller and contact band, (1-50, 1-48, 1-49, Plate 0805).  Spring Guide, for toggle joint Fig. 51a.  Toggle Joint, for circuit shifter, complete, with spring guide, spring, pivot, machine screw and nut. (1-51, 1-53, 1-54, 1-52, Plate 0805).  Machine Screw and Nut, No. 0=32x½", for toggle joint Fig. 51a.  Pivot for toggle joint Fig. 51a.  Double Circuit Shifter Bracket.  Machine Screw, No. 12-32x½", for fastening support Fig. 57 to combination plate, for machine with horizontal spring combination, complete, with machine screws, (1-56, 1-58, Plate 0805).  Machine Screw, No. 12-32x½", for fastening support Fig. 57, to channel bar. Price per hundred.  Machine Screw, No. 12-32x½", for fastening support Fig. 57, to channel bar. Price per hundred.  Some End Bracket for intermediate bearing.  Coupling only, for lever and contact roller shafts.  Achine Screw, (1-60, 1-38, 1-47, Plate 0805).  Machine Screw, No. 10-32x½", for fastening cap to clamp Fig. 66.  Shaft for indication segments.  Machine Screw, No. 10-32x½", for fastening cap to clamp Fig. 66.  Machine Screw, No. 10-32x½", for fastening cap to clamp Fig. 66.  Clamp Fig. 66. Price per hundred.  Machine Screw, No. 10-32x½", for fastening clamp to indication segment.  Machine Screw, No. 10-32x½", for fastening clamp to indication segment.  Price per hundred.  Machine Screw, No. 10-32x½", for fastening clamp to indication segment.  Machine Screw, No. 10-32x½", for fastening clamp to indication segment.  Machine Screw, No. 10-32x½", for fastening clamp to indication segment.  Machine Screws, No. 10-32x½", for fastening clamp to indication segment.  Machine Screws, No. 10-32x½", for fastening clamp to indication segment.  Machine Screws, No. 10-32x½", for fastening clamp to indication segment.  Machine Screws, No. 10-6, 1-68, 1-66, 1-65, 1-65, 1-66, 1-65, 1	Fig.			
bushing for fastening to circuit shifter	47	per hundred	5 00	
Contact Band, for circuit shifter	48	Contact Roller, complete, with machine screw and		
Circuit Shifter only, for switch lever		bushing for fastening to circuit shifter	NAME OF THE PARTY	
as above, complete, with contact roller and contact band, (1-50, 1-48, 1-49, Plate o805)	49	Contact Band, for circuit shifter		
contact band, (I-50, I-48, I-49, Plate 0805) 44 40  51 Spring Guide, for toggle joint Fig. 51a. 24  Toggle Joint, for circuit shifter, complete, with spring guide, spring, pivot, machine screw and nut. (I-51, I-53, I-54, I-52, Plate 0805). 50  Machine Screw and Nut, No. 6-32x½", for toggle joint Fig. 51a. 10  Spring for toggle joint Fig. 51a. 10  Spring for toggle joint Fig. 51a. 10  Pivot for toggle joint Fig. 51a. 10  Spring for toggle joint Fig. 51a. 10  Spring for toggle joint Fig. 51a. 10  Machine Screw, No. I2-32x½", for fastening support Fig. 57 to combination plate. Price per hundred. 210  Support for combination plate, for machine with horizontal spring combination, complete, with machine screws, (I-56, I-58, Plate 0805) 16  Machine Screw, No. I2-32x½", for fastening support Fig. 57, to channel bar. Price per hundred 20  Machine Screw, No. I2-32x½", for fastening support Fig. 57, to channel bar. Price per hundred 20  Machine Screw, No. I0-32x½", for fastening cap to clamp Fig. 66. Price per hundred 20  Set Screw, No. I0-32x½", for fastening cap to clamp Fig. 66. Price per hundred 20  Machine Screw, No. I0-32x½", for fastening clamp to indication segment. 20  Machine Screw, No. I0-32x½", for fastening clamp to indication segment. 20  Machine Screw, No. I0-32x½", for fastening clamp to indication segment. 20  Machine Screw, No. I0-32x½", for fastening clamp to indication segment. 20  Machine Screw, No. I0-32x½", for fastening clamp to indication segment. 20  Machine Screw, No. I0-32x½", for fastening clamp to indication segment. 20  Machine Screw, No. I0-32x½", for fastening clamp to indication segment. 20  Machine Screw, No. I0-32x½", for fastening clamp to indication segment. 20  Machine Screw, No. I0-32x½", for fastening clamp to indication segment. 20  Machine Screw, No. I0-32x½", for fastening clamp to indication segment. 20  Machine Screw, No. I0-32x½", for fastening clamp to indication segment. 20  Machine Screw, No. I0-32x½", for fastening clamp to indication segment. 20  Machine Screw, No. I0-32	50	Circuit Shifter only, for switch lever	2 10	
Spring Guide, for toggle joint Fig. 51a.  Toggle Joint, for circuit shifter, complete, with spring guide, spring, pivot, machine screw and nut. (1-51, 1-53, 1-54, 1-52, Plate 0805).  Machine Screw and Nut, No. 6-32x½", for toggle joint Fig. 51a.  Pivot for toggle joint Fig. 51a.  Double Circuit Shifter Bracket  Machine Screw, No. 12-32x½", for fastening support Fig. 57 to combination plate, for machine with horizontal spring combination, complete, with machine screws, (1-56, 1-58, Plate 0805).  Machine Screw, No. 12-32x½", for fastening support Fig. 57, to channel bar. Price per hundred.  Machine Screw, No. 12-32x½", for fastening support Fig. 57, to channel bar. Price per hundred.  Support for combination complete, with machine screws, (1-60, 1-38, 1-47, Plate 0805).  Machine Screw, (1-60, 1-38, 1-47, Plate 0805).  Machine Screw, No. 10-32x½", for fastening cap to clamp Fig. 66. Price per hundred.  Set Screw, No. 10-32x½", for fastening cap to clamp Fig. 66. Price per hundred.  Machine Screw, No. 10-32x½", for fastening clamp to indication segment.  Machine Screw, No. 10-32x½", for fastening clamp to indication segment.  Machine Screw, No. 10-32x½", for fastening clamp to indication segment.  Machine Screw, No. 10-32x½", for fastening clamp to indication segment.  Machine Screw, No. 10-32x½", for fastening clamp to indication segment.  Machine Screw, No. 10-32x½", for fastening clamp to indication segment.  Machine Screw, No. 10-32x½", for fastening clamp to indication segment.  Machine Screw, No. 10-32x½", for fastening clamp to indication segment.  Machine Screw, No. 10-32x½", for fastening clamp to indication segment.  Machine Screw, No. 10-32x½", for fastening clamp to indication segment.  Machine Screw, No. 10-32x½", for fastening clamp to indication segment.  Machine Screw, No. 10-32x½", for fastening clamp to indication segment.  Machine Screw, No. 10-32x½", for fastening clamp to indication segment.  Machine Screw, No. 10-32x½;  Machine Screw, No. 10-32x½;  Machine Screw, No. 10-32x½;  Machine Screw, N	50a			
Toggle Joint, for circuit shifter, complete, with spring guide, spring, pivot, machine screw and nut.  (1-51, 1-53, 1-54, 1-52, Plate o805).  Machine Screw and Nut, No. 6-32x½", for toggle joint Fig. 51a.  Price per hundred.  Spring for toggle joint Fig. 51a.  Double Circuit Shifter Bracket  Single Circuit Shifter Bracket  Machine Screw, No. 12-32x½", for fastening support Fig. 57 to combination plate. Price per hundred.  Machine Screw, (1-56, 1-58, Plate o805).  Machine Screw, No. 12-32x½", for fastening support Fig. 57, to channel bar. Price per hundred.  Machine Screw, No. 12-32x½", for fastening support Fig. 57, to channel bar. Price per hundred.  Coupling only, for lever and contact roller shafts.  Machine Screw, (1-60, 1-38, 1-47, Plate o805).  Machine Screw, No. 10-32x½", for fastening cap to clamp Fig. 66. Price per hundred.  Machine Screw, No. 10-32x½", for cap Fig. 65. Price per hundred.  Machine Screw, No. 10-32x½", for fastening clamp to indication segment.  Machine Screw, No. 10-32x½", for fastening clamp to indication segment. Price per hundred.  Machine Screw, No. 10-32x½", for fastening clamp to indication segment. Price per hundred.  Machine Screw, No. 10-32x½", for fastening clamp to indication segment. Price per hundred.  Machine Screw, No. 10-32x5½", for fastening clamp to indication segment. Price per hundred.  Machine Screw, No. 10-32x5½", for fastening clamp to indication segment. Price per hundred.  Machine Screw, No. 10-32x5½", for fastening clamp to indication segment. Price per hundred.  Machine Screw, No. 10-32x5½", for fastening clamp to indication segment. Price per hundred.  Machine Screw, No. 10-32x5½", for fastening clamp to indication segment. Price per hundred.  Machine Screw, No. 10-32x5½", for fastening clamp to indication segment. Price per hundred.  Machine Screw, No. 10-32x5½", for fastening clamp to indication segment. Price per hundred.  Machine Screw, No. 10-32x5½", for fastening clamp to indication segment. Price per hundred.				
guide, spring, pivot, machine screw and nut. (1-51, 1-53, 1-54, 1-52, Plate o805).  52 Machine Screw and Nut, No. 6-32x½", for toggle joint Fig. 51a. Price per hundred.  53 Spring for toggle joint Fig. 51a.  54 Pivot for toggle joint Fig. 51a.  55 Double Circuit Shifter Bracket  56 Machine Screw, No. 12-32x½", for fastening support Fig. 57 to combination plate. Price per hundred.  57 Support for combination plate, for machine with horizontal spring combination, complete, with machine screws, (1-56, 1-58, Plate o805).  58 Machine Screw, No. 12-32x½", for fastening support Fig. 57, to channel bar. Price per hundred.  59 End Bracket for intermediate bearing.  60 Coupling only, for lever and contact roller shafts.  60 Coupling only, for lever and contact roller shafts.  60 Shaft for indication segments.  61 Shaft for indication segments.  62 Machine Screw, No. 10-32x½", for fastening cap to clamp Fig. 66. Price per hundred.  63 Set Screw, No. 10-32x½", for cap Fig. 65. Price per hundred.  64 Journal for clamp Fig. 66  66 Clamp for indication segment.  67 Machine Screw, No. 10-32x½", for fastening clamp to indication segment. Price per hundred.  68 Indication Segment only, for switch lever.  68 Indication Segment only, for switch lever.  68 as above, complete, with clamp, cap, journal, machine screws, and set screw, (1-68, 1-65, 1-65.	51	Spring Guide, for toggle joint Fig. 51a	24	-
Machine Screw, No. 12–32x7/8", for fastening support Fig. 57, to channel bar. Price per hundred.  Sa Shacket for intermediate bearing. Coupling only, for lever and contact roller shafts. Sa Short indication segment. Sate Screw, No. 10–32x7/8", for fastening cap to clamp Fig. 66. Shaft for indication segment. Set Screw, No. 10–32x5/8", for fastening clamp to indication segment. Machine Screw, No. 10–32x5/8", for fastening cap to indication segment. Machine Screw, No. 10–32x5/8", for fastening clamp to indication segment. Machine Screw, No. 10–32x5/8", for fastening clamp for indication segment. Machine Screw, No. 10–32x5/8", for fastening clamp to indication segment. Machine Screw, No. 10–32x5/8", for fastening clamp to indication segment. Machine Screw, No. 10–32x5/8", for fastening clamp to indication segment. Machine Screw, No. 10–32x5/8", for fastening clamp to indication segment. Machine Screw, No. 10–32x5/8", for fastening clamp to indication segment. Machine Screw, No. 10–32x5/8", for fastening clamp to indication segment. Machine Screw, No. 10–32x5/8", for fastening clamp to indication segment. Machine Screw, No. 10–32x5/8", for fastening clamp to indication segment. Machine Screw, No. 10–32x5/8", for fastening clamp to indication segment. Machine Screw, No. 10–32x5/8", for fastening clamp to indication segment. Machine Screw, No. 10–32x5/8", for fastening clamp to indication segment. Machine Screw, No. 10–32x5/8", for fastening clamp to indication segment. Machine Screw, No. 10–32x5/8", for fastening clamp to indication segment. Machine Screw, No. 10–32x5/8", for fastening clamp to indication segment. Machine Screw, No. 10–32x5/8", for fastening clamp to indication segment. Machine Screw, No. 10–32x5/8", for fastening clamp to indication segment. Machine Screw, No. 10–32x5/8", for fastening clamp to indication segment. Machine Screw, No. 10–32x5/8", for fastening clamp to indication segment. Machine Screw, No. 10–32x5/8", for fastening clamp to indication segment.	51a	Toggle Joint, for circuit shifter, complete, with spring		
Machine Screw and Nut, No. 6-32x\()2", for toggle joint Fig. 51a. Price per hundred. 500  Spring for toggle joint Fig. 51a. 12  Double Circuit Shifter Bracket 370  Single Circuit Shifter Bracket 210  Machine Screw, No. 12-32x\()8", for fastening support Fig. 57 to combination plate. Price per hundred. Support for combination plate. Price per hundred. Support for combination plate, for machine with horizontal spring combination, complete, with machine screws, (1-56, 1-58, Plate 0805) 16  Machine Screw, No. 12-32x\()7", for fastening support Fig. 57, to channel bar. Price per hundred 200  End Bracket for intermediate bearing 700  Coupling only, for lever and contact roller shafts. 800  Set Screw, (1-60, 1-38, 1-47, Plate 0805) 800  Machine Screw, No. 10-32x\()7", for fastening cap to clamp Fig. 66. Price per hundred 2000  Machine Screw, No. 10-32x\()7", for fastening cap to clamp Fig. 66. Price per hundred 2000  Machine Screw, No. 10-32x\()8", for cap Fig. 65. Price per hundred 2000  Machine Screw, No. 10-32x\()8", for fastening clamp to indication segment. Price per hundred 2000  Machine Screw, No. 10-32x\()8", for fastening clamp to indication segment. Price per hundred 2000  Machine Screw, No. 10-32x\()8", for fastening clamp to indication segment. Price per hundred 2000  Machine Screw, No. 10-32x\()8", for fastening clamp to indication segment. Price per hundred 2000  Machine Screw, No. 10-32x\()8", for fastening clamp to indication segment. Price per hundred 2000  Machine Screw, No. 10-32x\()8", for fastening clamp to indication segment. Price per hundred 2000  Machine Screw, No. 10-32x\()8", for fastening clamp to indication segment. Price per hundred 2000  Machine Screw, No. 10-32x\()8", for fastening clamp to indication segment. Price per hundred 2000  Machine Screw, No. 10-32x\()8", for fastening clamp to indication segment. Price per hundred 2000  Machine Screw, No. 10-32x\()8", for fastening clamp to indication segment. Price per hundred 2000  Machine Screw, No. 10-32x\()8", for fastening clamp to indi			50	
Fig. 51a. Price per hundred.  5 Spring for toggle joint Fig. 51a.  54 Pivot for toggle joint Fig. 51a.  55 Double Circuit Shifter Bracket.  56 Machine Screw, No. 12–32x5%", for fastening support Fig. 57 to combination plate. Price per hundred.  57 Support for combination plate, for machine with horizontal spring combination, complete, with machine screws, (1-56, 1-58, Plate 0805).  58 Machine Screw, No. 12–32x7%", for fastening support Fig. 57, to channel bar. Price per hundred.  50 Coupling only, for lever and contact roller shafts.  60 Coupling only, for lever and contact roller shafts.  60 Shaft for indication segments.  61 Shaft for indication segments.  62 Machine Screw, No. 10–32x7%", for fastening cap to clamp Fig. 66. Price per hundred.  63 Set Screw, No. 10–32x3%", for cap Fig. 65. Price per hundred.  64 Journal for clamp Fig. 66  65 Clamp for indication segment.  66 Clamp For indication segment.  67 Machine Screw, No. 10–32x5%", for fastening clamp to indication segment.  68 Indication Segment only, for switch lever.  68 Indication Segment only, for switch lever.  68 as above, complete, with clamp, cap, journal, machine screws, and set screw, (1-68, 1-65, 1-65.		(1-51, 1-53, 1-54, 1-52, Plate 0005).	50	
Spring for toggle joint Fig. 51a	52	Machine Screw and Nut, No. 0-32x /2, 101 toggle joint	F 00	
54 Pivot for toggle joint Fig. 51a 55 Double Circuit Shifter Bracket 56 Machine Screw, No. 12–32x5%", for fastening support Fig. 57 to combination plate. Price per hundred. 57 Support for combination plate, for machine with horizontal spring combination, complete, with machine screws, (1-56, 1-58, Plate 0805) 58 Machine Screw, No. 12–32x7%", for fastening support Fig. 57, to channel bar. Price per hundred 59 End Bracket for intermediate bearing 60 Coupling only, for lever and contact roller shafts. 60 as above, complete, with machine screw and set screw, (1-60, 1-38, 1-47, Plate 0805) 61 Shaft for indication segments 62 Machine Screw, No. 10–32x7%", for fastening cap to clamp Fig. 66. Price per hundred 63 Set Screw, No. 10–32x7%", for cap Fig. 65. Price per hundred. 64 Journal for clamp Fig. 66 66 Clamp for indication segment 67 Machine Screw, No. 10–32x5%", for fastening clamp to indication segment. 68 Indication Segment only, for switch lever 69 as above, complete, with clamp, cap, journal, machine screws, and set screw, (1-68, 1-65, 1-65)		Fig. 51a. Price per nundred.		
55a Single Circuit Shifter Bracket 56 Single Circuit Shifter Bracket 56 Machine Screw, No. 12–32x5g", for fastening support Fig. 57 to combination plate. Price per hundred. 57 Support for combination plate, for machine with horizontal spring combination, complete, with machine screws, (1-56, 1-58, Plate 0805) 58 Machine Screw, No. 12–32x7g", for fastening support Fig. 57, to channel bar. Price per hundred 59 End Bracket for intermediate bearing 60 Coupling only, for lever and contact roller shafts. 60a as above, complete, with machine screw and 60a set screw, (1-60, 1-38, 1-47, Plate 0805) 61 Shaft for indication segments 62 Machine Screw, No. 10–32x7g", for fastening cap to 63 Clamp Fig. 66. Price per hundred 64 Journal for clamp Fig. 66 65 Clamp for indication segment 66 Clamp for indication segment 67 Machine Screw, No. 10–32x5g", for fastening clamp 68 to indication segment. 69 This price per hundred 60 Clamp for indication segment 61 Machine Screw, No. 10–32x5g", for fastening clamp 62 to indication segment. 63 Price per hundred 64 Journal for clamp Fig. 66 65 Clamp for indication segment. 66 Clamp for indication segment. 67 Machine Screw, No. 10–32x5g", for fastening clamp 68 This price per hundred 69 This price per hundred 60 Clamp Fig. 66 Clamp for indication segment. 60 Clamp Fig. 66 Clamp for indication segment. 61 Machine Screw, No. 10–32x5g", for fastening clamp 62 This price per hundred 63 This price per hundred 64 Journal for clamp Fig. 66 65 Clamp for indication segment. 66 Clamp for indication segment. 67 Machine Screw, No. 10–32x5g", for fastening clamp 68 This price per hundred 69 This price per hundred 60 Clamp Fig. 66 Clamp for indication segment. 60 Clamp Fig. 66 Clamp for indication segment. 61 This price per hundred 62 Oo 63 This price per hundred 64 Journal for clamp fig. 66 Clamp for indication segment. 65 This price per hundred 66 Clamp for indication segment. 67 This price per hundred 68 This price per hundred 69 This price per hundred 60 Clamp for indication segment. 60 Clamp for ind		Spring for toggle joint Fig. 51a		
Single Circuit Shifter Bracket  Machine Screw, No. 12–32x3½", for fastening support Fig. 57 to combination plate. Price per hundred.  Support for combination plate, for machine with horizontal spring combination, complete, with machine screws, (1-56, 1-58, Plate o805)  Machine Screw, No. 12–32x7½", for fastening support Fig. 57, to channel bar. Price per hundred  Send Bracket for intermediate bearing.  Coupling only, for lever and contact roller shafts.  Coupling only, for lever and contact roller shafts.  Machine Screw, (1-60, 1-38, 1-47, Plate o805).  Machine Screw, No. 10–32x7½", for fastening cap to clamp Fig. 66. Price per hundred.  Machine Screw, No. 10–32x7½", for cap Fig. 65. Price per hundred.  Machine Screw, No. 10–32x5½", for fastening clamp to indication segment.  Machine Screw, No. 10–32x5½", for fastening clamp to indication segment.  Price per hundred.  Machine Screw, No. 10–32x5½", for fastening clamp to indication segment.  Price per hundred.  Machine Screw, No. 10–32x5½", for fastening clamp to indication segment.  Price per hundred.  Machine Screw, No. 10–32x5½", for fastening clamp to indication segment.  Price per hundred.  Machine Screw, No. 10–32x5½", for fastening clamp to indication segment.  Price per hundred.  Machine Screw, No. 10–32x5½", for fastening clamp to indication segment.  Price per hundred.  Machine Screw, No. 10–32x5½", for fastening clamp to indication segment.  Price per hundred.  Machine Screw, No. 10–32x5½", for fastening clamp to indication segment.  Machine Screw, No. 10–32x5½", for fastening clamp to indication segment.  Machine Screw, No. 10–32x5½", for fastening clamp to indication segment.  Machine Screw, No. 10–32x5½", for fastening clamp to indication segment.  Machine Screw, No. 10–63x5½,", for fastening clamp to indication segment.		Privot for toggle joint Fig. 51a		
Machine Screw, No. 12-32x5%", for fastening support Fig. 57 to combination plate. Price per hundred.  Support for combination plate, for machine with horizontal spring combination, complete, with machine screws, (1-56, 1-58, Plate 0805)  Machine Screw, No. 12-32x7%", for fastening support Fig. 57, to channel bar. Price per hundred  Coupling only, for lever and contact roller shafts.  Sabove, complete, with machine screw and set screw, (1-60, 1-38, 1-47, Plate 0805).  Machine Screw, No. 10-32x7%", for fastening cap to clamp Fig. 66. Price per hundred  Set Screw, No. 10-32x7%", for cap Fig. 65. Price per hundred.  Journal for clamp Fig. 66 Clamp for indication segment.  Machine Screw, No. 10-32x5%", for fastening clamp to indication segment.  Price per hundred.  Indication Segment only, for switch lever.  As above, complete, with clamp, cap, journal, machine screws, and set screw, (1-68, 1-65, 1-65.				
Fig. 57 to combination plate. Price per hundred.  Support for combination plate, for machine with horizontal spring combination, complete, with machine screws, (1-56, 1-58, Plate 0805)		Marking Coron No. 12 22754" for factoring support	2 10	7 F S
Support for combination plate, for machine with horizontal spring combination, complete, with machine screws, (1-56, 1-58, Plate o805)  Machine Screw, No. 12–32x7/8", for fastening support Fig. 57, to channel bar. Price per hundred	50	Machine Screw, No. 12-32x/8, 101 lastening support	2 00	
zontal spring combination, complete, with machine screws, (1-56, 1-58, Plate o805)  Machine Screw, No. 12-32x7/8", for fastening support Fig. 57, to channel bar. Price per hundred 2 00  End Bracket for intermediate bearing 70  Coupling only, for lever and contact roller shafts. 80  as above, complete, with machine screw and set screw, (1-60, 1-38, 1-47, Plate o805) 86  Shaft for indication segments 90  Machine Screw, No. 10-32x7/8", for fastening cap to clamp Fig. 66. Price per hundred 2 00  Set Screw, No. 10-32x3/8", for cap Fig. 65. Price per hundred 2 00  Gamp Fig. 66 30  Clamp For indication segment 2 50  Machine Screw, No. 10-32x3/8", for fastening clamp to indication segment 2 50  Machine Screw, No. 10-32x3/8", for fastening clamp to indication segment 2 50  Machine Screw, No. 10-32x3/8", for fastening clamp to indication segment 2 30  Indication Segment only, for switch lever 2 30  Bas above, complete, with clamp, cap, journal, machine screws, and set screw, (1-68, 1-65, 1-65, 1-65)		Current for combination plate, for machine with hori-	2 00	
chine screws, (1-56, 1-58, Plate o8o5)  Machine Screw, No. 12-32x78", for fastening support Fig. 57, to channel bar. Price per hundred  Coupling only, for lever and contact roller shafts.  as above, complete, with machine screw and set screw, (1-60, 1-38, 1-47, Plate o8o5)  Machine Screw, No. 10-32x78", for fastening cap to clamp Fig. 66. Price per hundred  Set Screw, No. 10-32x78", for cap Fig. 65. Price per hundred.  Journal for clamp Fig. 66  Clamp For indication segment  Clamp For indication segment  Machine Screw, No. 10-32x58", for fastening clamp to indication segment.  Price per hundred  Durnal for clamp Fig. 66  Clamp For indication segment.  Machine Screw, No. 10-32x58", for fastening clamp to indication segment.  Price per hundred  Durnal for clamp Fig. 66  Clamp For indication segment.  Price per hundred  Durnal for clamp Fig. 66  Clamp For indication segment.  Directors  2 00  2 30  Machine Screw, No. 10-32x58", for fastening clamp to indication segment.  Price per hundred  Directors  2 00  2 30  Machine Screw, No. 10-32x58", for fastening clamp to indication segment.  Price per hundred  Directors  Directors  2 00  2 30  Machine Screw, No. 10-32x58", for fastening clamp to indication segment.  Price per hundred  Directors  Directors	57	Support for combination place, for machine with ma-		100
Find Bracket for intermediate bearing		chino corews (1.56 1.58 Plate 0805)	16	
Find Bracket for intermediate bearing	-8	Machine Screw, No. 12-22x7/" for fastening support		
59 End Bracket for intermediate bearing	50	Fig. 57 to channel har Price per hundred	2 00	
Coupling only, for lever and contact roller shafts.  as above, complete, with machine screw and set screw, (1-60, 1-38, 1-47, Plate 0805).  Shaft for indication segments.  Machine Screw, No. 10-32x½", for fastening cap to clamp Fig. 66. Price per hundred.  Set Screw, No. 10-32x½", for cap Fig. 65. Price per hundred.  Journal for clamp Fig. 66.  Clamp For indication segment.  Clamp For indication segment.  Machine Screw, No. 10-32x½", for fastening clamp to indication segment.  Price per hundred.  Indication Segment only, for switch lever.  as above, complete, with clamp, cap, journal, machine screws, and set screw, (1-68, 1-65, 1-65.	ro.	End Bracket for intermediate hearing		
as above, complete, with machine screw and set screw, (1-60, 1-38, 1-47, Plate 0805)		Compling only for lever and contact roller shafts.		
set screw, (1-60, 1-38, 1-47, Plate 0805)		as above complete with machine screw and		
Shaft for indication segments  Machine Screw, No. 10–32x½", for fastening cap to clamp Fig. 66. Price per hundred.  Set Screw, No. 10–32x½", for cap Fig. 65. Price per hundred.  Clamp for clamp Fig. 66.  Clamp for indication segment.  Machine Screw, No. 10–32x¾", for fastening clamp to indication segment.  Price per hundred.  Machine Screw, No. 10–32x¾", for fastening clamp to indication segment.  Price per hundred.  Machine Screw, No. 10–32x¾", for fastening clamp to indication segment.  Price per hundred.  Machine Screw, No. 10–32x¾", for fastening clamp to indication segment.  Machine Screw, No. 10–32x¾", for fastening clamp to indication segment.  Machine Screw, No. 10–32x¾", for fastening cap to condition	ooa	set screw (1-60 1-28, 1-47, Plate 0805)	86	
Machine Screw, No. 10–32x¾", for fastening cap to clamp Fig. 66. Price per hundred 200  63 Set Screw, No. 10–32x¾", for cap Fig. 65. Price per hundred 200  64 Journal for clamp Fig. 66 30  66 Clamp for indication segment 250  67 Machine Screw, No. 10–32x¾", for fastening clamp to indication segment. Price per hundred 200  68 Indication Segment only, for switch lever 230  68a as above, complete, with clamp, cap, journal, machine screws, and set screw, (1-68, 1-66, 1-65.	6r	Shaft for indication segments	90	
clamp Fig. 66. Price per hundred 200  Set Screw, No. 10-32x¾", for cap Fig. 65. Price per hundred. 200  Governal for clamp Fig. 66 300  Clamp for indication segment 2500  Machine Screw, No. 10-32x¾", for fastening clamp to indication segment. Price per hundred 200  Indication Segment only, for switch lever 2300  Results in the segment only for switch lever 2300  Results in the segment only for switch lever 2300  Results in the segment only for switch lever 2500  Results in the segment only for switch lever 2500  Results in the segment only for switch lever 2500  Results in the segment only for switch lever 2500  Results in the segment only for switch lever 2500  Results in the segment only for switch lever 2500  Results in the segment 2500  Results in the segm		Machine Screw, No. 10-32x7/6", for fastening cap to		
63 Set Screw, No. 10–32x3/8", for cap Fig. 65. Price per hundred			2 00	
hundred	63	Set Screw, No. 10-32x3/8", for cap Fig. 65. Price per		
64 Journal for clamp Fig. 66	-3		2 00	
66 Clamp for indication segment 250 67 Machine Screw, No. 10-32x%//, for fastening clamp to indication segment. Price per hundred 200 68 Indication Segment only, for switch lever 230 68a as above, complete, with clamp, cap, journal, machine screws, and set screw, (1-68, 1-66, 1-65,	64	Journal for clamp Fig. 66	30	
to indication segment. Price per hundred		Clamp for indication segment	2 50	
to indication segment. Price per hundred	67	Machine Screw, No. 10-32x5/8", for fastening clamp		
68 Indication Segment only, for switch lever		to indication segment. Price per hundred	2 00	
machine screws, and set screw, (1-68, 1-66, 1-65,	68	Indication Segment only, for switch lever	2.30	
machine screws, and set screw, (1-68, 1-66, 1-65,	68a	as above, complete, with clamp, cap, journal,		
7.64 0.60 0.67 T-62 Plate 080F) F 20		machine screws, and set screw, (1-68, 1-66, 1-65.		
1-04, z-02, z-0/, 1-03, 11ate 0005)		1-64, 2-62, 2-67, 1-63, Plate 0805)	5 30	
69 Indication Segment only, for signal lever 2 30	69	Indication Segment only, for signal lever	2 30	100
69a as above, complete, with clamp, cap, journal,	69a	as above, complete, with clamp, cap, journal,		
machine screws and set screw, (1-69, 1-66, 1-65,	110000	machine screws and set screw, (1-69, 1-66, 1-65,		
1-64, 2-62, 2-67, 1-63, Plate 0805) 5 30		1-64, 2-62, 2-67, 1-63, Plate 0805)	5 30	

Details Appplicable to the Horizontal or Vertical Roller Type

#### Order by Plate and Figure

		Li Pri		
voi				
Fig.	Caila famin limiting lately and assument		**	
70	Guide for indication latch and segment.	1	12	
71	Special Screw, for fastening guide Fig. 70 to bushing		IO	
-	Fig. 72  Bushing for fastening indication magnet to back plate		10	
72			00	
	of machine		90	
73	Armature Stem, complete, with indication latch and	*	-00	
-	armature lock nut, for switch lever	1	90	
74	Armature Stem, complete, with indication latch and	*	70	
	armature lock nut, for signal lever		70 80	
75	Indication Magnet only	13	00	
75a	Switch Indication Magnet, complete, with armature,			NO.
	armature stem, spring for releasing armature, and	20	00	
	cap, (1-75, 1-77, 1-73, 1-76, 1-78, Plate 0805)	20	00	
75b	Signal Indication Magnet, complete, with armature,			
	armature stem, spring for releasing armature and	20	00	
-6	cap, (1-75, 1-77, 1-74, 1-76, 1-78, Plate 0805.)	20	00	
76	Spring for releasing armature Armature for indication magnets		60	
77			82	
78	Cap for indication magnets  Back Bearing, 2-way, only, for indication segment		02	
79	shafts		90	
200	shafts		90	
79a	as above, complete with machine screws,	T	00	
80	(1-79, 2-81, Plate 0805)		00	
00	shafts		00	
8oa	as above, complete, with machine screws,		00	
ova	(r So a Sr Plate oSor)	T	10	
81	(1-80, 2-81, Plate 0805)			
01	Price per hundred	2	00	
82	Price per hundred	3	00	
02	machine		60	
83	Terminal Board, complete, with terminals, for II			
-3	levers	27	00	
83a	as above, for 15 levers		00	
83b	as above, for 17 levers.	-	00	ar Sens
84	Terminal, complete, with machine screws, washers,			
	and wood screw for fastening to terminal board.		20	
85 .	Machine Screw and Washer, No. 12-32x3/8", for			
-3.	terminal. Price per hundred	2	00	
86	Zinc Plate, 1/8" thick, for track model. Specify length			
	and width when ordering			
87	Name Plate for machine.			
88	Resistance coil, complete, as shown. Specify resis-			
	tance when ordering	4	00	
		-		



Locking Dogs, Track Model and Machine Details Applicable to the Horizontal or Vertical Roller Type

Locking Dogs, Track Model and Machine Details, Applicable to the Horizontal or Vertical Roller Type

The front of a machine is that part occupied by a man when operating the levers.

		List Price
Fig.		
I	One-Arm Home Bridge Signal, for track model	10
2	" " Home Ground Signal, for track model	10
3	" " Distant Signal, for track model	IO
4	Two-Arm Home Signal, for track model	IO
5	" Signal, one home and one distant blade,	
,	for track model	40
6 -	Three-Arm Home Signal, for track model	40
7	blades, for track model	
8	Four-Arm Signal, for track model	42
	Four-Arm Bracket Signal, for track model	54
9	Pot Signal, for track model	80
II	Operating Arm only, for track model,	26
		50
12	Special Screw, No. 4-40 x 13/64", for fastening connecting rod Fig. 14 to operating arm Fig. 11.	
	Price per hundred	4 00
13		
7.10	and screw for holding operating arm Fig. 11 as above, complete, with reinforcing springs,	I 12
1 3а	used only on large machines	
		2 00
14	Connecting Rod for track model. Specify length	
*-	when ordering. Price per foot	12
15	Special Screw, No. 4-40 x ½", for fastening connect-	
16	ing rod Fig. 14 to crank. Price per hundred	4 00
	Switch, for track model	12
17	Number Plate, complete, with bushing and screw, for	
	track model signals. Specify number when or-	
.0	dering  Number Plate, for track model switch. Specify num-	20
18		
	ber when ordering	20
19	Machine Screw, ½6"-60 x 38", for fastening tracks to track model plate. Price per hundred	
22	그렇게 하는 사람들은 사람들이 되었다면 하는 것이 되었다면 살아서 되었다면 하는데	2 00
20	Bushing for screw Fig 19	02
21	Pivot Post, for cranks of track model, complete, with	
	washer	06
22	Guide for connecting rod Fig. 14.	20
23	Link for operating double slip for track model	26

Locking Dogs, Track Model and Machine Details, Applicable to the Horizontal or Vertical Roller Type

		List Price	
Fig.			
24	Bushing for number plate Fig. 17	02	
25	Brass Bar, 5/32" x 1/4", for track model signal bridge.		
	Specify length when ordering. Price per foot	24	
26	Machine Screw, No. 4-40 x 3/16", for fastening track model signals to bridge. Price per hundred	1 00	
27	Phosphor Bronze Rod for connections to switches and		
	signals on track model. Price per foot	12	
28	Turnbuckle for joining connecting rods of track		
	model	06	
29	Lever, complete, with set screw, for track model	16	
30	Crank, 3-arm 90°, complete, with set screw, for track		
	model	30	
31	Crank, 2-Arm 90°, used without set screw, for track		
	model	- 22	
32	Crank, 3-Arm 90°, as above	30	
33	Crank, 2-Arm 90°, complete, with set screw, for track		
	model	22	
34	Compensating Lever, complete, with set screw, for		
	track model	34	
35	as above, used without set screw, for track		
	model	34	
36	Double Slip, for track model	1 80	
37	Contact Spring, for combination plate, for alternate		
	rollers	18	
38	as above, for adjacent rollers	12	
39	as above, for signal or switch control	10	
40	as above, for lock magnet control	10	
41	Contact Spring, with long connector, for combination		
	plate	10	
42	Round Head Wood Screw, No. 6 x 3/8", for fastening		
	contact springs to combination plate. Price per		
	hundred.,	1 00	
43	Cross Strip, for combination plate. Specify length		
	when ordering. Price per foot	20	
44	Battery Strip, for combination plate. Specify length		
	when ordering. Price per foot	22	

Locking Dogs, Track Model and Machine Details, Applicable to the Horizontal or Vertical Roller Type

The term "front and back drilling," as applied to locking dogs, refers to the position of the dogs with relation to the front and back of the machine.

The front of a machine is that part occupied by a man when operating the levers.

									List Price	
Fig.	No.	43	Locking	Dog,	3/8	inch	thick	k, back drilling	22	
45a		44	14	**	346	inch	thic	k, back drilling	20	
45b	66	45	**		3/8	44		front drilling.	22	
45C		46		66	346		64	11 11	20	
46	**	31	66	44	3/8	14		back drilling	14	
46a	44	32	14		3/16	1.			12	
46b	6.6	33	44	4.6	3/8	66	++	front drilling.	14	
46c	1.6	34		**	3/16	4.6	**		12	
46d	6.6	58	"		3/16			middle drilling	16	
47	**	3	16	44	3/8	66	4.6	back drilling.	12	
47a	"	4	66	4.6	3/16	44	14	" "	10	
47b		5	"	66	3/8	4.4	66	front drilling	12	
47C		6	44	14	3/16	4.6			10	
48	"	19	4.6	"	3/8	44	"	front or back drl'g	20	
48a	14	20	16	6.6	3/16		4.6		20	
49		23	**	44	3/8	44	16	middle drilling	14	
49a		24	**	11	3/16	4.4	14	11 11	14	
50		35	**	44	3/8	44	4.6	front or back drl'g	22	
50a	**	36	**	11	3/16			16 11 11 11	20	
51	44	47	"	44	3/8	4.6		back drilling.	24	
51a	44	48	44	4.4	3/16				24	
51b	4.6	49	"	**	3/8	"	64	front drilling.	24	
5IC	44	50	"		3/16	"	4.6		24	
52	6.6	29		44	3/8		44	middle drilling	16	
52a	**	30		4.6	3/16	"			16	
53	66	7	1.1	44	3/8	44	6.6	14 11	10	
53a	4.6	8	"	11	3/16	4.6		11	16	
54	66	15		6.6	3/8	4.4	4.6	back drilling	20	
54a		16	4.6	44	3/16	**	14	" "	20	
54b	**	17	**	1.6	3/8	6.6	"	front drilling.	20	
54C	- 44	18	"	6.6	3/16	64	64		20	
55	"	25	"	61	3/8	"	"	back drilling.	16	
55a	"	26	"		3/16		6.6		16	
55b		27	"	"	3/8	4.6	44	front drilling.	16	
55c	**	28	- (4	66	3/16			"	16	1

#### Locking Dogs, Track Model and Machine Details, Applicable to the Horizontal or Vertical Roller Type


The term "front and back drilling," as applied to locking dogs, refers to the position of the dogs with relation to the front and back of the machine.

The front of a machine is that part occupied by a man when operating the levers.

•		
g.		List Price
8.	No. 13 Locking Dog, 3/8 in. thick, front or back drl'ng	14
a	" 14 " " 3/16" " " " " "	12
,	11 37 11 11 38 11 11 11 11 11	20
a	" 38 " " 3/16" " " " " " "	18
	" 9 " " 3% " back drilling	14
ı	" IO " " 3/16" " " " " " " " " " " " " " " " " " "	12
	" II " " 3% " " front drilling	14
	" 12 " " 3/16" " " " " "	12
	" 57 " " 3/16 " " middle drilling	12
	" 21 " " 3% " front or back drl'ng	16
	. 22 . 3/16	16
	" 39 " " 38 " " back drilling	16
	" 40 " " 3/16 " " " " " …	16
	" 41 " " 3/8 " front drilling	16
	" 42 " " 3/16 " " " " " …	16
	" I " " all middle drilling	10
	2 " " 3/16 " " " " "	10
	Rivet, 1/8" x 15/16", for fastening locking dog, 3/16 inch	
	thick, to locking bar. Price per hundred	1 00
	Rivet, 1/8" x 1 1/8", for fastening looking dog, 3/8 inch	
	thick, to locking bar. Price per hundred	I 00
	Single Reach Trunnion, as shown	20
	Double Reach Trunnion	20
	Triple Reach Trunnion	40
	Right Hand Swinging Dog, 3/8 inch thick, as shown.	I 42
	Left Hand Swinging Dog, 3/8 inch thick	1 42
	Swinging Dog, 3/16 inch thick, as shown	1 40
	Handle, complete, as shown, with latch, for case	60
	Hinge only, 2" x 1½", for back of track model case.	12
	Wood Screw, No. 6 x 1/2", for fastening hinge Fig. 67,	
	to back of track model case. Price per hundred	1 00
	as above, for fastening hinge Fig. 67 to sup-	
	porting strip for back of track model case. Price	
	per hundred	1 00
	Round Head Machine Screw, No. 10-32 x ¼", for fast-	
	ening name plate to machine. Price per hundred.	100

Locking Dogs, Track Model and Machine Details, Applicable to the Horizontal or Vertical Roller Type

		List Price	
Fig.	Cap Screw, 5/16" x 3/4", for fastening intermediate bearing plate to trunnion. Price per hundred.	2 00	
72	Cap Screw, 5/16" x 1", for fastening intermediate bearing plate to end bracket. Price per hundred	2 00	
73	Cap Screw, $\frac{3}{8}$ " x $\frac{3}{4}$ ", for fastening angle iron to leg.	3 00	
74	Cap Screw, 3/8" x I", for fastening end bracket to intermediate bearing. Price per hundred	3 00	
75	Bolt and Nut, 3/8" x 11/4", for fastening intermediate bearing to right and left hand channel bars. Price		
76	per hundred Cap Screw, ¼" x 1¼", for fastening circuit controller	3 00	
	base to front plate. Price per hundred Bolt, 38" x 358", for fastening back bearing plate to	2 00	
77	back plate. Price per hundred	6 00	
78	mediate bearing. Price per hundred	6 00	
79	and left hand channel bars. Price per hundred.	4 00	
-80	Bolt and Nut, 3/8" x 1 1/2", for fastening back plate to right and left hand channel bars. Price per hun-	3 00	
81	dred		
82	ing back of case, to leg. Price per hundred  Machine Screw, with Nut, 5/16" x 13/4", for fastening	3 00	
83	locking bracket to front plate. Price per hundred		
-3	hand channel bars to front plate. Price per hundred	300	
.84	Machine Screw, ¼" x 1", for fastening lever to shaft.  Price per hundred	3 00	
-85	Brass Machine Screw, No. 6-32 x ½", for fastening cover to locking bracket. Price per hundred		



THE ELECTRO-PNEUMATIC INTERLOCKING MACHINE Vertical Roller Type


#### Vertical Roller Type

In ordering Electro-Pneumatic Interlocking Machines, a signaled track plan should be furnished, drawn to the scale of not over one hundred feet to the inch. This plan must show the location of the tower and the relation of the front of the machine to the track, and also the route or routes to be governed by each signal. It must also indicate the switches which are to be controlled by one lever, unless it is preferred to leave this to our judgment. If any special mechanical locking or electric appliances are required which would not ordinarily be included, full information concerning these must accompany the order. List prices shown on this page are based on machine cases being made of oak, and do not include track models, hoods for levers Fig. 40 Plate 0811, or special attachments for electric detector circuits for which special quotations will be furnished, on application, to cover the particular layout of tracks.

The front of a machine is that part occupied by a man when operating the levers.

Order by plate, figure and instructions given above

	CAPACI	TY OF	MACHINE	PRINC	PRINCIPAL DIMENSIONS			Draw'g	LIST PRICE			
Fig.	Levers	Lock'g Bars	Combin't'n Grooves	Length (Outside	Width e of Case)	Cer	eight to nter of evers	C-2827 Letter	Pe Lev		Pe Spa	
I	6	20	35	2' 21"	2' 13/"	2'	83/1" 83/1"	K	159	00	51	00
2	II	20	35	2/ 2/1	2' 134" 2' 134"	2'	83/11	K	159	00	51	00
2a	II	30	35	2' 2'	2' 656"	3'	27/8"	L	159	00	51	00
3	17	20	35	4'0"	2' 134"	2'	834" 278" 834" 278"	K	159	00	51	00
3a	17	30	35	116"	2 516	2'	27/8"	L	159	00	51	00
	23	20	35	5'0"	2' 134" 2' 618" 2' 134" 2' 134" 2' 618"	2'		K	159	00	51	00
4 4a	23	30	35	5'0"	2' 612"	3'	27/8"	L	159	00	51	00
5	29	20	35	7'0"	2' 13/"	2'	83/1	K	159	00	51	00
5a	29	30	35	7'0"	2' 61%"	3'	278" 834" 278" 278" 278" 278" 278" 278"	L	159	00	51	00
6	35	20	35	8' 3"	10/ 13/	190	83/11	K	159	00	51	00
ба.	35	30	35	8' 3"	2' 618' 2' 834' 2' 834' 3' 778' 3' 778'	3'	27/8"	L	159	00	51	00
6b	35	36	35	8' 3"	2' 83/1	3'	27/8"	M	159	00	51	00
	47	36	35	10'9"	2' 834'	3'	27/2"	M	174	00	54	00
7 7a	47	48	35	10'9"	3' 778'	3'	27/0"	N	174	00	54	0
8		48	35	13' 3"	3' 778'	3'	27/8"	N	174	00	54	0
8a	59	60	35	13' 3"	4' 118'	3'	27/11	0	174	00	54	0
	71	60	35	15'9"	4 I-6	3'	27/2"	0	174	00	54	0
9	71	72	35	15'9"	4' 638'	3'	27/11	P	174	00	54	0
9a	83	60	35	118' 3"	A 1 6	3'	27/0"	0	174	00	54	0
Ioa	83	72	35	18' 3"	4' 63%	3'	27/11	P	174	00	54	0
II		60	35	20' 9"	4' 116'	3'	27/11	0	174	00	54	0
Ha	95	72	35	120'0"	4' 63%	3	27/11	P	174	00	54	0
12	107	60	35	23' 3"	4' 638' 4' 118'	3'	278" 278" 278" 278" 278" 278" 278" 278"	0	174	00	54	0
12a	107	72	35	23' 3"	4 6%	3'	27/11	P	174	00	54	0
	119	72	35	25' 9"	1 63/	2	27011	P	189	00	57	0
13 13a	119	108	35	25' 9"	E'TTI	1 3'	27/2"	Q	189	00	57	0
14	131	72	35	28' 3"	14 130%	1 3'	2//11	P	189	00	57	0
14a	131	108	35	28' 3"	IZ TICA	1 3'	278" 278" 278" 278" 278" 278"	Q	189	00	57	0
CONTRACTOR OF THE PARTY OF THE	143	72	35	30' 9"	1 636	3'	27%"	P	189	00	57	0
15 15a	143	108	35	30' 9"	5' 1178	3'	27/11	0	189	00	57	0
16		72	35	33' 3"	A (13/	3'	27/11	QP	189	00	57	0
16a	155	108	35	33' 3"	5 11%	1 3'	27/0"	0	189	00	57	0
	155	72	35	35'9"	4' 63%	3'	27/0"	QP	189			0
17	167	108	35	35' 9"	5' TT 76	3'	27/11		189	00		
17a		108	35	38' 3"	5' 1178	3'	27/8" 27/8" 27/8" 27/8" 27/8" 27/8"	00000	189			
	179	108	35	40'9"	5' 1178	" 3'	27/11	õ	189	00		
19	191	108	35	43' 3"	5' 1178	3'	27/11	õ	189		1 500	
21	203	108	35	45' 9"	5' 1178	" 3"	27/8"	ñ	205		1 2	



THE ELECTRO-PNEUMATIC INTERLOCKING MACHINE Vertical Roller Type, Details

### Vertical Roller Type, Details

The front of a machine is that part occupied by a man when operating the levers.


		List Price	
Fig.	Leg only, as shown, for machine having one 10-way		
I	locking bracket. I. R. T. Co's. Standard.	16 60	
Ia	as above, for machine having one 15-way		
14	locking bracket. Penna. R. R. Standard	24 90	
ıb	as above, for machine having two 12-way		
	locking brackets. Penna. R. R. Standard	17 90	
IC	as above, for machine having two 15-way		
	locking brackets. Penna. R. R. Standard	17 60	
ıd	as above, for machine having two 15-way		
	locking brackets. C. & N. W. R. R. Standard.	25 60	
2	Front Plate, as shown, for 11 lever section	43 80	
2a	as above, for 17 lever section.	76 60	
2b	as above, for 6 lever machine	21 70	
2C	as above, for II lever machine	41 40	
2d	as above, for 17 lever machine	54 60	
2e	Right Hand Front Plate, for II lever section	42 50	
2f	as above, for 17 lever section	55 50	
2g	Left Hand Front Plate, for II lever section	42 50	
2h	as above, for 17 lever section	55 50	
3	Back Plate, as shown, for II lever section	39 00	
3a	as above, for 17 lever section	56 00	
3b	as above, for 6 lever machine.	25 00	
3C	as above, for 11 lever machine	35 50	
3d	as above, for 17 lever machine.	54 40	
зе	Right Hand Back Plate, for 11 lever section	38 40	6 5
3f	as above, for 17 lever section	53 00	
3g	Left Hand Back Plate, for II lever section	38 40	
3h	as above, for 17 lever section	53 00	
4	Lower Support, as shown, for combination plate for 6		
	lever machine	4 80	
4a	as above, for 11 lever machine	8 20	
4b	as above, for 17 lever machine.	11 80	

Vertical Roller Type, Details

		List Price	
Fig.			
5	Upper Support, as shown, for combination plate for 6		
	lever machine	5 10	
5a	as above, for 11 lever machine	8 30	
5b	as above, for 17 lever machine	12 00	
6	Tie Rod as shown, ¾"x 1'-9", complete, with four nuts, for holding legs together, for 6 lever ma-		
6a	as above, ¾"x2'-9½", for holding legs	50	
	together for II lever machine	60	
6b	as above, 34"x4'-01/2", for holding legs		
	together, for 17 lever machine	70	
7	Intermediate Bearing Plate, for 6 lever machine	3 40	
8	Terminal Strip. Specify length when ordering. Price	,	
	per foot	I 50	
9	Contact Roller and Shaft only	7 30	
10	Extension Shaft for contact roller	I IO	
II	Shaft for indication segments	90	
12	Circuit Shifter, complete, as shown	4 00	
13	Single Circuit Shifter Bracket	2 10	
14	Double Circuit Shifter Bracket.	3 70	
15	Bushing for back plate	60	
16	Bevel Gear for indication segment shaft, with machine		
	screw Fig. 34	90	
17	as above, for contact roller extension shaft,		
	with machine screw Fig. 34	90	
18	Battery Strip, for 6 lever machine	42	
19	as above, for II lever machine	60	
19a	as above, for 17 lever machine	80	
20	Bracket for fastening terminal strip to leg	42	
21	Shaft, complete, as shown, with bushings, for ma- chine having one 10-way locking bracket		
22	Jaw, for fastening hood to front plate of machine.	3 70	
23	Jaw, complete, with link and rivets for fastening hood	50	
	to jaw Fig. 22.	I 12	
24	Tap Bolt, 3/8"x7/8", for fastening lower support Fig. 4		
25	to leg. Price per hundred	3 00	
	to leg. Price per hundred	3 00	
		The second second	

Vertical Roller Type, Details

T2:		List Price	
Fig. 26	Bushing for side of case.	04	
27	Machine Screw, No. 12-32x¾", for fastening combination plate to leg. Price per hundred	2 00	
28	Machine Screw, No. 12-32x1", for fastening front of case to leg. Price per hundred	4 00	
29	Machine Screw, No. 12-32x5%", for fastening moulding to front plate. Price per hundred	3 00	
30	Tap Bolt, 3%"x35%", for fastening back bearing plate to back plate. Price per hundred.	6 00	
31	Machine Screw, No. 12-32x½", for fastening combination plate to upper and lower supports. Price per	0 00	
32	hundred	2 00	
33	per hundred	3 00	
	mediate bearing to back plate. Price per hundred.  Machine Screw, No. 8-32x1", for fastening bevel gear	3 00	
34	to shaft. Price per hundred	2 00	
35	Flat Head Machine Screw, No. 10-32x11/16", for fast ening terminal strip to bracket Fig. 20. Price		
36	per hundred Machine Screw, No. 12-32x3%", for fastening bracket	2 00	
37	Fig. 20 to leg. Price per hundred	2 00	
38	case to leg. Price per hundred  Machine Screw and Nut, ¾"x1¾", for fastening front	9 00	
	plate to leg. Price per hundred	6 00	
39	Cap Screw, 5/16"x3/4", for fastening intermediate bearing plate to end bracket. Price per hundred	2 00	
40	Hood for levers of 6 lever machine  Note:—For price of hood for machines of over six levers add \$1.20 to list price of Fig. 40 for each additional lever.		
41	Latch Plate, for opening in case to accommodate special locking lever	80	
42	Special Locking Lever, complete, as shown, with bearing, pin and cotters	4 20	



THE ELECTRO-PNEUMATIC PUSH BUTTON MACHINE
(For Classification Yards)


# THE ELECTRO-PNEUMATIC PUSH BUTTON MACHINE (For Classification Yards)


This machine is furnished in 12-way sections with iron cases, although if desired, a two, four or six-way can be furnished in a wooden case.

Orders for repair parts of the mechanism, shown in Fig. B on the opposite plate, should always be accompanied by samples of the parts required.

#### Order by Plate, Figure and Instructions Given Above

		List Price
Fig.		11100
A	12-way Electro-Pneumatic Push Button Machine, complete, as shown, with iron case	1006 00
Aa	2-way Electro-Pneumatic Push Button Machine, com-	
	plete, with wooden case	196 00
Ab	4-way, as above	374 00
Ac	6-way, as above	552 00
B	Single Mechanism only, complete, as shown	80 00
I	Back Plate for case of Fig. A	2 60
2	Top Plate for case of Fig. A	2 40
3	Bottom Plate, complete, as shown, for Fig. A, with	
	screws, washers, nuts, and retaining strips for	
	mechanisms	3 50
4	Front Plate, for case of Fig. A, complete, with glass,	
	retaining strips for glass, and screws	29 00
5	Right Hand End Plate for case of Fig. A	1 62
6	Left Hand End Plate for case of Fig. A	162
7	Push Button, complete, as shown with collar and	
	cotter	80






ELECTRO-PNEUMATIC SWITCH AND LOCK MOVE-MENT LAYOUTS FOR SINGLE SWITCH WITH ONE DETECTOR BAR


#### ELECTRO-PNEUMATIC SWITCH AND LOCK MOVE-MENT LAYOUTS FOR SINGLE SWITCH WITH ONE DETECTOR BAR

Mechanical Details, such as front and lock rods, detector bars, rail clips, rocking shafts, bearings, etc., are the U. S. & S. Co.'s standard, and will be found in the mechanical catalogue.

Magnets are wound to 120 ohms resistance unless otherwise specified. See page 171 for table of resistances.

#### Order by Plate, Figure and Instructions Given Below





Left Hand

ELECTRO-PNEUMATIC SWITCH AND LOCK MOVEMENT LAYOUTS FOR SINGLE SWITCH WITH TWO DETECTOR BARS


#### ELECTRO-PNEUMATIC SWITCH AND LOCK MOVE-MENT LAYOUTS FOR SINGLE SWITCH WITH TWO DETECTOR BARS

Mechanical Details, such as front and lock rods, detector bars, rail clips, rocking shafts, bearings, etc., are the U. S. & S. Co.'s standard, and will be found in the mechanical catalogue.

Magnets are wound to 120 ohms resistance unless otherwise specified. See page 171 for table of resistances.

#### Order by Plate, Figure and Instructions Given Below

		List Price	
Fig.			
В	Layout for a single switch with two detector bars back of points. Specify whether a right or left hand layout is desired, and weight of rail.		
	Assemblage: — Iron base plate for supporting cylinder and movement on ties; tie plate with riser plates; switch cylinder with valves and magnets; No. 12 switch and lock movement with indication box; covers for cylinder and movement; switch operat-		
	ing rod and cage; front and lock rods; rocking shaft with arms, bearings, and plates for fasten- ing to ties; two 50 foot detector bars with driv- ing pieces, and 32 motion plate rail clips, com-		
	plete; connecting rods between switch and lock movement and rocking shaft, and between rock- ing shaft and detector bars; two pieces, 21/2" x		
	½", strap iron; and all the necessary pins, bolts,	6 00	
-	nuts, lag screws and rivets.	446 00	
Ba	Layout, as above, without detector bars or their fittings	322 00	)




ELECTRO-PNEUMATIC SWITCH AND LOCK MOVE-MENT LAYOUTS FOR MOVABLE POINT FROG CROSSING WITH TWO DETECTOR BARS CONNECTED IN MULTIPLE

#### ELECTRO-PNEUMATIC SWITCH AND LOCK MOVE-MENT LAYOUTS FOR MOVABLE POINT FROG CROSSING WITH TWO DETECTOR BARS CONNECTED IN MULTIPLE

Mechanical Details, such as front and lock rods, detector bars, rail clips, rocking shafts, bearings, etc., are the U. S. & S. Co.'s standard, and will be found in the mechanical catalogue.

Magnets are wound to 120 ohms resistance unless otherwise specified. See page 171 for table of resistances.

	I,ist Price	
Fig.		
C Layout for a movable point frog crossing with two detector bars connected in multiple. Specific whether a right or left hand layout is desired and weight of rail.	y	
Assemblage: —Iron base plate for supporting cylinder and movement on ties; two tie plates with rise plates; switch cylinder with valves and magnets. No. 12 tandem switch and lock movement wit indication box; covers for cylinder and movement two switch operating rods and cages; two from and lock rods; rocking shaft with arms, bearings and plates for fastening to ties; two 50 foot detector bars with driving pieces, and 32 motion plate rail clips, complete; connecting rods be tween switch and lock movement and rocking	r	
shaft, and between rocking shaft and detected bars; two pieces, $2\frac{1}{2}$ " x $\frac{1}{2}$ ", strap iron, and all the	r "	
necessary pins, bolts, nuts, lag screws and rivets.  Ca Layout, as above, without detector bars or the		4 5
fittings		



ELECTRO-PNEUMATIC SWITCH AND LOCK MOVE-MENT LAYOUTS FOR MOVABLE POINT FROG CROSSING WITH TWO DETECTOR BARS CONNECTED IN TANDEM


1 Tiot 1 1


#### ELECTRO-PNEUMATIC SWITCH AND LOCK MOVE-MENT LAYOUTS FOR MOVABLE POINT FROG CROSSING WITH TWO DETECTOR BARS CONNECTED IN TANDEM

Mechanical Details, such as front and lock rods, detector bars, rail clips, rocking shafts, bearings, etc., are the U.S. & S. Co.'s standard, and will be found in the mechanical catalogue.

Magnets are wound to 120 ohms resistance unless otherwise specified. See page 171 for table of resistances.

	List Price	
Fig.		
D Layout for a movable point frog crossing with two detector bars connected in tandem. Specify whether a right or left hand layout is desired and weight of rail		
Assemblage: — Iron base plate for supporting cylinder and movement on ties; two tie plates with riser plates; switch cylinder with valves and magnets; No. 12 tandem switch and lock movement with		
indication box; covers for cylinder and move- ment; two switch operating rods and cages; two front and lock rods; rocking shaft with arms,		
bearings, and plates for fastening to ties; two 50 foot detector bars with driving pieces, and 32 motion plate rail clips, complete; connecting rods		
between switch and lock movement and rocking shaft, and between rocking shaft and detector bars; two pieces, 2½" x ½", strap iron; and all the		
necessary pins, bolts, nuts, lag screws and rivets .	534 00	
Da Layout, as above, without detector bars or their fit- tings	418 00	





ELECTRO-PNEUMATIC SWITCH AND LOCK MOVE-MENT LAYOUTS FOR MOVABLE POINT FROGS AND ONE END OF A SINGLE SLIP CROSSING


## ELECTRO-PNEUMATIC SWITCH AND LOCK MOVE-MENT LAYOUTS FOR MOVABLE POINT FROGS AND ONE END OF A SINGLE SLIP CROSSING

Mechanical Details, such as front and lock rods, detector bars, rail clips, rocking shafts, bearings, etc., are the U. S. & S. Co.'s standard, and will be found in the mechanical catalogue.

Magnets are wound to 120 ohms resistance unless otherwise specified.

See page 171 for table of resistances.

	List Price	
Fig.  E Layout for movable point frogs and one end of a single slip crossing with six detector bars. Specify whether a right or left hand layout is desired, and weight of rail  Assemblage:—Two iron base plates for supporting cylinder and movements on ties; three tie plates with riser plates; switch cylinder with valves and magnets; No. 12 tandem switch and lock movement; No. 12 switch and lock movement; No. 12 switch and lock movements; switch operating rods and cages; front and lock rods; rocking shaft with arms, bearings, and plates for fastening to ties; two 50-foot detector bars and four short lengths with driving pieces, and 49 motion plate rail clips, complete;		
connecting rods between switch and lock movements and rocking shaft, and between rocking shaft and detector bars; $2\frac{1}{2}$ " x $\frac{1}{2}$ ", strap iron; and all the necessary pins, bolts, nuts, lag screws		
and rivets.  Ea Layout, as above, without detector bars or their	706 00	
fittings	502 00	



ELECTRO-PNEUMATIC SWITCH AND LOCK MOVEMENT LAYOUTS FOR ONE END OF DOUBLE SLIP CROSSING, AND FOR MOVABLE POINT FROGS AND THE OTHER END OF A DOUBLE SLIP CROSSING


## ELECTRO-PNEUMATIC SWITCH AND LOCK MOVE-MENT LAYOUTS FOR ONE END OF A DOUBLE SLIP CROSSING, AND FOR MOVABLE POINT FROGS AND THE OTHER END OF A DOUBLE SLIP CROSSING.

Mechanical details, such as front and lock rods, detector bars, rail clips, rocking shafts, bearings, etc., are the U. S. & S. Co.'s. standard, and will be found in the mechanical catalogue.

Magnets are wound to 120 ohms resistance unless otherwise specified.

See page 171 for table of resistances.

		List Price	
Fig.			
F	Layout for one end of a double slip crossing with four detector bars. Specify weight of rail.  Assemblage: — Iron base plate for supporting cylinder and movement on ties; tie plate with riser plates; switch cylinder with valves and magnets; No. 12 switch and lock movement with indication box; covers for cylinder and movement; switch operating rod and cages, front and lock rods; point separator; rocking shaft with arms, bearings, and plates for fastening to ties; two 50 foot detector bars and two short lengths, with driving pieces and 50 motion plate rail clips, complete; connecting rods between switch and lock movement and rocking shaft, and between rocking shaft and detector bars; 2½" x ½" strap iron, and all the necessary pins, bolts, nuts, lag screws	£30.00	
17.	and rivets . Layout, as above, without detector bars or their	530 00	
Fa	fittings	348 00	
G	Layout, for movable point frogs and one end of a double slip crossing with eight detector bars. Specify weight of rail.  Assemblage: — Two iron base plates for supporting cylinder and movements on ties; three tie plates with riser plates; switch cylinder with valves and magnets; No. 12 tandem switch and lock movement; No. 12 switch and lock movement with indication box; covers for cylinder and movements; switch operating rods and cages; front and lock rods; point separator; rocking shaft with arms, bearings, and plates for fastening to ties; two 50 foot detector bars and six short lengths with driving pieces; and 86 motion plate rail clips, complete; connecting rods between switch and lock movements and rocking shaft, and between rocking shaft and detector bars; two special pipe carriers; 2½" x ½" strap iron; and all the necessary pins, bolts, nuts, lag screws		2.7
Ga	and rivets Layout, as above, without detector bars or their	800 00	
	fittings	520 00	March
			The state of




ELECTRO-PNEUMATIC SWITCH AND LOCK MOVEMENT LAYOUTS FOR ONE END OF A DOUBLE SLIP CROSSING WITH TWO DETECTOR BARS AHEAD OF POINTS

### ELECTRO-PNEUMATIC SWITCH AND LOCK MOVEMENT LAYOUTS FOR ONE END OF A DOUBLE SLIP CROSSING WITH TWO DETEC-TOR BARS AHEAD OF POINTS

Mechanical details, such as front and lock rods, detector bars, rail clips, rocking shafts, bearings, etc., are the U. S. & S. Co's. standard and will be found in the mechanical catalogue.

Magnets are wound to 120 ohms resistance unless otherwise specified. See page 171 for table of resistances.

	List Price	
Fig.  H Layout for one end of a double slip crossing with tw		
detector bars ahead of points. Specify whether right or left hand layout is desired, and weigh		
of rail		
Assemblage: — Iron base plate for supporting cylinder and movement on ties; tie plate with riser plate		
switch cylinder with valves and magnets; No.	12	
switch and lock movement with indication bo covers for cylinder and movement; switch		
operating rod and cages; front and lock rod	s;	
point separator; rocking shaft with arms, bea ings, and plates for fastening to ties; two 50 fo		
detector bars with driving pieces, and 32 motion		
plate rail clips, complete; connecting rods b		
tween switch and lock movement and rocking		
shaft, and between rocking shaft and detect		
bars; 2½" x ½", strap iron; and all the necessar		
pins, bolts, nuts, lag screws and rivets		
Ha Layout, as above, without detector bars or the		
fittings	348 00	




DIRECT ACTING ELECTRO-PNEUMATIC SWITCH MOVEMENT LAYOUT FOR SINGLE SWITCH WITHOUT DETECTOR BAR (For Classification Yards)


#### DIRECT ACTING ELECTRO-PNEUMATIC SWITCH MOVEMENT LAYOUT FOR SINGLE SWITCH WITHOUT DETECTOR BAR

#### (For Classification Yards.)

Magnets are wound to 400 ohms resistance unless otherwise specified. See page 171 for table of resistances.

		List Price	15
Fig.			
J	Layout for a single switch without detector bar. Specify weight of rail. Penna. R. R. Standard.		
	Assemblage: — Iron base plate for supporting cylinder and circuit controller on ties; tie plates, with riser		
	plates; switch cylinder and switch valve with- out lock magnet; rotary circuit controller; insu-		
	lated head and second switch rods; switch operat-		
	ing rod; right or left hand switch foot and con- necting rod between switch point and circuit		
	controller; and all the necessary pins, bolts, nuts, lag screws and rivets.	214 00	






ELECTRO-PNEUMATIC MOTION PLATE SWITCH AND LOCK MOVEMENT LAYOUTS, WITH DETECTOR BAR MOVEMENT, FOR SINGLE SWITCH WITH ONE DETECTOR BAR


### ELECTRO-PNEUMATIC MOTION PLATE SWITCH AND LOCK MOVEMENT LAYOUTS, WITH DE-TECTOR BAR MOVEMENT, FOR SINGLE SWITCH WITH ONE DETECTOR BAR

Mechanical details, such as front and lock rods, detector bars, rail clips. etc., are the U.S. & S. Co's. standard, and will be found in the mechanical catalogue.

Magnets are wound to 120 ohms resistance unless otherwise specified. See page 171 for table of resistances.

		List Price	
Fig.		1	
K	Layout for a single switch with detector bar ahead of points. Specify whether a right or left hand layout is desired, and weight of rail.  Assemblage: — Iron base plate for supporting cylinder and movements on ties; tie plate with riser plates; switch cylinder with valves and magnets; motion plate switch and lock movement with indication box; motion plate detector bar movement; switch operating rod and cage; front and lock rods; 50 foot detector bar with driving piece and 16 motion plate rail clips, complete; connecting rod between detector bar movement and detector bar; 2½"x½", strap iron; and all the necessary pins,		
	bolts, nuts, lag screws and rivets	316 00	
Ka	Layout, as above, without detector bar movement, detector bar, or its fittings	260 00	






ELECTRO-PNEUMATIC MOTION PLATE SWITCH AND LOCK MOVEMENT LAYOUTS, WITH DETECTOR BAR MOVEMENT, FOR SINGLE SWITCH WITH TWO DETECTOR BARS

#### ELECTRO-PNEUMATIC MOTION PLATE SWITCH AND LOCK MOVEMENT LAYOUTS, WITH DE-TECTOR BAR MOVEMENT, FOR SINGLE SWITCH WITH TWO DETECTOR BARS

Mechanical details, such as front and lock rods, detector bars, rail clips, rocking shafts, bearings, etc., are the U. S. & S. Co's. standard and will be found in the mechanical catalogue.

Magnets are wound to 120 ohms resistance unless otherwise specified. See page 171 for table of resistances.

I. Layout for a single switch with two detector bars back of points. Specify whether a right or left hand layout is desired, and weight of rail.  Assemblage:—Iron base plate for supporting cylinder and movements on ties; tie plate with riser plates; switch cylinder with valves and magnets; motion plate switch and lock movement with indication box; motion plate detector bar movement; switch operating rod and cage; front and lock rods; rocking shaft with arms, bearings and plates for fastening to ties; two 50 foot detector bars with driving pieces and 32 motion plate rail clips, complete; connecting rods between detector bar movement and rocking shaft, and between rocking shaft and detector bars; two pieces, 2½"x½", strap iron; and all the necessary pins, bolts, nuts, lag screws and rivets.  La Layout, as above, without detector bar movement, detector bars or their fittings	376 00	



ELECTRO-PNEUMATIC SWITCH AND LOCK MOVEMENTS WITH CYLINDERS

#### ELECTRO-PNEUMATIC SWITCH AND LOCK MOVEMENTS WITH CYLINDERS

The No. 12 and No. 14 Switch and Lock Movements are identical, except that No. 12 is used with a solid lock rod, while No. 14 is arranged to accommodate an adjustable lock rod in which the distance between the notches may be varied at will.

Magnets are wound to 120 ohms resistance unless otherwise specified. See page 171 for table of resistances.

When ordering, specify layout for which movement is desired. For layouts see Plates 0815, 0817, 0819, 0821, 0823, 0825, and 0827.

		List Price	
Fig.			
A	No. 12 Switch and Lock Movement, complete, with a 5 inch metallic packed cylinder, switch valve, indication box, base plate and covers for movement and cylinder. When ordering, specify layout for which movement is desired. For layouts see		
	Plates 0815, 0817, 0825 and 0827 as above, with a 6 inch metallic packed cylin-	244 00	
Aa	der	246 00	
Ab	as above, with a 6½ inch metallic packed cylinder	248 00	
Ac	No. 14 Switch and Lock Movement, complete, with a 5 inch metallic packed cylinder, switch valve, indication box, base plate and covers for movement and cylinder. When ordering, specify layout for which movement is desired. For layouts see		
Ad	Plates 0815, 0817, 0825 and 0827 as above, with a 6 inch metallic packed cylin-	246 00	
Ae	der as above, with a 6½ inch metallic packed cyl-	248 00	
В	inder No. 12 Tandem Switch and Lock Movement, complete, with a 6½ inch metallic packed cylinder, switch valve, indication box, base plate and covers for movement and cylinder. When ordering, specify layout for which movement is desired.	250 00	* *
	For layouts see Plates 0819, 0821, 0823, and 0825	280 00	
Ba Bb	as above, without indication box and a 7½ inch	270 00	
	metallic packed cylinder	286 00	
Bc Bd	as above, without indication box  No. 14 Tandem Switch and Lock Movement, complete, with a 6½ inch metallic packed cylinder, switch valve, indication box, base plate and covers	276 00	
	for movement and cylinder. When ordering, specify layout for which movement is desired.	202 25	
Be	For layouts see Plates 0819, 0821, 0823, and 0825 as above, without indication box	282 00	
Bf	as above, with indication box and a 71/2 inch	2/2 00	
-	metallic packed cylinder	290 00	
Bg	as above, without indication box	280 00	

# ELECTRO-PNEUMATIC SWITCH AND LOCK MOVEMENTS AND DETAILS

The No. 12 and No. 14 Switch and Lock Movements are identical, except that No. 12 is used with a solid lock rod, while No. 14 is arranged to accommodate an adjustable lock rod in which the distance between the notches may be varied at will.


rd		List Price	
Fig.	No. 12 Switch and Lock Movement, complete, as-		
Λ	shown, with indication box	32 00	
	No. 14 Switch and Lock Movement, complete, with		
Aa	indication box	32 00	
В	No. 12 Tandem Switch and Lock Movement, com-		
	plete, as shown, with indication box	48 00	
Ba	as above, without indication box	38 00	
Bb	No. 14 Tandem Switch and Lock Movement, com-		
110	plete, with indication box	48 00	
Вс	as above, without indication box	38 00	
C	Switch Indication Box, Circuit Controller, complete,		
-	as shown	10 00	
	Base, as shown for No. 12 switch and lock move-		
I	ment	5 40	
	as above, for No. 14 switch and lock move-		
Ia		5 40	
	Stud, I" x 6", complete, with \( \frac{5}{8} \) inch hex nut for		
2	Stud, I x 6 , complete, with 8 men nex	30	
	guide rollers	48	
3	Strap for guide rollers	1 00	
4	Cotter, ¼" x 1¾", for stud Fig. 6. Price per hundred.	1 00	
5	Cap for lock rod guide rollers, for No. 12 switch and	36	
	lock movement	30	
5a	as above, for No. 14 switch and lock move-		
	ment.	44	
6	Stud, 11/4" x 51/4", complete, with cotter for switch		
	crank Fig. 19	30	
7	Guide Roller	36	
8	Operating Roller for slide bar	36	
9	Upper Slide Bar only, as shown, for single movements.	I 20	
98	as above, for No. 12 tandem movement	2 22	
9b	as above, for No. 14 tandem movement	2 22	1

# ELECTRO-PNEUMATIC SWITCH AND LOCK MOVEMENTS AND DETAILS

Fig.	Ĭ	List Price
9c	Slide Bar, for single movements, complete, with lugs, operating roller and stud, locking dogs, rivets, contact block and cap screws, (1-9, 1-10, 2-11, 1-8,	
9d	I-16, I-14, I-15, 6-13, 4-12, I-45, 2-46, Plate 0837). Slide Bar, for No. I2 tandem movement, complete, as above, (I-9a, I-10a, 2-II, 2-8, 2-I6, 2-I4, I-I5a, 9-	6 00
9e	13, 4-12, 1-45, 2-46, Plate 0837)	10 70
	13, 4-12, 1-45, 2-46, Plate 0837)	10 70
10	Lower Slide Bar only, as shown, for single movements.	1 30
Ioa	as above, for tandem movements	2 22
11	Rivet, ½" x 3", for fastening lug Fig. 11 to slide	60
13	bars. Price per hundred	3 00
14	bar. Price per hundred	1 00
15	tandem movements  Lower Locking Dog, for slide bar, for single move-	28
	ments	22
15a	as above, for tandem movements	24
16	Stud for operating roller of slide bar	16
17	Strap for switch crank and intermediate guide roller	48
18	Stud for intermediate guide roller	16
19	Switch Crank, as shown, for No. 12 switch and lock	
	movement	2 90
19a	as above, for No. 14 switch and lock move-	
20	Bolt and Nut, ¾ " x 10", for fastening movement to	2 90
21	tie. Price per hundred	12 00
22	to tie. Price per hundred  Bolt and Nut, 3/4 " x 8 ", for fastening movement to	12 00
	tie. Price per hundred	11 00

# ELECTRO-PNEUMATIC SWITCH AND LOCK MOVEMENTS AND DETAILS

		List Price	
Fig.			
23	Bolt and Nut, 34" x 71/2", for fastening movement to tie. Price per hundred	11 00	
24	Bolt and Nut, 34" x 234", for fastening movement	12 00	
	to base plate. Price per hundred	2 00	
25	34 inch Lock Washer. Price per hundred	2 00	
26	¾ inch Plate Washer. Price per hundred	I 10	
27	Indication box only, as shown	72	
28	Cover only, for indication box		
29	Insulating Separator, for indication box	22	
30	Top Insulation, for indication box	34	
31	Bottom Insulation, for indication box	34	
32	Top Insulating Plate, for indication box	22	
33	Bottom Insulating Plate, for indication box	20	
34	Insulation only, for cover of indication box	12	
35	Machine Screw, No. 6-32 x ½", for fastening insulation		
	Fig. 34 to cover of indication box. Price per		
	hundred	I 00	
36	Insulating Bushing for indication box	02	
37	Terminal Post, for indication box, complete, as shown,		
	with nuts and insulating bushing	10	
38	as above, without insulating bushing	08	
39	Contact Spring for indication box	20	
40	Spring, complete, with two rivets, 1/8" x 3/8", and		
	pin, No. 30 x 7/16", for fastening cover to indica-		
	tion box	24	
41	Connector for terminal posts of indication box.	02	
42	Connector and Lock Plate for terminal posts of in-		
	dication box	20	
43	Nut Lock for cap screw Fig. 46	02	
44	Rivet, 3/16" x I", for fastening cover to indication		
	box. Price per hundred	I 00	
45	Contact Block, for slide bar, complete, with insulating		
	block, contact plate and rivets for fastening in-		
	sulating block to contact block	90	
46	Cap Screw, 1/4" x 5/8", for fastening contact block		
	to slide bar. Price per hundred	2 00	



ELECTRO-PNEUMATIC MOTION PLATE SWITCH AND LOCK MOVEMENT

## ELECTRO-PNEUMATIC MOTION PLATE SWITCH AND LOCK MOVEMENT

Magnets are wound to 120 ohms resistance unless otherwise specified. See page 171 for table of resistances.

When ordering, specify layout for which movement is desired. For layouts see Plates 0831 and 0833.


		I,ist Price	
Fig.			
A	Motion Plate Switch and Lock Movement, complete, as shown, with base plate, cylinder, switch valve, indication box and detector bar movement. When ordering, specify layout for which movement is		
	desired. For layouts see Plates 0831 and 0833.	248 00	
I	Motion Plate, for switch and lock movement, com-		
	plete, as shown, with slide bars	8 58	
III	Motion Plate only	3 60	
112	Upper Slide Bar only	I 00	
II2a	Lower Slide Bar only	00 I	
113	Lug for slide bar	70	
2	Cap for guide rollers of switch and lock movement for		
	switch operating slide bar	1 10	4 3
3	Roller for slide bar Fig. 5	34	
4	Pin, 78" x 238", complete, with cotter, for slide bar		
	Fig. 5	10	
5	Switch Operating Slide Bar, complete, as shown, with		
	roller and pin, (1-3, 1-4, Plate 0839)	6 50	

# ELECTRO-PNEUMATIC MOTION PLATE SWITCH AND LOCK MOVEMENT

51 Filling Block, for slide bar. 52 Lower Slide Bar only. 53 Upper Slide Bar only. 54 Rivet, ¼" x 7/16", for fastening lock Fig. 56 to upper slide bar. Price per hundred. 55 Cotter, ¼" x 1½", for lock Fig. 56. Price per hundred. 56 Lock for securing pin Fig. 4 in slide bar. 61 Indication Box, complete, as shown. 62 Indication Box only, with insulating plates and separator. 63 Cover only, with insulating plate, for indication box. 64 Terminal Post, for indication box, complete, with nuts, washer and insulating bushing. 65 Bolt for contact spring, complete, with nuts, washer, insulating bushing, and plate for connecting to terminal post 66 Rivet, ¾16" x 1", for fastening cover to indication box.  Price per hundred 67 Spring for fastening cover to indication box, complete, with two rivets, ½8" x ¾8", and pin, No. 30 x 7/16". 68 Bushing, for wire openings in indication box. 7 Contact Block, for slide bar of Fig. I, complete, as shown, with insulating block, contact plate and	Fig.		List Price	
Lower Slide Bar only  Upper Slide Bar only  Rivet, ¼" x ¾6", for fastening lock Fig. 56 to upper slide bar. Price per hundred  Cotter, ¼" x 1½", for lock Fig. 56. Price per hundred  Lock for securing pin Fig. 4 in slide bar.  Indication Box, complete, as shown.  Indication Box only, with insulating plates and separator.  Cover only, with insulating plate, for indication box.  Contact Spring for indication box, complete, with nuts, washer and insulating bushing.  Bolt for contact spring, complete, with nuts, washer, insulating bushing, and plate for connecting to terminal post  Rivet, ¾6" x 1", for fastening cover to indication box.  Price per hundred  Spring for fastening cover to indication box, complete, with two rivets, ½8" x ¾8", and pin, No. 30 x ¾6".  Bushing, for wire openings in indication box  Contact Block, for slide bar of Fig. I, complete, as shown, with insulating block, contact plate and	270	Filling Block, for slide bar	34	
Upper Slide Bar only  Rivet, ¼" x ¾ x 1½", for fastening lock Fig. 56 to upper slide bar. Price per hundred  Cotter, ¼" x 1½", for lock Fig. 56. Price per hundred  Lock for securing pin Fig. 4 in slide bar.  Indication Box, complete, as shown.  Indication Box only, with insulating plates and separator.  Cover only, with insulating plate, for indication box.  Contact Spring for indication box, complete, with nuts, washer and insulating bushing.  Bolt for contact spring, complete, with nuts, washer, insulating bushing, and plate for connecting to terminal post  Rivet, ¾ 6" x 1", for fastening cover to indication box.  Price per hundred  Spring for fastening cover to indication box, complete, with two rivets, ½ x 3 3", and pin, No. 30 x ½ 6".  Bushing, for wire openings in indication box  Contact Block, for slide bar of Fig. I, complete, as shown, with insulating block, contact plate and	52	Lower Slide Bar only		
Rivet, ½" x ¾" x ¾" for fastening lock Fig. 56 to upper slide bar. Price per hundred	53	Upper Slide Bar only		
Cotter, ¼" x 1½", for lock Fig. 56. Price per hundred	54	Rivet, ¼" x 1/16", for fastening lock Fig. 56 to upper		
56 Lock for securing pin Fig. 4 in slide bar	55	Cotter, ¼"x 1½", for lock Fig. 56. Price per hun-		
6 Indication Box, complete, as shown 61 Indication Box only, with insulating plates and separator 62 Cover only, with insulating plate, for indication box. 63 Contact Spring for indication box, complete, with nuts, washer and insulating bushing. 65 Bolt for contact spring, complete, with nuts, washer, insulating bushing, and plate for connecting to terminal post 66 Rivet, ¾6" x I", for fastening cover to indication box.  Price per hundred 67 Spring for fastening cover to indication box, complete, with two rivets, ½" x ¾8", and pin, No. 30 x ¼6". 68 Bushing, for wire openings in indication box 7 Contact Block, for slide bar of Fig. I, complete, as shown, with insulating block, contact plate and	r6	Look for coording him this simplify has	I IO	
61 Indication Box only, with insulating plates and separator	1000	Tradication Beautiful pin Fig. 4 in sinde par	40	
rator			10 00	
Cover only, with insulating plate, for indication box.  Contact Spring for indication box.  Terminal Post, for indication box, complete, with nuts, washer and insulating bushing.  Bolt for contact spring, complete, with nuts, washer, insulating bushing, and plate for connecting to terminal post  Rivet, %16" x I", for fastening cover to indication box.  Price per hundred  Spring for fastening cover to indication box, complete, with two rivets, ½" x ¾", and pin, No. 30 x ½".  Bushing, for wire openings in indication box  Contact Block, for slide bar of Fig. I, complete, as shown, with insulating block, contact plate and	01			De mi
Contact Spring for indication box	62	Cover only, with insulating plate for indication boy		100
Terminal Post, for indication box, complete, with nuts, washer and insulating bushing.  Bolt for contact spring, complete, with nuts, washer, insulating bushing, and plate for connecting to terminal post  Rivet, %6" x I", for fastening cover to indication box.  Price per hundred  Spring for fastening cover to indication box, complete, with two rivets, ½" x ¾", and pin, No. 30 x ½".  Bushing, for wire openings in indication box  Contact Block, for slide bar of Fig. I, complete, as shown, with insulating block, contact plate and	63	Contact Spring for indication box		
65 Bolt for contact spring, complete, with nuts, washer, insulating bushing, and plate for connecting to terminal post  66 Rivet, ¾6" x I", for fastening cover to indication box.  Price per hundred  67 Spring for fastening cover to indication box, complete, with two rivets, ½" x ¾", and pin, No. 30 x ¼6".  68 Bushing, for wire openings in indication box  Contact Block, for slide bar of Fig. I, complete, as shown, with insulating block, contact plate and		Terminal Post, for indication box, complete, with nuts,	28	
66 Rivet, 3/6" x 1", for fastening cover to indication box.  Price per hundred  67 Spring for fastening cover to indication box, complete, with two rivets, ½" x 3/8", and pin, No. 30 x 7/16".  68 Bushing, for wire openings in indication box  Contact Block, for slide bar of Fig. 1, complete, as shown, with insulating block, contact plate and	65	Bolt for contact spring, complete, with nuts, washer, insulating bushing, and plate for connecting to	30	
Price per hundred  67 Spring for fastening cover to indication box, complete, with two rivets, ½" x ¾", and pin, No. 30 x ½".  68 Bushing, for wire openings in indication box			16	
67 Spring for fastening cover to indication box, complete, with two rivets, ½" x ¾", and pin, No. 30 x ½".  68 Bushing, for wire openings in indication box  7 Contact Block, for slide bar of Fig. 1, complete, as shown, with insulating block, contact plate and	66			
with two rivets, ½" x ¾", and pin, No. 30 x ½".  88 Bushing, for wire openings in indication box			1 00	
68 Bushing, for wire openings in indication box	67			
7 Contact Block, for slide bar of Fig. 1, complete, as shown, with insulating block, contact plate and	68	Bushing for wire openings in indication how		
shown, with insulating block, contact plate and	7	Contact Block for slide bar of Fig. 1 complete as	02	
sixote for forth in the same		shown, with insulating block contact plate and		
invers for fastening insulating block to contact		rivets for fastening insulating block to contact		
block		block	04	

# ELECTRO-PNEUMATIC MOTION PLATE SWITCH AND LOCK MOVEMENT

	Ţ	List Price	
Fig.	w sw s s itest block to		
8	Cap Screw, ¼" x 5%", for fastening contact block to slide bar of Fig. 1. Price per hundred	2 00	
9	Motion Plate, for detector bar movement	2 90	
IO	Guide Roller for lock rod of switch and lock move-		
	ment	34	
II	Guide Roller for slide bar Fig. 5	34	
12	Base for switch and lock movement, complete, as shown, with studs, nuts and cotters, for guide		
12a	rollers	7 40	
	operating slide bar, guide rollers, cap, contact		
	block with screws, and indication box, (1-12,		
	1-1, 1-5, 4-10, 4-11, 1-2, 1-7, 2-8, 1-6, Plate 0839).	53 00	
13	Base for detector bar movement, complete, as shown,		
	with studs and cotters, for guide rollers	5 40	
13a	as above, complete, with crank, pin, cotter,		
	bolt, rollers and straps, (1-13, 1-17, 1-18, 1-19, 1-15,		
	1-16, 4-14, 2-20, Plate 0839)	15 00	
14	Guide Roller for detector bar movement	34	
15	Bolt, complete, as shown, with nut and lock washer		
	for crank Fig. 17	1 66	
16	Roller, for crank Fig. 17	34	
17	Crank only, for detector bar movement	3 00	
17a	as above, complete, with bolt and roller,		
	(1-17, 1-15, 1-16, Plate 0839)	5 30	
18	Pin for fastening crank Fig. 17 to base Fig. 13	22	
19	Cotter for fastening pin Fig. 18 to base Fig. 13. Price		
-	per hundred	1 00	
20	Strap for guide rollers of detector bar movement	44	



ELECTRO-PNEUMATIC SWITCH VALVE AND CYLINDERS

# ELECTRO-PNEUMATIC SWITCH VALVE AND CYLINDERS

# For Switch Valve and Details see Plate 0849

While this plate includes cylinders with metallic and leather packing the object in illustrating the latter is for convenience in ordering renewals, as on all new work we furnish cylinders with metallic packing unless otherwise specified.

Magnets are wound to 120 ohms resistance unless otherwise specified. See page 171 for table of resistances.

When ordering specify whether right or left hand cylinder is desired. The cylinders shown on the opposite plate are right hand.

		I,ist Price
Fig.		
A	5-inch Cylinder and Valve, complete, with leather packing. When ordering specify whether right or left hand is desired. Right hand is shown.	158 00
Аа	6-inch, as above	160 00
Ab	6½-inch, as above	162 00
Ac	71/-inch as above	170 00
В	5-inch Cylinder and Valve, complete, with metallic packing. When ordering specify whether right	
	or left hand is desired. Right hand is shown.	166 00
Ba	6-inch, as above	168 00
Bb	6½-inch, as above	170 00
Вс	7½-inch, as above	178 00
Ia	5-inch Cylinder only, as shown, for leather packing as above, complete, with heads, stuffing box, gaskets, bolts, nuts, piston complete, and oil	10 60
	plugs, (1-1, 1-12, 1-13a, 2-14, 4-27, 6-23, 1-2b,	
	2-24 Plate 0841)	30 00
ıb	6-inch Cylinder only, for leather packing	10 80
IC	as above, complete, with heads, stuffing box, gaskets, bolts, nuts, piston complete, and oil plugs, (I-Ib, I-I2a, I-I3c, 2-I4a, 4-27, 6-23, I-2c,	
	2-24 Plate 0841)	32 00
ıd	6½-inch Cylinder only, for leather packing.	12 60
Ie	as above, complete, with heads, stuffing box, gaskets, bolts, nuts, piston complete, and oil plugs, (1-Id, 1-12b, 1-13e, 2-14b, 4-27, 6-23, 1-2d, 2-24,	
	Plate 0841)	34 00
If	71/2-inch Cylinder only, for leather packing	17 60
Ig	as above, complete, with heads, stuffing box, gaskets, bolts, nuts, piston complete, and oil plugs, (1-1f, 1-12c, 1-13g, 2-14c, 4-27, 6-23, 1-2e, 2-24,	
	Plate 0841)	42 00

#### ELECTRO-PNEUMATIC SWITCH VALVE AND CYLINDERS

For Switch Valve and Details see Plate 0849

			-
		List Price	
Fig.			
2	Piston Rod only, as shown, for leather packed cylin-		
	der	1 65	
2a	as above, complete, with screw jaw, lock nut,	. 6.	
2b	pin and cotter, (I-2, I-2I, I-20, I-22, Plate 084I).  Piston, for 5-inch leather packed cylinder, complete,	2 64	
210	with piston rod, piston head, followers, lead		
	washer, leather packing, washers, nut and lock		
	washer, (1-2a, 1-4, 1-8, 1-9, 2-6, 1-3, 2-7, 2-5, 1-11,		
	I-Io, Plate 0841)	9 90	
2C	Piston, for 6-inch leather packed cylinder, complete,		
	as above, (1-2a, 1-4a, 1-8a, 1-9a, 2-6a, 1-3, 2-7a, 2-5a, 1-11, 1-10, Plate 0841)	10.30	
2d	Piston for 6½-inch leather packed cylinder, complete,	10 30	
	as above, (1-2a, 1-4b, 1-8b, 1-9b, 2-6b, 1-3, 2-7b,		
	2-5b, I-II, I-Io, Plate 0841)	11 30	
2e	Piston for 7½-inch leather packed cylinder, complete,		
	as above, (1-2a, 1-4c, 1-8c, 1-9c, 2-6c, 1-3, 2-7c, 2-5c, 1-11, 1-10, Plate 0841)		
	2-5c, 1-11, 1-10, Plate 0841)	12 80	
3 4	Lead Washer for piston rod	02	
4	cylinder	2 00	
48	as above, for 6-inch leather packed cylinder.	2 20	
4b	as above, for 61/2-inch leather packed cylinder	2 30	
4C	as above, for 7½-inch leather packed cylinder.	2 50	
5	Washer, as shown, for piston of 5-inch leather packed		
	cylinder as above, for piston of 6-inch leather packed	10	
5a	cylinder	10	3
5b	as above, for piston of 6½-inch leather packed		
	cylinder	12	
5c	as above, for piston of 7½-inch leather packed		9
	cylinder	12	
6	Spring Follower, as shown, for piston of 5-inch leather	**	
6a	packed cylinder	12	
	evlinder	12	1
6b	eylinder		1
	packed cylinder.	14	1
6c	as above, for piston of 7½-inch leather		1
~	packed cylinder	16	1
7	packed cylinder	90	
7a	as above, for piston of 6-inch leather packed	90	1
	cylinder	1 00	
7b	as above, for piston of 61/2-inch leather packed		
	cylinder	1 10	
7C	as above, for piston of 71/2-inch leather packed	T 20	
	cylinder	1 301	1

## ELECTRO-PNEUMATIC SWITCH VALVE AND CYLINDERS

For Switch Valve and Details see Plate 0849

		List Price	
			The same
Fig.			
8	Intermediate Piston Follower, as shown, for 5-inch	,	6
	leather packed cylinder	I 60	
8a	as above, for 6-inch leather packed cylinder.	I 80	State
8b	" " 6½" " "	2 00	
8c	" " 7½" " " "	2 20	
9	End Piston Follower, as shown, for 5-inch leather		
1	packed cylinder	90	
9a	as above for 6-inch leather packed cylinder.	I IO	
9b	" " 6½-inch " "	I 20	TA STATE
9c	" " 7½-inch " " "	I 30	
10	Lock Washer, for piston head of leather packed		
	owlinder	04	
II	Nut, for piston head of leather packed cylinder	56	
12	Back Head, as shown, for 5-inch leather packed cylin-		
	der	I 54	
12a	as above, for 6-inch leather packed cylinder	1 66	
12b	" " 6½-inch " " "	1 88	
I2C	" " " 7½-inch " " " "	2 20	
13	Front Head only, as shown, for 5-inch leather packed	2 46	
-	cylinder	2 76	
13a	as above, complete, with stuffing box, (1-13,	4 76	
	1-15, 1-16, 1-17, 1-18, 1-19, Plate 0841)		
13b	Front Head only, for 6-inch leather packed cylinder.	3.08	
13c	as above, complete, with stuffing box, (1-13b,	- 06	
1	1-15, 1-16, 1-17, 1-18, 1-19, Plate 0841)	5 06	
13d	Front Head only, for 61/2-inch leather packed cylinder.	3 08	
13e	as above, complete, with stuffing box, (I-I3d,	5 16	
	1-15, 1-16, 1-17, 1-18, 1-19, Plate 0841).	3 66	
13f	Front Head only, for 71/2-inch leather packed cylinder.	3 00	
13g	as above, complete, with stuffing box, (1-13f,	F 70	
	1-15, 1-16, 1-17, 1-18, 1-19, Plate 0841)	5 70 12	
14	Gasket, for head of 5-inch leather packed cylinder	12	1
14a	as above, for head of 6-inch leather packed	14	/
	cylinder	-	
14b	as above, for head of 61/2-inch leather packed	14	
	cylinder		1000
14c	as above, for head of 7½-inch leather packed	16	
	cylinder	30	
15	Spring, for stuffing box.	73	
16		16 1	A POST OF
17	Leather Packing, for stuffing box		100000000000000000000000000000000000000
18	Lock Nut, for stuffing box	10000	
19	Nut, for stuffing box	740	
20	Lock Nut, for screw jaw on piston rod	1	
21	Strew law, for Distoil rou		

# ELECTRO-PNEUMATIC SWITCH VALVE AND CYLINDERS


For Switch Valve and Details see Plate 0849

Fig.		List Price	
	This will said to		
22	Pin, 1/8" x 23/8", with cotter, for screw jaw Fig. 21 Bolt and Nut, 1/2" x 13/4", for fastening front or back	10	
1	head to leather packed cylinder	03	100
24	Oil Plug, for cylinder.	12	
25	rap Bolt, ½" x 3%", for fastening switch valve to		
26	Bolt and Nut, 1/2" x 23/8", for fastening front or back	06	
27	head to metallic packed cylinder	12	
-0	to cylinder. Price per hundred.	3 00	
28 28a	5-inch Cylinder only, as shown, for metallic packing. as above, complete, with heads, stuffing box, gaskets, bolts, nuts, piston complete, and oil plugs, (1-28, 1-34, 1-33a, 2-32, 4-27, 6-26, 1-29a, 4-24, Plate 0841)	12 80	
28b	6-inch Cylinder only for motalling	39 00	30
28c	6-inch Cylinder only, for metallic packing as above, complete, with heads, stuffing box, gaskets, bolts, nuts, piston complete, and oil plugs, (1-28b, 1-34a, 1-33c, 2-32a, 4-27, 6-26, 1-29c,	13 20	
28d	4-24, Plate 0841)	41 00	
28e	6½-inch Cylinder only, for metallic packing	14 30	
28e	as above, complete, with heads, stuffing box, gaskets, bolts, nuts, piston complete, and oil plugs, (1-28d, 1-34b, 1-33e, 2-32b, 4-27, 6-26, 1-29e, 4-24, Plate 0841)		
28f	7½-inch Cylinder only, for metallic packing.	43 00	
28g	as above, complete, with heads, stuffing box, gaskets, bolts, nuts, piston complete, and oil plugs, (1-28f, 1-34c, 1-33g, 2-32c, 4-27, 6-26, 1-29g, 4-24, Plate 0841)	16 00	
29	Piston and Piston Rod, as shown, with lead washer	51 00	
29a	Fig. 3, for 5 inch metallic packed cylinder as above, complete, with piston rings, gaskets, screw jaw, lock nut, pin and cotter, (1-29, 2-30,	9 40	
29b	2-31, 1-21, 1-20, 1-22, Plate 0841). Piston and Piston Rod, with lead washer Fig. 3, for	13 20	
29c	6 inch metallic packed cylinder.  as above, complete, with piston rings, gaskets, screw jaw, lock nut, pin and cotter, (1-29b, 2-30a,	8 50	
29d	Piston and Piston Rod, with lead washer Fig. 2 for	13 20	
29e	6½ inch metallic packed cylinder as above, complete, with piston rings, gaskets, screw jaw, lock nut, pin and cotter, (1-29d, 2-30b,	11 00	
	2-31b, 1-21, 1-20, 1-22, Plate 0841)	16 00	1

## ELECTRO-PNEUMATIC SWITCH VALVE AND CYLINDERS

For Switch Valve and Details see Plate 0849

		List Price	
Fig.			
29f 29g	Piston and Piston Rod, with lead washer Fig. 3, for 7½ inch metallic packed cylinder	13 20	
30	2-31c, 1-21, 1-20, 1-22, Plate 0841)	18 30	
3	inder	I 00	
30a 30b	as above, for 6 inch metallic packed cylinder as above, for 6½ inch metallic packed cyl-	1 30	
30c	as above, for 7½ inch metallic packed cyl-	1 40	
	inder	I 60	
31	Gasket, for 5 inch piston Fig. 29	46	591
31a	as above, for 6 inch piston Fig. 29b	56	
31b	as above, for 61/2 inch piston Fig. 29d	62	
31c	as above, for 71/2 inch piston Fig. 29f	70	
32	Gasket, as shown, for head of 5 inch metallic packed		
32a	cylinder	22	
	cylinder.	24	
32b	as above, for head of 61/2 inch metallic packed		
32C	cylinder	26	
33	cylinder. Front head only, as shown, for 5 inch metallic packed	30	
	cylinder.	4 20	
33a	as above, complete, with stuffing box, (1-33, 1-15, 1-16, 1-17, 1-18, 1-19, Plate 0841).	6 40	
33b	Front Head only, for 6 inch metallic packed cylinder.	4 70	
33c	as above, complete, with stuffing box, (1-33b,		
33d	I-15, I-16, I-17, I-18, I-19, Plate 0841) Front Head only, for 6½ inch metallic packed cyl-	6 80	
	inder	5 00	
33e	as above, complete, with stuffing box, (1-33d,		
	1-15, 1-16, 1-17, 1-18, 1-19, Plate 0841)	7 30	
33f	Front Head only, for 7½ inch metallic packed cylinder	5 30	
33g	as above, complete, with stuffing box, (1-33f,		
34	Back Head, as shown, for 5 inch metallic packed	7 00	
	cylinder	2 90	
34a	as above, for 6 inch metallic packed cylinder.	3 10	
34b	as above, for 6½ inch metallic packed cylin-		
34c	der	3 30	
	der	3 70	1




ELECTRO-PNEUMATIC SWITCH CYLINDER WITH LEATHER PACKING AND SWITCH VALVE APPLIED TO BACK CYLINDER HEAD

## ELECTRO-PNEUMATIC SWITCH CYLINDER WITH LEATHER PACKING AND SWITCH VALVE APPLIED TO BACK CYLINDER HEAD

For Application see Plate 0839. For Switch Valve see Plate 0849.

Magnets are wound to 120 ohms resistance unless otherwise specified. See page 171 for table of resistances.

		I,ist Price	
Fig.			
A	5" x 9" Cylinder and Valve, complete, as shown, with leather packing. Specify resistance of magnets when ordering	168 00	
I	Piston Rod only, with lead washer	I 90	
Ia	Piston, complete, with piston rod, piston head, followers, packing, washers, nut for piston head, lock washer, screw jaw, and lock nut, (I-I, I-2, I-20, I-23, 2-21, 2-22, 2-19, I-15, I-14, I-6a, I-12, Plate 0843).	11 00	
2	Piston Head only	2 30	
2	Lock Nut for stuffing box	- 44	
3	Nut for stuffing box	90	
4	Spring for stuffing box	30	
3 4 5 6	Screw Jaw only, as shown, for piston rod	72	
6a	as above, complete, with pin and cotter	82	
	Tap Bolt, ½" x 1¼", for fastening back head to cyl-	02	
7	inder. Price per hundred.	3 00	
0	Bolt and Nut, ½" x 178", for fastening back head to	3 00	584
8	Bolt and Nut, 1/2 x 1/8, for fastering back field to	12	
18	cylinder. Bolt and Nut, $\frac{1}{2}$ " x $2\frac{5}{6}$ ", for fastening back head to	12	
9	cylinder	12	
10	Leather Packing for stuffing box	44	
II	Gland for stuffing box	08	
12	Lock Nut for screw jaw on piston rod	20	5.7
13	Cylinder, as shown, with gasket for back head	12 00	33321
13a	as above, complete, with head, stuffing box, piston, bolts, nuts and oil plug, (1-13, 1-24a, 1-4,		
	1-3, 1-5, 1-10, 1-11, 1-1a, 1-7, 4-8, 1-9, 1-18,		
	Plate 0843)	44 00	
TA	Lock Washer for piston head	06	
14	Nut for piston head	60	
15	Lead Washer for air ports in back cylinder head	06	
	Sleeve for air ports in back cylinder head	08	
17 18	Oil Plug for cylinder	12	
	Washer for piston	IO	
19	End Follower for piston	90	
20	Spring Follower for piston	12	
21			1000
22	Leather Packing for piston		L 33
23	Intermediate Follower for piston	12 00	
24	Combined Back Cylinder Head and Valve Base only.	12 00	
24a	as above, complete, with oil plug, sleeves and		1970. 9
	washers for air ports, (1-24, 1-18, 3-17, 2-16, Plate		Diane.
	0843)	12 70	1




ELECTRO-PNEUMATIC SWITCH CYLINDER WITH METALLIC PACKING AND SWITCH VALVE APPLIED TO BACK CYLINDER HEAD

## ELECTRO-PNEUMATIC SWITCH CYLINDER WITH METALLIC PACKING AND SWITCH VALVE APPLIED TO BACK CYLINDER HEAD

(For Direct Acting Purposes Only)

For application see plate 0829. For switch valve see plate 0849. Magnets are wound to 400 ohms resistance unless otherwise specified. See page 171 for table of resistances.

		List Price	
Fig.			
A	4"x4" Cylinder and Valve, complete, as shown. Specify resistance of magnets when ordering	144 00	
Aa	4" x 5" Cylinder and Valve, complete. Specify resistance of magnets when ordering	144 00	
1	Gasket for end of cylinder	22	
2	Gasket for piston	44	
3	Oil Plug for cylinder	12	
4	Stud, 1/2" x 5-1/2", complete, with nut, for fastening		
7	switch valve and back cylinder head to cylinder.	12	
5	Piston and Piston Rod, as shown, with lead washer Fig.		
3	6 for A" x A" evlinder	8 30	
5a	as above, complete, with piston rings, gaskets,		
-	screw eye and lock nut, (1-5, 2-7, 2-2, 1-13, 1-12,		
	Plate 0845)	14 30	
5b	Piston and Piston Rod, with lead washer Fig. 6 for		
	4" v 5" cylinder	7 00	
5c	as above, complete, with piston rings, gaskets,		
	screw eye and lock nut, (1-5b, 2-7, 2-2, 1-13, 1-12,	1	
	Plate 0845)	13 20	
6	Lead Washer for piston rod	02	
7	Piston Ring	I 00	2.5
8	Spring for stuffing box	30	
9	Gland for stuffing box	08	
10	4" x 4" Cylinder only, as shown	11 40	
Ioa	as above, complete, with head, gasket, stuffing		
	box, piston, studs and oil plugs, (1-10, 1-14, 1-1,		
	1-16, 1-15, 1-11, 1-9, 1-8, 1-5a, 4-4, 2-3, Plate 0845).	40 00	
10p	4" x 5" Cylinder only	11 34	
IOC	as above, complete, with head, gasket, stuffing		
	box, piston, stud sand oil plugs, (I-10b, I-14, I-1,	20.00	
	1-16, 1-15, 1-11, 1-9, 1-8, 1-5c, 4-4, 2-3, Plate 0845).	39 00	
II	Leather Packing for stuffing box	44 20	1000000
12	Lock Nut for screw eye on piston rod		
13	Screw Eye for piston rod	13 20	1000
14	Lock Nut for stuffing box	44	
15	Nut for stuffing box	90	
16	Nut for stunding box	30	



ELECTRO-PNEUMATIC SWITCH VALVE, CIRCUIT CONTROLLER AND CASE

(For use where it is not practicable to attach valve directly to cylinder).


# ELECTRO-PNEUMATIC SWITCH VALVE, CIRCUIT CONTROLLER AND CASE

(For use where it is not practicable to attach valve directly to cylinder)

For switch valve see Plate 0849.

Magnets are wound to 120 ohms resistance unless otherwise specified. See page 171 for table of resistances.

Fig.		List Price
A	Electro-Pneumatic Switch Valve, Circuit Controller	
A	and Case, complete, with cover and lock	180 00
1	Base Plate, for circuit controller	2 20
2	Cap Screw, 3/8"x 7/8", for fastening base plate Fig. 1 to	
	case. Price per hundred	3 00
3	case. Price per hundred	
	two rivets, 3/16"x5%", for fastening to holder	
	Fig. 10	56
4	Pin, for stopping rotary movement of circuit control-	
	ler shaft	08
5	Plug, for case	02
6	Flat Head Machine Screw, ¼"x½", for fastening	
	handle to cover. Price per hundred	1 10
7 8	Handle for cover	90
	Shaft only, for circuit controller	4 30
8a	as above, complete, with dowel pin and	6
0	cap, (1-8, 1-81, 1-82, Plate 0847)	5 06
81	Dowel Pin only, for fastening cap to circuit con-	**
0	troller shaft	10
82	Cap only, for circuit controller shaft	70
9	Contact Bracket for circuit controller, complete, with	
	dowel pin for fastening to shaft, and two rivets, \\\\\'\x\13\'\6'' for fastening holder Fig. 10	2 10
-	Holder for contact plate of circuit controller	72
IO	Terminal Post and Contact Spring, for circuit con-	12
11	troller, complete, as shown, with nuts, washers,	A
	insulating bushing and washers	1 00
12	Valve Base, as shown	3,30
13	Eye Bolt, complete, with lock nut, for circuit control-	3.5-
13	ler shaft	22
14	Cover for case, complete, as shown, with handles,	
-4	screws and staple, (2-7, 8-6, 1-15, Plate 0847)	15 00
15	Staple for cover	12
16	Lead Gasket for valve base	06
17	Bolt and Nut. 1/2"x2", for fastening valve base to case.	
15	Price per hundred	5 00
18	Bolt and Nut 1/"x51/", for fastening valve to valve	
	base. Price per hundred	8 00
19	Hasp, complete, with rivet, 1/2 x17/16", for fastening	
	to case	34
20	Case only	12 00



ELECTRO-PNEUMATIC SWITCH VALVE


## ELECTRO-PNEUMATIC SWITCH VALVE

Magnets for switch valve in Fig. A are wound to 400 ohms resistance and in Fig. B to 120 ohms resistance unless otherwise specified. See page 171 for table of resistances.

		List Price	
ig.			
A	Switch Valve, complete, without lock magnet, used		
	on end of cylinder	110 00	
В	as above, with lock magnet, used on side or		
	end of cylinder		
I	Magnet Cap, complete, as shown, with plug and		
	chain	I 68	
III	Magnet Cap only	I 28	
112	Plug and Chain only	40	
2	Armature, complete, with stem	3 00	
2a	Spring for releasing armature	16	10
3	Magnet only. Specify resistance when ordering	13 80	
3a	as above, complete, with armature, spring for		
	releasing armature and cap. Specify resistance		
	when ordering. (1-3, 1-2, 1-2a, 1-1, Plate 0849)	18 00	100
1	Plug for Fig. A, to take the place of lock cylinder	1 10	1
5	Tap Bolt, 1/2"x35%", for fastening valve chamber Fig.		1
	15 and valve seat Fig. 20 to switch cylinder	06	
5	Pin Valve, complete, with spring, for lock magnet	72	
51	Spring only	34	1

### ELECTRO-PNEUMATIC SWITCH VALVE


		List Price	
Fig.			
62	Pin Valve only	38	
7	Head for lock cylinder Fig. 9	2 16	
8	Spring for lock cylinder Fig. 9	36	
9	Lock Cylinder	3 50	
IO	Piston for lock cylinder Fig. 9	3 20	
II	Stud, 1/2" x 5 1/2", with nut, for fastening valve chamber		
	Fig. 15 and cylinder head Fig. 31 to switch cyl-		
	inder	12	
12	Pin Valve Guide for lock cylinder head Fig. 7	44	
13	Gasket for head of valve chamber	06	
14	Oil Plug for valve chamber	12	
15	Valve Chamber, complete, with two guides for pin		
	valve Fig. 21 and two washers	12 00	
16	Piston Ring for switch valve piston Fig. 17	80	
17	Piston only, for switch valve	4 60	
17a	as above, complete, with piston rings, (1-17,		
	2-16, Plate 0849)	6 20	13.5
18	Head for valve chamber	40	
19	Saddle for "D" valve	2 30	
20	Valve Seat for Fig. B	7 00	
21	Pin Valve, as shown, with spring and plug, for nor-		
	mal or reverse magnet	I 06	



COVERS FOR ELECTRO-PNEUMATIC SWITCH CYLINDERS AND SWITCH AND LOCK MOVEMENTS

### COVERS FOR ELECTRO-PNEUMATIC SWITCH CYL-INDERS AND SWITCH AND LOCK MOVEMENTS

Fig.		I,ist Price	
A	Covers, complete, for valve, 7½ inch cylinder, and single switch and lock movement, (1-5, 1-6, 1-4,		
Aa	Plate 0851)	15 00	
В	1-4, Plate 0851)  Covers, complete, for valve, 7½ inch cylinder, and tandem switch and lock movement, (1-5, 1-6, 1-2,	15 00	
Ва	1-3, Plate 0851)	21 00	
1	1-2, 1-3, Plate 0851).  Cover, for single switch and lock movement without cylinder, complete, with two heads Fig. 12, bolts	21 00	
2	and nuts Short End of Cover, for tandem switch and lock movement, complete, with head Fig. 12, lap strip, bolts	6 30	
3	and nuts	5 90	
4	ment, complete, with head Fig. 12, bolts and nuts. Cover, for single switch and lock movement with	6 60	
	cylinder, complete, with head Fig. 12, bolts and nuts	8 00	
5	Cover, for switch valve, for 71/2 inch cylinder	3 30	
5a 6	as above, for 5, 6, or 6½ inch cylinder Cover, for 7½ inch cylinder, complete, with heads,	3 30	
	bolts and nuts, (1-14, 1-13, Plate 0851)	5 30	
6a	Cover only, for 7 1/2 inch cylinder	3 30	
6b	Cover, for 5, 6, or 6½ inch cylinder, complete, with heads, bolts and nuts, (1-14, 1-13, Plate 0851)	4° 80	
6c	Cover only, for 5, 6, or 6½ inch cylinder	2 90	
7	Yoke, for supporting switch valve cover, complete, with single hole cable strap, bushing and rivet,		
7a	(1-71, 1-72, 1-73, Plate 0851). as above, with double hole cable strap, (1-7,	2 42	
	I-7Ia, 2-72, I-73, Plate 0851)	2 54	
71	Cable Strap only, with one hole	24	2000
71a	as above, with two holes	32	
72 73	Bushing for cable strap.  Rivet, ½"x¾", for fastening cable strap to yoke.	26	
8	Price per hundred	2 00	8 10 2
8a	Filler, as shown, for 7½ inch cylinder cover	2 IO I 66	
8b	as above, "6½" " " " " " " " " " " " " " " " " "		3
9	Lag Screw, 1/2"x21/2", for fastening yoke and filler to	I 32	
10	wood base plate. Price per hundred. Bolt and Nut, ½"x2½", for fastening yoke and filler	2 00	
11	Dowel Pin, for holding cover in place on iron base	6 00	
7.0	plate. Price per hundred	6 00	
12	Head for movement cover.	66	
13	Back Head for cylinder cover	66 70	11000
		1	




RESERVOIRS AND HOSE CONNECTIONS


# RESERVOIRS AND HOSE CONNECTIONS


## Order by Plate and Figure


# 51006

Fig.			ist
A	Auxiliary Reservoir, Standard Type, complete, as shown.	13	50
В	Auxiliary Reservoir, Elevated Railroad Type, complete,		
	as shown	7	80
Ba	as above, with blow-off cock on top	7	30
C	Combined Auxiliary Reservoir and Dwarf Signal Foun-		
	dation, complete, as shown	10	80
D	Auxiliary Reservoir, complete, as shown	12	70
E	Main Air Reservoir, complete, as shown. When order-		
	ing, specify size of air inlet and outlet	120	00
F	Hose connection, complete, as shown, with union	2	30
Fa	as above, without union	1	70










FLANGE UNIONS AND EXPANSION JOINTS

# FLANGE UNIONS AND EXPANSION JOINTS

Fig.		List Price	
A	inch, Cast Iron Insulated Flange Union, complete, with phœnix packing gaskets and five ½ inch bolts	4 70	
Aa	1½ inch, Wrot Iron Insulated Flange Union, complete, with pheenix packing gaskets and four ½ inch bolts		
B Ba	<ul> <li>2 inch, Cast Iron Insulated Flange Union, complete, with phœnix packing gaskets and five ½ inch bolts</li> <li>2 inch, Wrot Iron Insulated Flange Union, complete,</li> </ul>	4 80	
	with phœnix packing gaskets and four 1/2 inch bolls		
С	2½ inch, Cast Iron Insulated Flange Union, complete, with phoenix packing gaskets and five ½ inch bolts	5 70	
Ca	with phoenix packing gaskets and four ½ inch		
D	bolts 3 inch, Cast Iron Insulated Flange Union, complete, with phoenix packing gaskets and five ½ inch	6 90	
Da	bolts 3 inch, Wrot Iron Insulated Flange Union, complete, with phœnix packing gaskets and five ½ inch bolts	0 90	
E	4 inch, Cast Iron Insulated Flange Union, complete, with phoenix packing gaskets and seven ½ inch bolts	8 60	
Ea	4 inch, Wrot Iron Insulated Flange Union, complete, with phoenix packing gaskets and five ¾ inch		
F	1½ inch, Cast Iron Flange Union, complete, with lead	2 20	
Fa	gasket and five ½ inch bolts.  1½ inch, Wrot Iron Flange Union, complete, with lead	2 30	4
G	gasket and four % inch bolts  inch, Cast Iron Flange Union, complete, with lead gasket and five ½ inch bolts	2 30	
Ga	2 inch, Wrot Iron Flange Union, complete, with lead gasket and four 1/8 inch bolts		
Н	<ul> <li>2½ inch, Cast Iron Flange Union, complete, with lead gasket and five ¾ inch bolts</li> <li>2½ inch, Wrot Iron Flange Union, complete, with lead</li> </ul>	2 80	
J	gasket and five 5% inch bolts	3 80	
Ja	3 inch, Wrot Iron Flange Union, complete, with lead gasket and five % inch bolts		
K	4 inch, Cast Iron Flange Union, complete, with lead gasket and seven % inch bolts	5 40	
Ka	4 inch, Wrot Iron Flange Union, complete, with lead gasket and seven 5% inch bolts		
М .	34 inch, Expansion Joint for condenser, complete, as shown, with nipple 91/4 inches long	3 70	
Ma N	as above, with nipple 4½ inches long 2 inch, Expansion Joint for main air line, 6 inch	3 40	
Na	stroke, complete, as shown 2 inch, Expansion Joint for main air line, 14 inch	9 50	
Nb	stroke, complete	I2 20 I7 70	
Nc	3 inch, Expansion Joint for main air line, 10 inch stroke, complete	22 50	




The signals listed below include blades, glass, front and back spectacles, ladders and ladder foundations, anchor bolts and all other fittings shown on the following plates.

They do not include lamps, circuit controllers (except in Figs. 1 to 4 inclusive where a circuit controller forms a part of the mechanism), pole changers, number plates or reservoirs, which must be ordered separately when required. Any variations from the general dimensions shown on the following plates must be specifically called for when ordering.

Magnets are wound to 16, 120 and 400 ohms resistance, as per table of resistances on page 171.

Fig.  1 Electro-Pneumatic Rotary Pot Signal, 1 foot 6¾ inches from base to the center of lens opening. See Plate o887			9.	
Electro-Pneumatic Rotary Pot Signal, 1 foot 6¾ inches from base to the center of lens opening. See Plate o887.  as above, 8 feet from base to the center of lens opening. See Plate o887.  One Arm, 60°, Electro-Pneumatic Dwarf Signal. See Plate o875.  Two Arm, as above. See Plate o877.  One Arm, 60°, Electro-Pneumatic Bridge or Bracket Signal. See Plate o867.  Two Arm, as above. See Plate o867.  Two Arm, as above. See Plate o867.  288 00				
from base to the center of lens opening. See Plate 0887	Fig.			4
Plate 0887	1	Electro-Pneumatic Rotary Pot Signal, I foot 63/4 inches		
2 as above, 8 feet from base to the center of lens opening. See Plate o887		from base to the center of lens opening. See		
2 as above, 8 feet from base to the center of lens opening. See Plate o887		Plate 0887	100 00	
108 00   3   One Arm, 60°, Electro-Pneumatic Dwarf Signal. See   Plate 0875   82 00   164 00   165 0	2			
Plate 0875			108 00	
Plate 0875	3	One Arm, 60°, Electro-Pneumatic Dwarf Signal. See		
One Arm, 60°, Electro-Pneumatic Bridge or Bracket Signal. See Plate 0867		Plate 0875	82 00	
One Arm, 60°, Electro-Pneumatic Bridge or Bracket Signal. See Plate 0867	4	Two Arm, as above. See Plate 0877	164 00	
Signal. See Plate 0867				
7 Two Arm, as above. See Plate o867				
	7		288 00	
	8			

Fig.		Lis Pric	st ce
9	One-Arm, 60°, Electro-Pueumatic Ground Post Sig- nal. See Plate 0861	233	00
10	Two-Arm, as above. See Plate o863	354	00
II	Three-Arm, as above. See Plate o865	537	
14	One-Arm, 60°, Electro-Pneumatic Cantilever Signal,		
	dummy to right of post	262	
15	Two-Arm, as above	384	
16	Three-Arm, as above	566	00
17	One-Arm, 60°, Electro-Pneumatic Cantilever Signal, dummy to left of post	262	00
18	Two-Arm, as above	384	
19	Three-Arm, as above	566	
20	One-Arm, 60°, Electro-Pneumatic Pipe Post Bracket Signal, dummy on left hand side of post, 8 feet from top of platform to centre line of blade.	300	
	Type of main post as per Plate 0869	454	00
21	as above, dummy on right hand side of post.	454	00
22	One-Arm, 60°, Electro-Pneumatic Pipe Post Bracket Signal, dummy on left hand side of post, 14 feet from top of platform to centre line of blade.		
	Type of main post as per Plate 0869		
23	as above, dummy on right hand side of post.	464	00



The signals listed below include blades, glass, front and back spectacles, ladders and ladder foundations, anchor bolts, and all other fittings shown on the following plates.

They do not include lamps, circuit controllers, pole changers, number plates, or reservoirs, which must be ordered separately when required.


Any variations from the general dimensions shown on the following plates must be specifically called for when ordering.

Magnets are usually wound to 16, 120 and 400 ohms resistance, as per table of resistances on page 171.

v:-		List Price	
Fig.	Three-arm, 60°, Electro-Pneumatic Pipe Bracket Sig-		
3-	nal, two-arm doll on right hand side of post,		
	one-arm doll on left hand side of post. Both dolls		
	are 8 feet from top of platform to center line of		
	bottom blade. Type of main post as per Plate 0869.	719 00	
32	as above, one-arm doll on right hand side		
	of post, two-arm doll on left hand side of post	719 00	1
33	as above, one-arm doll on right hand side of		
	post, 14 feet from top of platform to center line of		
	blade; two-arm doll on left hand side of post, 8 feet		
	from top of platform to center line of bottom blade.	730 00	
34	Four-arm, 60°, Electro-Pneumatic Pipe Bracket Sig-		
	nal, two-arm doll on right hand side of post, 8		
	feet from top of platform to center line of bottom		
	blade; two-arm doll on left hand side of post, 14		
	feet from top of platform to center line of bottom		
	blade. Type of main post as per Plate 0869		
35	as above, two-arm doll on right hand side		
	of post, 14 feet from top of platform to center line		
	of bottom blade; two-arm doll on left hand side of		
	post, 8 feet from top of platform to center line of		
	bottom blade	854 00	

Fig.		List Price
36	Two-arm, 60°, Electro-Pneumatic Pipe Bracket Sig- nal, both dolls 8 feet from top of platform to center line of blade. Type of main post as per Plate 0869.	596 00
37	as above, doll on right hand side of post, 14 feet from top of platform to center line of blade; doll on left hand side of post, 8 feet from top of platform to center line of blade	608 oo
38	Three-arm, 60°, Electro-Pneumatic Pipe Bracket Sig- nal, two-arm doll on right hand side of post, one-arm doll on left hand side of post. Both dolls are 8 feet from top of platform to center line of	
39	bottom blade. Type of main post as per Plate 0869.  as above, two-arm doll on right hand side of post, 8 feet from top of platform to center line of bottom blade; one-arm doll on left hand side of post, 14 feet from top of platform to center line of	720 00
40	blade Four-Arm, 60°, Electro-Pneumatic Pipe Bracket Signal, two-arm doll on right hand side of post, two-arm doll on left hand side of post. Both dolls are	730 00
41	8 feetfrom top of platform to center line of bottom blade. Type of main post as per Plate 0869 Two-Arm, 60°, Electro-Pneumatic Pipe Bracket Sig- nal, one-arm doll on right hand side of post, one- arm doll on left hand side of post. Both dolls are	844 00
42	8 feet from top of platform to center line of blade as above, one-arm doll on right hand side of post, 14 feet from top of platform to center line of blade; one-arm doll on left hand side of post, 8	614 00
	feet from top of platform to center line of blade.	624 00

		List Price	
Fig.			
43	Three-Arm, 60°, Electro-Pneumatic Pipe Bracket Signal, two-arm doll on right hand side of post, one-arm doll on left hand side of post. Both dolls are 8 feet from top of platform to center line of bottom blade.	738 00	
44	as above, two-arm doll on right hand side of post, 8 feet from top of platform to center line of bottom blade; one-arm doll on left hand side of post, 14 feet from top of platform to center line of		
	blade	748 00	
45	Four-Arm, 60°, Electro-Pneumatic Pipe Bracket Signal, two-arm dolls on right and left hand sides of post. Both dolls are 8 feet from top of platform to cen-		
	ter line of bottom blade	860 00	
46	Two-Arm, 60°, Electro-Pneumatic Lattice Bracket Sig- nal, one-arm dolls on right and left hand sides of post; dummy on middle of post. Both dolls are 8 feet from top of platform to center line of blade.		
47	as above, dummy on right hand side of post, one-arm doll on left hand side of post, 8 feet from top of platform to center line of blade; one-arm		
	doll on middle of post, 14 feet from top of plat- form to center line of blade		
48	Three-Arm, 60°, Electro-Pneumatic Lattice Bracket Signal, one-arm dolls on left and right hand sides of post, 8 feet from top of platform to center line of blade; one-arm doll on middle of post, 14 feet		* *
49	from top of platform to center line of blade as above, one-arm dolls on left and right hand sides and middle of post, 8 feet from top of platform to center line of blade		



ONE ARM ELECTRO-PNEUMATIC GROUND SIGNALS


# ONE ARM ELECTRO-PNEUMATIC GROUND SIGNALS

The signals listed below include blades, glass, front and back spectacles ladders and ladder foundations, anchor bolts, and all other fittings shown on the opposite plate.

They do not include lamps, circuit controllers, pole changers, number plates, or reservoirs, which must be ordered separately when required. Any variation from the general dimensions shown on the opposite plate must be specifically called for when ordering.

Magnets are usually wound to 16, 120 and 400 ohms resistance, as per table of resistances on page 171.

		List Price	
Fig.		222 00	
A	One-arm, 60°, two-position home signal	233 00	
Aa	Distant signal, as above.	232 00	
Ab	One-arm, 75°, two-position home signal, Penna. R. R.		
	Standard	251 00	
Ac	as above, with pedestal	422 00	
Ad	One-arm, 75°, two-position distant signal, Penna. R.R.		
	Standard	250 00	
Ae	as above with pedestal	420 00	
Af	One-arm, 75°, three-position signal, Penna. R. R.		
23.1	Standard	333 00	
Ag	as above, with pedestal	513 00	
B	One-arm, 90°, two-position home signal		
Ba	Distant signal, as above	234 00	
Bb	One-arm, 90°, three-position signal	317 00	6 19
DD	For each foot added to the standard heights of the		
	signals shown on the opposite plate, add \$2.20		
	to list price.		
	Details of the above signals will be found on the fol-		
	lowing plates: Mechanisms, Plate 0897; Bearings		
	and Bases, Plates o899 and o901; Post Fittings,		
	Plate 0903; Front Spectacles and Blades, Plate		
	0905; Back Spectacles, Plate 0907; Circuit Con-		
	trollers, Plate 0911.	1	



TWO ARM ELECTRO-PNEUMATIC GROUND SIGNALS


# TWO ARM ELECTRO-PNEUMATIC GROUND SIGNALS

The signals listed below include blades, glass, front and back spectacles, ladders and ladder foundations, anchor bolts and all other fittings shown on the opposite plate.

They do not include lamps, circuit controllers, pole changers, number plates or reservoirs, which must be ordered separately when required. Any variation from the general dimensions shown on the opposite plate must be specifically called for when ordering.

Magnets are usually wound to 16, 120 and 400 ohms resistance, as per table of resistances on page 171.

		List Price	-		
Fig.		343 C	0	+	
A	Two-arm, 60°, two-position home and route signal	343			
Aa	Two-arm, 75°, two-position home and route signal	246 0			
	Penna. R. R. Standard	376 0			
Ab	as above, with pedestal	556 0			
Ac	Two-arm, 90°, two-position home and route signal	348 0	-		
Ad	as above, top arm three-position	430 0			
В	Two-arm, 60°, two-position home signal	354			
Ba	as above, home and distant signal	353	00		
Bb	Two-arm, 75°, two-position home signal, Penna. R. R.				
	Standard	392 (			
Bc	as above, with pedestal	572	00		
Bd	Two-arm, 75°, two-position home and distant signal,				
	Penna. R. R. Standard	391			
Be	as above, with pedestal	571	3 123		
Bf	Two-arm, 90°, two-position home signal	359			
Bg	as above, home and distant signal	358	200		
Bh	Two-arm, 90°, home signal, top arm three-position.	441	2000		
Bj	Two-arm, 90°, three-position home signal	518	00		
	For each foot added to the standard heights of the	I DE			1
	signals shown on the opposite plate, add \$2.60				1
	to list price.				ı
	Details of the above signals will be found on the fol-				ı
	lowing plates: Mechanisms, Plate 0897; Bearings				-
	and Bases, Plate o899; Post Fittings, Plate o903;				1
	Front Spectacles and Blades, Plate 0905; Back				
	Spectacles, Plate 0907; Circuit Controllers, Plate 0911				
				To an artist	



THREE ARM ELECTRO-PNEUMATIC GROUND SIGNALS


# THREE ARM ELECTRO-PNEUMATIC GROUND SIGNALS

The signals listed below include blades, glass, front and back spectacles, ladders and ladder foundations, anchor bolts and all other fittings shown on the opposite plate.

They do not include lamps, circuit controllers, pole changers, number plates or reservoirs, which must be ordered separately when required. Any variation from the general dimensions shown on the opposite plate must be specifically called for when ordering.

Magnets are usually wound to 16, 120 and 400 ohms resistance, as per table of resistances on page 171.

		I,is Pric	t e	
Fig.				
A	Three-arm, 60°, two-position home and route signal.	537	00	
Aa	Three-arm, 75°, two-position home and route signal,			
	Penna, R. R. Standard	570		
Ab	as above, with pedestal	744		
Ac	Three-arm, 90°, two-position home and route signal.	543		XII.
Ad	as above, top arm three-position	625	00	
В	Three-arm, 60°, two-position home signal	537	00	
Bb	as above, two home and one distant	536	00	
Вс	as above, one home and two distant	535	00	
Bd	Three-arm, 75°, two-position home signal, Penna.		1	
	R. R. Sandard	592	00	
Be	as above, with pedestal	750	00	
Bf	Three-arm, 75°, two-position two home and one distant,			
	Penna, R. R. Standard	591	00	
Bg	as above, with pedestal	749	00	
Bh	Three-arm, 75°, two-position one home and two distant,			
	Penna. R. R. Standard	590	00	
Bj	as above, with pedestal	748	00	
Bk	Three-arm, 90°, two-position home signal	543	oo	
Bm	as above, top arm three-position	625	00	
Bn	Three-arm, 90°, two-position two home and one			
	distant.	542	00	
Вр	as above, two distant and one home	541	00	
	For each foot added to the standard heights of the			
	signals shown on the opposite plate, add \$2 80 to list price.			
	Details of the above signals will be found on the following plates: Mechanisms, Plate 0897; Bearings and Bases, Plate 0899; Post Fittings, Plate 0903;			
	Front Spectacles and Blades, Plate 0905; Back- Spectacles, Plate 0907; Circuit Controllers, Plate 0911.			



### ONE, TWO AND THREE ARM ELECTRO-PNEUMATIC BRIDGE OR BRACKET SIGNALS


The signals listed below include blades, glass, front and back spectacles,

They do not include lamps, circuit controllers, pole changers, number plates, channel irons or reservoirs, which must be ordered separately when required. Any variation from the general dimensions shown on the opposite plate must be specifically called for when ordering.

Magnets are usually wound to 16, 120 and 400 ohms resistance, as per

table of resistances on page 171.

Fig.		List Price	
A A	One arm, 60°, two-position home signal	165 00	
Aa	Distant Signal, as above	164 00	
Ab	One-arm, 75°, two-position home signal, Penna R. R.	104 00	
12.67	Standard	165 00	
Ac	Distant signal, as above	164 00	
Ad	One-arm, 75°, three-position signal, Penna. R. R.		
	Standard	247 00	
Ae	One-arm, 90°, two-position home signal	167 00	
Af	Distant Signal, as above	166 00	
Ag	One-arm, 90°, three-position signal	249 00	
В	Two-arm, 60°, two-position home signal	288 00	
Ba	as above, home and distant	287 00	
Bb	Two-arm, 75°, two-position home signal, Penna. R. R.		
	Standard	288 00	
Bc	as above, home and distant	287 00	
Bd	Two-arm, 90°, two-position home signal	293 00	
Ве	as above, home and distant	292 00	
Bf	Two-arm, 90°, home signal, top arm three-position Two-arm, 90°, three-position home signal	375 00	
Bg	Two-arm, 90°, three-position home signal	452 00	
C	Three-arm, 60°, two-position home signal	454,00	
Ca	as above, two home and one distant	453 00	
СЪ	as above, one home and two distant	452 00	
Cc	Three-arm, 75°, two-position home signal, Penna. R.		
41	R. Standard	454 00	
Cd	as above, two home and one distant, Penna.		
C1-	R. R. Standard	453 00	
Ce	as above, one home and two distant, Penna.	450 00	
Cf	R. R. Standard	452 00	
1992	Three-arm, 90°, two-position home signal	461 00	
Cg Ch	as above, top arm three-position	543 00	
CII		460 00	
Cj	as above, two distant and one home		
CJ	For each foot added to the standard heights of the signals on the opposite plate, add \$2.20 to list price.	459 00	
	Details of the above signals will be found on the following plates: Mechanisms, Plate 0897; Bearings and Bases, Plate 0899; Post Fittings, Plate 0903; Front Spectacles and Blades, Plate 0905; Back Spectacles, Plate 0907; Circuit Controllers, Plate 0911.		




ELECTRO-PNEUMATIC BRACKET SIGNAL

### ELECTRO-PNEUMATIC BRACKET SIGNAL

Bracket signal combinations are too numerous to list. We therefore merely list below the complete main bracket post without the upper posts or fittings. By adding the prices of the posts shown on Plate o867, to the price of the main post listed below, the amount of any ordinary combination can readily be obtained. Some of the combinations most generally used are shown on Plates o857 and o859

		Price	
Fig.			
· A	Main Bracket Post, complete, with cross-trees, plat- form, channel irons, hand rails, ladder and ladder foundation, anchor bolts and pipe fittings. (No		
Aa	upper posts)	266 00	
Aa	Standard	438 00	



102

### ONE-ARM ELECTRO-PNEUMATIC SUSPENDED ROUTE SIGNAL

This signal is designed to be attached to the base of an existing bridge or bracket signal as shown on the opposite plate.

If required as a separate signal the fact must be stated when ordering,

so that a special support can be furnished.

The signals listed below include blades, glass, front and back spectacles,


anchor bolts and all other fittings shown on the opposite plate.

They do not include lamps, circuit controllers, number plates, channel irons or reservoirs, which must be ordered separately when required. Any variation from the general dimensions shown on the opposite plate must be specifically called for when ordering.

Magnets are usually wound to 16, 120 and 400 ohms resistance, as per

table of resistances on page 171.

Fig.		List Price	
A	Suspended Route Signal, 60°, two-position	120 00	
Aa-	Suspended Route Signal, 75°, two-position, Penna.R		
110	R. Standard	120 00	
Ab	as above, three-position, Penna. R. R. Standard	200 00	
Ac	Suspended Route Signal, 900, two-position	120 00	
I 2	Movement Cover, complete, with chain	10 24	
-	fastening bracket to signal base	4 02	
3	Lever only.	6 00	
3 4 5	Shaft, with cotters, for Fig. 3	14	
5	Up and Down Rod, complete, with jaw, pins, nut, and	2 00	
,	cotters	16.50	
6 6a	Post only as above, complete, with hand hole plate,	10.30	
va	handle and clamp, adjusting screw with lock nut,		
	journals, semaphore shaft with washers and cotters, semaphore crank, and lamp bracket with		6 15
	bolts and nuts	25 30	
7	Semaphore Shaft, with journals and cotters	3 90	
8	Journal for semaphore shaft	1 30	
9	Semaphore Crank Lamp Bracket, complete, with bolts and nuts	I 00	
10	Details of the above signals that are not listed above will be found on the following plates: Mechanisms, Plate 0897, Front Spectacles and Blades, Plate 0905; Back Spectacles, Plate 0907.		



60 DEGREE ELECTRO-PNEUMATIC SUSPENDED STARTING SIGNALS


# 60 DEGREE ELECTRO-PNEUMATIC SUSPENDED STARTING SIGNALS

The signals listed below include blades, glass, front spectacles, and all other fittings shown on the opposite plate.

They do not include lamps, number plates or reservoirs which must be ordered separately when required.

Magnets are usually wound to 16, 120 and 400 ohms resistance, as per table of resistances on page 171.

		List Price	
Fig.			
A	Suspended Starting Signal, for wood structure, complete, without lamp	86 00	
В	Suspended Starting Signal, for iron structure, com-		
	plete, without lamp	88 00	
D	Magnet and Valve, complete. Specify resistance when		
	ordering. (For details see Plate 0875)	30 00	
I	Post only	6 30	
2	Mechanism Cover	5 20	Man I
3	Cylinder only	6 40	
3a	as above, complete, with oil plug, base, cap,		
	gasket, piston, hollow piston rod, piston rings,		
	cage for piston rings, nut, and circuit breaker		
	complete	26 00	
4	Base Casting for wood structure	I 60	
5	Semaphore Shaft, complete, with washers and cotters.	44	
6	Front Spectacle, with rings and bolts	1 50	
7	Rubber Blade, with plate and bolts	90	
8	Connecting Link	I IO	
9	Yoke	78	
10	Up and Down Rod, with nuts	70	
II	Spring	40	2 2
12	Guide Rod	14	
13	Collar for Fig. 12.	12	
14	Stud for fastening cover to base casting	12	
15	Shaft for connecting Figs. 3 and 10	12	
17	Bolt and Nut, \( \frac{5}{8}'' \times 5\frac{1}{2}'' \), for fastening signal post to		
1/	base casting	12	
20	Clip or Gib for bolt that fastens suspended starting		
20	signal to iron structure	12	
21	Lug for mechanism cover	24	100
21	Dug for mechanism cover	~-	



ONE ARM ELECTRO-PNEUMATIC DWARF SIGNAL

# ONE ARM ELECTRO-PNEUMATIC DWARF SIGNAL

The signals listed below include blades, glass, front and back spectacles and all other fittings shown on the opposite plate.

They do not include lamps, number plates or reservoirs, which must be ordered separately when required.

Magnets are usually wound to 16, 120 and 400 ohms resistance, as per table of resistances on page 171.


Fig.		List Price	
A	One-Arm, 60° Electro-Pneumatic Dwarf Signal, com-		
	plete, without lamp, I foot 101/2 inches from base		
	to center of semaphore shaft	82 00	
Aa	as above, 90°, 2 feet 17% inches from base to		
	center of semaphore shaft	86 00	
В	Lamp for above	6 60	
I	Combined Post and Base for 60° dwarf signal	9 40	
Ia	as above, for 90° dwarf signal	10 00	
2	Mechanism Cover	I 80	
3	Cap for combined post and base	44	
4	Cap Screw, 3/8"x1", for fastening cap to base. Price		
	per hundred	3 00	
5	Lamp Bracket	24	
5a	Lamp Bracket, complete, with tap bolts, (1-5, 2-6,		
	Plate 0875)	30	
6	Tap Bolt, 3%"x 7%", for fastening lamp bracket to base.		
	Price per hundred	2 00	
7	Semaphore Shaft, with nuts, washers and cotters	80	
7a	Front Spectacle, 60°, with rings and bolts	1 76	
7b	Front Spectacle, 90°, with rings and bolts	3 70	
7c -	Back Spectacle, with ring and bolts	52	
7d	Rubber Blade, with plate and bolts	76	
8	Journal for semaphore shaft	66	TO WHENT
9	Semaphore Crank for 60° dwarf signal	46	
9a	as above, for 90° dwarf signal	46	

## ONE ARM ELECTRO-PNEUMATIC DWARF SIGNAL

Y81		I	List Price	
Fig.	He and Dame Bad assessed to the in the in-			
10	Up and Down Rod, complete, with jaw, pin, nuts and			
	cotter, for one-arm 60° signal		10	
Ioa	as above, for 90° signal	1	10	
II	Pin, %"x134", with cotter, for jaw on up and down rods		08	
12	Spring Socket, lower		08	
13	Spring Socket, upper		06	
14	Pin, 1/2"x113/16", with washers and cotters, for joining			
	semaphore crank and up and down rod		08	
15	Spring for 60° dwarf signal		40	
15a	as above for 90°, dwarf signal		40	
16	Cylinder only, with oil plug, for 60° dwarf signal	5	30	
16a	as above, complete, with cap, gasket, piston,			
	piston rings, cage for piston rings, nut, and circuit			
	breaker complete, (1-16, 1-17, 1-18, 1-21, 2-20,			
	I-19, I-22, Plate 0875)	24	00	
16b	Cylinder only, with oil plug, for 90° dwarf signal		30	
16c	as above, complete, with cap, gasket, piston,	,	5	
	piston rings, cage for piston rings, nut, and circuit			
	breaker, complete, (1-16b, 1-17, 1-18, 1-21, 2-20,			2
	1-19, 1-22, Plate 0875)	21	00	
17	Cap for Cylinder.		10	
18	Leather Gasket for cylinder cap	-	22	
19	Cage for piston rings	2	00	
20	Piston ring	2	66	
21	Piston	-		
21a	Piston, complete, with piston rings, cage for piston	2	42	
	rings and nut, (1-21, 2-20, 1-19, 1-22. Plate 0875).			
22	Nut for fastening cage for piston rings to piston	0	00	
23	Hollow Pictor Pod and Air Inlat for 600 d		36	
	Hollow Piston Rod and Air Inlet for 60° dwarf signal.		22	
23a	as above, for 90° dwarf signal		34	

# ONE ARM ELECTRO-PNEUMATIC DWARF SIGNAL

		List Price	
Fig.		2 20	
24	Valve Base	3 30	
25	Valve Body	3 08	
25a	Valve and Magnet, complete, with union, pin valve		
	and spring, armature, spring for releasing arma-		
	ture, and magnet cap. Specify resistance of mag-		
	net. (1-25, 1-32, 1-27, 1-26, 1-31, 1-30, 1-33, Plate		
	0875)		
26	Pin Valve and Spring	72	
261	Pin Valve only	38	
262	Spring only	34	
27	Union for valve body	I 72	
28	Yoke, with tap bolt and lock nut	50	
29	Stud for fastening yoke to valve base	08	
30	Spring for releasing armature	16	
31	Armature, with stem, complete	3 00	
32	Magnet only. Specify resistance	13 80	
32a	Magnet, complete, with armature, spring for releasing		
	armature, and cap. Specify resistance. (1-32, 1-31,		
	I-30, I-33, Plate 0875)	18 00	
33	Magnet Cap, with chain and plug	I 68	
331	Magnet Cap only	I 28	
332	Plug and Chain only	40	
34	Circuit Breaker Springs attached to hard rubber base,		
	complete, with binding posts and screws	I 60	
341	Circuit Breaker Spring only	24	
342	Hard Rubber Base only, for circuit breaker	70	
343	Binding Post, complete	18	
35	Hard Rubber Block, for placing under Fig. 34	34	
36	Hard Rubber Contact Block, with brass strip, and		
	screws for attaching to cylinder	I 24	
37	Tap Bolt, 3/8"x21/2", for fastening valve body to base.	04	



TWO ARM ELECTRO-PNEUMATIC DWARF SIGNAL


## TWO ARM ELECTRO-PNEUMATIC DWARF SIGNAL

The signals listed below include blades, glass, front and back spectacles, and all other fittings shown on the opposite plate.

They do not include lamps, number plates, or reservoirs which must be ordered separately when required.

Magnets are usually wound to 16, 120 and 400 ohms resistance, as per table of resistances on page 171.

Aa B	Two-Arm, 60°, Electro-Pneumatic Dwarf Signal, complete, without lamp, I foot 10½ inches from base to center line of bottom blade and I foot 10½ inches between blades  as above, 90°, 2 feet 1½ inches from base to center line of bottom blade, I foot 10½ inches between blades	164	00	
Aa B	plete, without lamp, I foot IO½ inches from base to center line of bottom blade and I foot IO½ inches between blades  as above, 90°, 2 feet 1½ inches from base to center line of bottom blade, I foot IO½ inches between blades		00	
В	to center line of bottom blade and I foot 10½ inches between blades  as above, 90°, 2 feet 1½ inches from base to center line of bottom blade, I foot 10½ inches between blades		00	
В	inches between blades  as above, 90°, 2 feet 1% inches from base to center line of bottom blade, I foot 10½ inches between blades		00	
В	as above, 90°, 2 feet 17% inches from base to center line of bottom blade, I foot 10½ inches between blades			
В	center line of bottom blade, I foot 10 1/2 inches be-			
	tween blades			
		166	00	
	Single Mechanism, complete; for details see Plate			
I	o875. Specify resistance of magnet	54	00	
	Combined Post and Base, for signal, I foot 10 1/2 inches			
	from base to center line of bottom blade	21	00	
Ia	as above, for signal, 2 feet 17/8 inches from			
	base to center line of bottom blade	22	co	
2	Cap for covering semaphore crank of bottom blade		40	
	Semaphore Bearing for top blade	3	52	
4	Cap for top bearing		44	
5	Mechanism cover	I	80	
6	Up and Down Rod, complete, with jaw, pin, nuts and			
	cotter, for bottom blade of signal, I foot 101/2 inches			
	from base to center line of bottom blade	I	10	
6a	as above, for signal, 2 feet 17% inches from			
	base to center line of bottom blade	1	22	
7	Up and Down Rod, complete, with jaw, pin, nuts and			
	cotter, for top blade of signal, I foot 101/2 inches			
	from base to center line of bottom blade	1	IO	
7a	as above, for signal, 2 feet 17% inches from			
	base to center line of bottom blade		22	
8	Front Spectacle, 60°, with rings and bolts		40	
8a	Front Spectacle, 90°, with rings and bolts		70	
9	Rubber Blade, with plate and bolts	1	10	
10	Semaphore Snaft, with nuts, washers and cotters, for		80	
	top blade		66	
Ica	Journal for semaphore shaft		00	2.19
II	Semaphore Shaft, with nuts, washers and cotters, for		60	
	bottom blade		82	
12	Back Spectacle, with ring and bolts		46	
13	Semaphore Crank for 60° dwarf signal		56	
13a	as above, for 90° dwarf signal		26	
14	Lamp Bracket		90	
	Spring for 60° dwarf signal		90	
15a	as above, for 90° dwarf signal		10	
16	Spring Socket, top		IO	1
17	Spring Socket, bottom			



ONE ARM 60 DEGREE ELECTRO-PNEUMATIC DWARF SIGNAL


# ONE ARM 60 DEGREE ELECTRO-PNEUMATIC DWARF SIGNAL

The signals listed below include blades, glass, front and back spectacles, and all other fittings shown on the opposite plate.

They do not include number plates or reservoirs, which must be ordered separately when required.

Magnets are usually wound to 16, 120 and 400 ohms resistance, as per table of resistances on page 171.

		List Pric	
ig.	D 0 D 10 1		
A	One-Arm 60° Electro-Pneumatic Dwarf Signal, com-		
	plete, electrically lighted, 3 feet 3 inches from	02	00
	base to center line of blade	92	00
Aa	as above, for oil lighting, including special	100	00
. 1	lamp One-Arm 60° Electro-Pneumatic Dwarf Signal, com-	100	00
Ab	plete, electrically lighted, 5 feet 4 inches from		
	base to center line of blade	94	00
	as above, for oil lighting, including special	94	00
1c	as above, for on righting, meruding special	102	00
	lamp		
3	Specify resistance of magnet.	54	00
	Combined Post and Base, for signal, 3 feet 3 inches	31	
	from base to center line of blade	12	00
a	as above, for signal, 5 feet 4 inches from base		
a	to center line of blade	14	50
	Mechanism Cover		80
	Lamp Cover, complete, with lens rings and lenses	6	30
a	Special Oil Lamp		50
a	Lens Ring, complete, for lamp cover, (no lens)	2	00
	Up and Down Rod, complete, with jaw, pin, nuts and		
	cotter, for signal, 3 feet 3 inches from base to		
	center line of blade	1	80
a	as above, for signal, 5 feet 4 inches from base		
	to center line of blade	2	00
	Blade, (wood)		70
I	Carriage Bolt, ¼"x1", for blade. Price per hundred	2	00
	Back Spectacle, with ring and bolts		70
	Front Spectacle with rings and bolts		30
I	Semaphore Shaft, with nuts, washers and cotters	I	22
2	Journal for semaphore shaft		66
3	Semaphore Crank, with pin, washers and cotters		52
	Lamp Socket and block	I	46
a	Lamp Socket, complete, with screws and lamps. When		
	ordering specify voltage		64
0	Plug Cut-Out, with plugs	I	36
1	Pipe for wire connections to lamps		66
12	Pipe Clamp, with screws		20



TWO ARM 60 DEGREE ELECTRO-PNEUMATIC DWARF SIGNAL

# TWO ARM 60 DEGREE ELECTRO-PNEUMATIC DWARF SIGNAL

The signals listed below include blades, glass, front and back spectacles and all other fittings shown on the opposite plate.

They do not include number plates or reservoirs, which must be ordered separately when required.

Magnets are usually wound to 16, 120 and 400 ohms resistance, as per table of resistances on page 171.


		List Price	
Fig.			
A	Two-arm, 60°, Electro-Pneumatic Dwarf Signal, complete, electrically lighted, 3 feet 6 inches from base to center line of bottom blade, I foot Io inches between center lines of blades.	200 00	
Aa	as above, for oil lighting, including special	200 00	
214	lamp	216 00	
1	Combined Post and Base		
2	Front Spectacle, with rings and bolts	1 30	
2a	Back Spectacle, with ring and bolts	70	
3	Blade, (wood)	70	
31	Carriage Bolt, ¼"x 1", for blade. Price per hundred.	2 00	
4	Semaphore Shaft, with nuts, washers and cotters	I 22	
5	Semaphore Crank	44	
6	Journal for semaphore shaft	66	
7	Pin, with washers and cotters for semaphore crank	08	Carlotte .
8	Up and Down Rod for top arm, complete, with jaw,		
	pin, nuts and cotter	2 00	

# TWO ARM 60 DEGREE ELECTRO-PNEUMATIC DWARF SIGNAL

		List Price
Fig.		
81	Up and Down Rod only	I 32
82	Lock Nut	04
83	Jaw only	50
84	Pin, 5/8" x 13/4", with cotter, for jaw Fig. 83	08
9	Up and Down Rod for bottom arm, complete, with jaw,	
	pin, nuts and cotter	I 80
10	Spring	40
II.	Spring Socket, top	06
12	Spring Socket, bottom	08
13	Hard Rubber Block for placing under Fig. 16	34
14	Lamp Cover, complete, with lens rings and lenses for	
	top lamp	6 30
14a	Special Oil Lamp, complete, for top arm	16 50
15	Lamp Socket and Block	I 46
15a	Lamp Socket and Block, complete, with screws and	
	lamps. When ordering specify voltage	2 64
16	Circuit Breaker Springs attached to hard rubber base,	
	complete, with binding posts and screws	I 60
17	Hard Rubber Contact Block, with brass strip and	
	screws for attaching to cylinder	I 24
18	Cylinder only, with oil plug	5 30
19	Nut for fastening cage for piston rings to piston	36
20	Cage for piston rings	2 00

# TWO ARM 60 DEGREE ELECTRO-PNEUMATIC DWARF SIGNAL

		List Price
Fig.		
20a 21	Piston Ring Lamp Cover, complete, with lens rings and lenses	66
2.1	for bottom lamp	6 20
2Ia	Special Oil Lamp, complete, for bottom arm	16 50
22	Cap for cylinder	1 10
22a	Leather Gasket for cylinder cap	22
23	Piston	2 42
23a	Piston, complete, with piston rings, cage for piston	
	rings and nut, (1-23, 2-20a, 1-20, 1-19, Plate 0881).	6 00
4	Tap Bolt, 3/8" x 21/2", for fastening valve body to base.	04
25	Tap Bolt, 1/2" x 2 1/2", with lock nut, for adjusting blade	06
26	Valve and Magnet, complete, as shown. Specify resistance of magnet.	30 00
27	Yoke with tap bolt and lock nut	50
8	Stud for fastening yoke to valve base	06
29	Valve Base.	3 30
30	Hollow Piston Rod and Air Inlet	22
31	Mechanism Cover	I 80
32	Pipe Clamp, with screws, for Fig. 33	26
33	Pipe for wire connections to top lamps	12
34	Pipe for wire connections to bottom lamps	62
35	Pipe Clamp, with screws, for Fig. 34	22



ONE ARM 60 DEGREE ELECTRO-PNEUMATIC DWARF SIGNAL


# ONE ARM 60 DEGREE ELECTRO-PNEUMATIC DWARF SIGNAL.

The signals listed below include blades, glass, front and back spectacles, and all other fittings shown on the opposite plate.

They do not include number plates or reservoirs, which must be ordered separately when required.

Magnets are usually wound to 16, 120 and 400 ohms resistance, as per table of resistances on page 171.

		List Price
Fig.	to but it be af Cional com	
A	One-Arm, 60°, Electro-Pneumatic Dwarf Signal, com-	
	plete, electrically lighted, I foot II inches, from	94 00
	base to center line of blade	94 00
Aa	as above, for oil lighting, including special	102 00
	lamp	102 00
В	Mechanism, complete, for details see Plate 0875.	54 00
	Specify resistance of magnet	10 60
I	Combined Post and Base	1 80
2	Mechanism Cover	
3	Lamp Cover, complete, with lens rings and lenses	6 30
за	Special Oil Lamp	16 50
4	Blade, (wood)	70
41	Carriage Bolt, ¼"x I", for blade. Price per hundred	2 00
5	Front Spectacle, with rings and bolts	I 30
6	Back Spectacle, with ring and bolts	70
7	Semaphore Shaft, with nuts, washers and cotters	I 22
7a	Journal for semaphore shaft	66
8	Semaphore Crank, with pin, washers and cotters	56
9	Up and Down Rod, complete, with jaw, pin, nuts and	
	cotters	1 40
10	Lamp Socket only	I 46
Ioa	Lamp Socket, complete, with screws and lamps.	
	When ordering specify voltage	2 64
II	Plug Cut-Out, with plugs.	
12	Lamp Bracket	
13	Filler, fastened to end of pipe for wire connections	
14	Pipe Clamp, with screws	22
15	Pipe for wire connections to lamp	32



TWO ARM 60 DEGREE ELECTRO-PNEUMATIC DWARF SIGNAL


### TWO ARM 60 DEGREE ELECTRO-PNEUMATIC DWARF SIGNAL

The signals listed below include blades, glass, front and back spectacles and all other fittings shown on the opposite plate.

They do not include number plates or reservoirs which must be ordered separately when required.

Magnets are usually wound to 16, 120 and 400 ohms resistance, as per table of resistances on page 171.

		List Price		
Fig.		11-50		
A	Two-Arm, 60°, Electro-Pneumatic Dwarf Signal, complete, electrically lighted, I foot 5¼ inches to center line of bottom blade and I foot between center lines of blades	210	00	
Aa	as above, for oil lighting, including special	224	00	
В	lamp			
	arm. Specify resistance of magnet	68	Sator	
I	Combined Post and Base	24	4000	
2	Mechanism Cover	10	00000	
3	Tap Bolt and Lock Nut for adjusting blade		06	
4	Pipe for wire connections to lamps		66	
5	Front Spectacle, with rings and bolts		30	
6 61	Blade, (wood)		50	
	hundred		00	
7	Semaphore Shaft, with nuts, washers and cotters		22	2
71	Journal for semaphore shaft		66	
72	Semaphore Crank, with pin, washers and cotters		56	
8	Back Spectacle, with ring and bolts		70	
9	Lens Ring, complete, for lamp cover. (No lens)	2	00	
10	Lamp Cover, complete, with lens rings and lenses	9	60	
Ioa	Special Oil Lamp	16	50	
IOI	Lamp Socket only	I	46	
102	Lamp Socket, complete, with screws, block and lamps. When ordering specify voltage	2	64	
****			36	
103	Plug Cut-Out, with plugs		40	100
II	Spring	4	20	
12	Mechanism Base only		80	
13	Base only, for operating shaft		-	3-33
14	Piston Rod, complete, with piston, piston rings, jaw,	8	60	
	pin and cotter		92	1000
15	Operating Crank at base of pole	2	10	
16	Up and Down Rod for top arm		00	
16a	as above, for bottom arm	-	00	
17	Spring Rod, complete, with spring socker, jaw, pm,	T	22	
-0	nut and cotter			
18	Cylinder, complete, with piston, piston rod, valve and			39/19/
	magnet. When ordering specify resistance of magnet		00	Service !
19	Magnet Cap, with plug and chain	I	68	
20	Valve and Magnet, complete, with union, pin valve and spring, armature, spring for releasing arma- ture, and magnet cap. Specify resistance of			
21	Yoke, with tap bolt and lock nut for fastening valve	30	00	
	body to valve base		50	Feb. 33
22	Union for valve body	I	72	



ELECTRO-PNEUMATIC ROTARY POT SIGNAL

# ELECTRO-PNEUMATIC ROTARY POT SIGNAL

The signal listed below does not include lamp, number plate or reservoir, which must be ordered separately when required.

Magnets are usually wound to 16, 120 and 400 ohms resistance, as per table of resistances on page 171.


		I,ist Price	
Fig.			
A	Electro-Pneumatic Rotary Pot Signal, complete, with mechanism cover, no lamp, 1 foot 6¾ inches from base to center of lens of lamp	100 00	
	For each foot added to the standard height given, add \$1.10 to list price. Maximum height 8 feet.		
В	Lamp for above		
1	Shaft	1 10	
Ia	Shaft, with cranks and bolts, (1-1, 1-2, 1-3, 1-20, 1-26,		
	Plate 0887)	6 20	
2	Crank for operating circuit controller	1 90	
3	Crank for piston and spring	3 12	
4	Cylinder Head	66	
5	Cylinder only	.6 10	+
5a	Cylinder, complete, no valve, (1-5, 1-4, 1-7, 1-6, 1-12,		
	4-8, 1-9, 1-10, 1-13, 1-14, 1-15, 2-151, 1-16, Plate		
	0887)	26 00	
6	Cylinder Base	3 64	
7	Leather Gasket for cylinder head	22	
8	Stud, with nuts for fastening head and base to cylinder,	14	
9	Piston Rod, with nut.	60	
9a	as above, with jaw, pin and cotter, (1-9, 1-10,		
	Plate 0887)	I 22	
9b	as above, with piston, complete, (1-9a, 1-13		
	I-I4, I-I5, 2-I5I, I-I6, Plate 0887)	8 90	
-10	Jaw for piston rod, with pin and cotter	66	

### ELECTRO-PNEUMATIC ROTARY POT SIGNAL

		List Price
Fig.	T1	,
101	Jaw only.	60
102	Pin, 5/8" x 13/4", for jaw Fig. 101	08
103	Split cotter, 3/16"x11/2", for pin Fig. 102. Price per	
	hundred	1 10
11	Fibre Gasket for valve body	04
12	Fibre Gasket for cylinder base	04
13	Nut for fastening cage for piston rings to piston	36
14	Cage for piston rings	2 00
15	Piston.	3 80
15a	Piston, complete, with piston rings, cage for piston	
	rings, and nuts, (1-15, 2-151, 1-14, 1-13, 1-16, Plate	
	0887)	8 40
151	Piston Ring	66
16	Ring Nut for holding piston rod in piston	70
17	Yoke, with tap bolt and lock nut for fastening valve	
	body to signal base	56
171	Tap Bolt for yoke	06
172	Lock Nut for yoke	04
18	Valve Body	4 20
18a	Valve and Magnet, complete, with union, pin valve	
	and spring, armature, spring for releasing arma-	
	ture, and magnet cap. Specify resistance of	
	magnet. (1-18, 1-25, 1-181, 1-19, 1-23, 1-24, 1-22,	
	Plate 0887)	30 00
181	Union for valve body	I 72
19	Pin Valve and Spring	72
191	Pin Valve only	38
192	Spring only	
20	Bolt and Nut, 3/8"x 21/2", countersunk head, for	34
	fastening Fig. 3 to Fig. 1. Price per hundred	6 00

# ELECTRO-PNEUMATIC ROTARY POT SIGNAL

		. 1	
		List Price	
Fig.			
21	Tap bolt, 3/8" x 1", for fastening hand hole plate to base.	2 00	
	Price per hundred.	ı 68	
22	Magnet Cap, with chain and plug	1 28	
221	Magnet Cap only		
222	Plug only.	40	*
223	Chain for plug.	3 00	
23	Armature, with stem, complete	16	
24	Spring for releasing armature	13 80	
25	Magnet only. Specify resistance		
25a	Magnet, complete, with armature, spring for releasing		
	armature, and cap. Specify resistance of magnet.	18 00	
	(1-25, 1-23, 1-24,1-22, Plate 0887) Bolt and Nut, 3/8" x 23/16", countersunk head, for fasten-		
26	ing Fig. 2 to Fig. 1. Price per hundred	6 00	
	Tap Bolt, ½"x1¼", for fastening cylinder base to sig-		
27	nal base. Price per hundred	3 00	
	Bolt, 5/8"x141/2", with nuts and washer, for spring	3	
28		26	
	Fig 29 as above, complete, with spring, spring sock-		
28a	ets, jaw, pin and cotter, (1-28, 1-29, 1-30, 1-31,		
	1-281, Plate 0887)	I 44	
	Jaw, with pin and cotter for Fig. 28	62	
281		40	
29	Spring Socket for magnet end of spring.	08	
30	Spring Socket for magnet end of spring	06	
31	Hand Hole Plate	66	£ 15
32	Mechanism Cover	4 40	,
33	Mechanism Cover	12 00	
34	Signal Base		



ELECTRO-PNEUMATIC SINGLE SLIDE SIGNAL


# ELECTRO-PNEUMATIC SINGLE SLIDE SIGNAL

The signals listed below include lenses and lamps.

They do not include number plates or reservoirs, which must be ordered separately when required.

Magnets are usually wound to 16, 120 and 400 ohms resistance, as per table of resistances on page 171.

41 Home Signal Slide, complete, with glass 5 Intermediate Post Cover, complete, with hasp 6 Hasp. } 7 Staple. \$ 8 Double Guide for slide. 9 Door, complete, with lock and knob for mechanism case. 10 Mechanism Case only. 10 Bolt and Nut, ½" x 3", for fastening post to mechanism case. Price per hundred. 11 Base. 11 Bolt and Nut, ½" x 2½", for fastening mechanism case to base. Price per hundred. 12 Lens Ring, complete, with clear lens. 11 Lens Ring, complete, with clear lens. 12	000 000
ally lighted  Aa Distant Signal, as above  B Mechanism, complete. Specify resistance.  1 Pinnacle.  2 Post.  3 Door, complete, with lock and knob for post.  4 Single Guide for slide.  41 Home Signal Slide, complete, with glass.  5 Intermediate Post Cover, complete, with hasp.  6 Hasp. }  7 Staple.  8 Double Guide for slide.  9 Door, complete, with lock and knob for mechanism case.  10 Mechanism Case only.  10 Bolt and Nut, 5%" x 3", for fastening post to mechanism case. Price per hundred.  11 Base.  11 Bolt and Nut, 34" x 2 ½", for fastening mechanism case to base. Price per hundred.  12 Lens Ring, complete, with clear lens.  13 Isola Distance.  216 68 68 68 68 68 68 68 68 68 68 68 68 68	00 00 00 00 00 20 44
Aa Distant Signal, as above.  B Mechanism, complete. Specify resistance.  Pinnacle.  Post.  Door, complete, with lock and knob for post.  Single Guide for slide.  Home Signal Slide, complete, with glass.  Intermediate Post Cover, complete, with hasp.  Hasp.  Staple.  Double Guide for slide.  Door, complete, with lock and knob for mechanism case.  Mechanism Case only.  Bolt and Nut, %" x 3", for fastening post to mechanism case. Price per hundred.  Base.  II Bolt and Nut, ¾" x 2½", for fastening mechanism case to base. Price per hundred.  Lens Ring, complete, with clear lens.	00 00 00 00 20 44
B Mechanism, complete. Specify resistance	00 00 20 44 00
Pinnacle	00 20 44 00
Door, complete, with lock and knob for post  Single Guide for slide.  I Home Signal Slide, complete, with glass  Intermediate Post Cover, complete, with hasp.  Hasp.  Staple.  Double Guide for slide.  Door, complete, with lock and knob for mechanism case.  Mechanism Case only.  Bolt and Nut, ½" x 3", for fastening post to mechanism case. Price per hundred.  Base.  Bott and Nut, ½" x 2½", for fastening mechanism case to base. Price per hundred.  Lens Ring, complete, with clear lens.	20 44 00
Joor, complete, with lock and knob for post.  Single Guide for slide.  Home Signal Slide, complete, with glass.  Intermediate Post Cover, complete, with hasp.  Hasp. {  Staple.  Double Guide for slide.  Door, complete, with lock and knob for mechanism case.  Mechanism Case only.  Bolt and Nut, 5%" x 3", for fastening post to mechanism case. Price per hundred.  Base.  II Bolt and Nut, 34" x 2½", for fastening mechanism case to base. Price per hundred.  Lens Ring, complete, with clear lens.	44
4 Single Guide for slide. 41 Home Signal Slide, complete, with glass	00
Home Signal Slide, complete, with glass  Intermediate Post Cover, complete, with hasp  Hasp. {  Staple. }  Double Guide for slide.	
5 Intermediate Post Cover, complete, with hasp	80
6 Hasp. { 7 Staple. } 8 Double Guide for slide	
7 Staple. 9 8 Double Guide for slide. 9 9 Door, complete, with lock and knob for mechanism case. 10 10 Mechanism Case only. 42 101 Bolt and Nut, 1/2 x 3", for fastening post to mechanism case. Price per hundred. 10 11 Base. 7 111 Bolt and Nut, 1/4" x 2 1/2", for fastening mechanism case to base. Price per hundred. 12 12 Lens Ring, complete, with clear lens. 1	12
8 Double Guide for slide	
9 Door, complete, with lock and knob for mechanism case. 10 Mechanism Case only.  10 Bolt and Nut, 1/2 x 3", for fastening post to mechanism  10 Case. Price per hundred.  11 Base.  11 Bolt and Nut, 1/4" x 2 1/2", for fastening mechanism  12 Case to base. Price per hundred.  13 Lens Ring, complete, with clear lens.  14	00
10 Mechanism Case only	50
case. Price per hundred.         10           11 Base.         7           111 Bolt and Nut, ¾" x 2½", for fastening mechanism case to base. Price per hundred.         12           12 Lens Ring, complete, with clear lens.         1	00
case. Price per hundred.         10           11 Base.         7           111 Bolt and Nut, ¾" x 2½", for fastening mechanism case to base. Price per hundred.         12           12 Lens Ring, complete, with clear lens.         1	
II Base. 7  III Bolt and Nut, ¾" x 2½", for fastening mechanism case to base. Price per hundred. 12  Lens Ring, complete, with clear lens. 1	00
case to base. Price per hundred	00
case to base. Price per hundred	12 13 15
12 Lens Ring, complete, with clear lens 1	00
	32
121 Lamp Socket only 1	46
122 Lamp Socket, complete, with support, screws and	
	64
	36
	66
as above, for distant signal	78
14 Indicator Blade Disc, complete, with indicator and	
	64
15 Lens Ring with sheet iron disc	80
16 Indicator Blade Disc, blank	



ELECTRO-PNEUMATIC DOUBLE SLIDE SIGNAL


#### ELECTRO-PNEUMATIC DOUBLE SLIDE SIGNAL

The signals listed below include lenses and lamps.

They do not include number plates or reservoirs, which must be ordered separately when required.

Magnets are usually wound to 16, 120 and 400 ohms resistance, as per table of resistances on page 171.

		List Price	
Fig.			
A	Double Slide, Home and Distant Signal, complete, as		
	shown, electrically lighted	310 00	
Aa	Double Slide Home Signal, complete, electrically		
	lighted	312 00	
В	Mechanism, complete, for single slide. When order-		
	ing specify resistance	68 00	
I	Pinnacle	2 00	
2	Post	26 00	
3	Door, complete, with lock and knob for post	7 20	
4	Single Guide for slide	44	
41	Home Signal Slide, complete, with glass	21 00	
5	Intermediate Post Cover, complete, with hasp	80	
6	Hasp .)	12	
7	Staple.		
8	Double Guide for slide	1 00	
81	Distant Signal Slide, complete, with glass	18 50	
9	Door, complete, with lock and knob for mechanism		- 1-975
	case	7 50	
10	Mechanism Case, only.	42 00	
101	Bolt and Nut, 58" x 3", for fastening post to mech-		
	anism case. Price per hundred	10 00	
11	Base	7 00	
III	Bolt and Nut, $\frac{3}{4}$ " x $2\frac{1}{2}$ ", for fastening mechanism		
	case to base. Price per hundred	12 00	
12	Lens Ring, complete, with clear lens	I 32	
121	Lamp Socket only	I 46	
122	Lamp Socket, complete, for home signal blade, with		347
	support, screws and lamps. When ordering specify		
	voltage	2 64	
123	as above, for distant signal		
124	Plug Cut-Out, with plugs	1 36	
13	Indicator Blade only, for home signal		-74
14	Indicator Blade Disc, complete, with home indicator	72.6	
	and connections	2 64	
15	Indicator Blade Disc, complete, with distant indicator		
	and connections	2 76	
16	Indicator Blade only, for distant signal	80	



ELECTRO-PNEUMATIC DWARF SLIDE SIGNAL


#### ELECTRO-PNEUMATIC DWARF SLIDE SIGNAL

The signal listed below includes lenses and lamps.

It does not include number plate or reservoir, which must be ordered separately when required.

Magnets are usually wound to 16, 120 and 400 ohms resistance, as per table of resistances on page 171.

		List Price
Fig.	0' 1 0''1 D 10' 1 11	
A	Single Slide Dwarf Signal, complete, as shown, elec-	
	trically lighted	118 00
В	Mechanism, complete. For details see Plate 0895.	
	When ordering specify resistance	68 00
I	Door, complete, with lock and knob	7 20
2	Indicator Blade Disc only	66
2a	Indicator Blade Disc, complete, with indicator and	
	connections	2 64
3	Lens Ring, inner	14
4	Lens Ring, outer	30
48	Lens Ring, complete, with screws and clear lens	I 32
5	Flat Head Machine Screw, ½"x7/8", for fastening	
	guide for slide to case. Price per hundred	4 00
6	Guide for slide	44
7	Adjusting Plate for indicator	26
8	Arm for operating indicator	44
81	Stud for indicator blade	14
9	Slide only	7 70
9a	Slide, complete, with glass	10 00
10	Lens (Clear)	66
II	Indicator Blade only	66
12	Split Cotter, 1/8"x3/4", for stud Fig. 81 Price per	
	hundred	1 00
13	Pinnacle	2 00
14	Mechanism Cover	2 90
15	Post only	13 00
16	Lamp Socket, complete, with support, screws and	
	lamps. When ordering specify voltage	2 64
161	Lamp Socket only	1 46
162	Plug Cut-Out, with plugs	1 36




ELECTRO-PNEUMATIC DWARF SLIDE SIGNAL MECHANISM AND DETAILS

# ELECTRO-PNEUMATIC DWARF SLIDE SIGNAL MECHANISM AND DETAILS

Magnets are usually wound to 16, 120 and 400 ohms resistance, as per table of resistances on page 171.

		List Price	
Fig.	Mechanism, complete, as shown. When ordering		
A	specify resistance	68 oc	,
I	Mechanism Base	3 50	
2	Hollow Piston Rod and Air Inlet	I 22	
3	Plug for oil hole in cylinder	12	
4	Cylinder only	7 00	)
41	Cap for cylinder	90	)
42	Leather Gasket for cylinder cap	22	2
5	Yoke, with tap bolt and lock nut for fastening valve		
	body to base	50	
6	Stud for fastening yoke to valve base	06	5
7	Piston only	2 80	
7a	Piston, complete, with piston ring and piston rod,		
	(1-7, 1-8, 1-2, Plate 0895)	5 00	
8	Piston Ring	66	5
9	Armature and Stem, complete	3 00	)
10	Spring for releasing armature	10	5
II	Magnet only. Specify resistance	13 80	)
Ha	Magnet, complete, with armature, spring for releasing		
	armature, and cap. Specify resistance. (1-11, 1-9,		
	I-Io, I-I2 Plate 0895)	18 00	0
12	Magnet Cap, with chain and plug	I 6	8
121	Magnet Cap only	I 2	8
122	Chain.		
123	rug.	4	
13	Valve Body, with union	4 2	0
13a	Valve and Magnet, complete, with union, pin valve		
	and spring, armature, spring for releasing arma-		
	ture and magnet cap. When ordering specify re-		
	sistance of magnet. (1-13, 1-11, 1-131, 1-9, 1-10,		
	1-12, Plate 0895)	30 0	0
131	Pin Valve and Spring	7	2



MECHANISMS FOR ELECTRO-PNEUMATIC HIGH SIGNALS

## MECHANISMS FOR ELECTRO-PNEUMATIC HIGH SIGNALS

Magnets are usually wound to 16, 120 and 400 ohms resistance, as per table of resistances on page 171.


		List Price	
ig.			
A	Three-Position Signal Mechanism, complete, as shown. When ordering specify resistance	130 00	
В	Two-Position Signal Mechanism, complete, as shown When ordering specify resistance	52 00	
c	Nut and Union for valve body, as shown, for a two- position signal movement or the bottom cylinder		
0	of a three-position signal movement	I 72	
E	movement	4 52	
	cylinder of a three-position signal movement Cylinder Bracket for a three-position signal move-	2 36	5
	ment	16 00	
	Top Cylinder Head for a three-position signal movement	4 80	
3	Cylinder Head and Bracket for a two-position signal	3 42	
	Cylinder, 3" x 7¾", for a two-position signal move- ment, or the bottom cylinder of a three-position		
,	signal movement	6 00	
	position signal movement	6 00	
5	Bottom Cylinder Head for a two or three-position signal movement.	66	5
7	Stud, 3%" x 934", with three nuts, for fastening head and base to cylinder of a two-position signal move- ment, or the bottom cylinder of a three-position sig-	164	
3	nal movement.  Stud, %"x7\%", and three nuts, for fastening head and bracket to the top cylinder of a three-posi-	1.	1
	tion signal movement.	1.	4

# MECHANISMS FOR ELECTRO-PNEUMATIC HIGH SIGNALS

Fig.		List Price	
9	Piston Rod for the top cylinder of a three- position signal movement	I 32	
10	Piston Rod and Lock Nut for a two-position signal movement or the bottom cylinder of a three-		
Ioa	position signal movement	56	
	I-12, Plate 0897)	I 22	
II	Jaw for Fig. 10.	60	
12	Pin and Cotter for jaw	08	
13	Washer for piston rod to cover opening in bottom cyl- inder head		
14	Ring Nut for holding piston rod in piston of top cylinder of a three-position signal move-	04	
15	Ring Nut for holding piston rod in piston for a two- position signal movement, or for the bottom cylin-	88	
	der of a three-position signal movement	70	
16	Piston Ring	66	
17	Cage for piston rings	2 00	
18	Piston only, for a two-position signal movement, or for the top or bottom cylinder of a three-position		
18a	signal movement.  Piston, complete, for a two-position signal movement, or for the bottom cylinder of a three-position signal movement, with piston rings, cage for piston rings, and nuts, (I-18, 2-16, I-17, I-15, I-19 or	3 80	
	I-20, Plate 0897)	11 60	
185	Piston, complete, for top cylinder of a three- position signal movement, with piston rings, cage for piston rings, and nuts, (1-18, 2-16, 1-17, 1-14,		
19	Nut for fastening cage for piston rings to piston, used in the two-position signal movement, or the top	12 00	
	cylinder of a three-position signal movement	36	1

# MECHANISMS FOR ELECTRO-PNEUMATIC HIGH SIGNALS


		List Price	
Fig.	Nut for fastening cage for piston rings to piston, used		
20	in the bottom cylinder of a three-position signal		
	movement	1 70	
	Gland for cylinder bracket Fig. 1.	14	
21	Spring used in stuffing box in cylinder bracket Fig. 1.	18	
22	Leather Packing for stuffing box in cylinder bracket	***	
23		14	
	Fig. 1  Nut for stuffing box in cylinder bracket Fig. 1	48	
24		06	
25 26	Oil Plug for cylinders	04	
	Leather Gasket for bottom cylinder heads	22	
27 28	Fibre Gasket for top cylinder heads	04	
	Magnet only. Specify resistance	13 80	
29	Magnet, complete, with armature, spring for releasing	13 00	
29a	armature, and cap, (1-29, 1-31, 1-30, 1-32, Plate		
		18 00	
	0897)	18 00	
30	Spring for releasing armature		
31	Armature, with stem complete	3 00 1 68	
32	Magnet Cap, with plug and chain.	1 28	
321	Magnet Cap only		
322	Plug and Chain for magnet cap	40	
33	Yoke, with tap bolt and lock nut, for fastening valve	6	
	body to signal mechanism	3 08	
34	Valve Body only	3 00	
34a	Valve and Magnet, with union, pin valve and spring,		
	armature, spring for releasing armature, and		
	magnet cap. Specify resistance of magnet. (1-34,		
	I-C, I-35, I-31, I-30, I-29, I-32, Plate 0897)	30 00	
35	Pin Valve and Spring	72	
351	Pin Valve only.	38	-
352	Pin Valve Spring only	34	
36	Pipe Connection between the top and bottom cylinders		
	of a three-position signal movement	1 70	
37	Air Inlet for the bottom cylinder of a three-position		
	signal movement	22	



PINNACLES, BEARINGS, BASES, ETC., FOR ELECTRO-PNEUMATIC HIGH SIGNALS

## PINNACLES, BEARINGS, BASES, ETC., FOR ELEC-TRO-PNEUMATIC HIGH SIGNALS

		List Pric		
Fig.				
r	Base Casting, with shafts and pipe plugs, for a three- arm bridge or ground signal	21	00	
2	Socket for six inch pipe for a three-arm bridge or bracket signal	8	80	
2a	signal	II	00	
3	Semaphore Bearing only, 60°, for the bottom arm of a three-arm signal	11	00	
3a 3b	three-arm signal as above, 75° Semaphore Bearing, 60°, complete, with hand hole plate, clamp for hand hole plate, semaphore shaft, crank, journals, separator, tap bolt with lock nut,	11		
20	set screws, and cotters as above, 75°, complete	19	6000	
3c 4	Channel Iron, 5 "x 2", for a bracket or bridge signal.	5.9	44	
5	Specify length when ordering. Price per foot Hook Bolt and Nut, I "x 1434", for fastening signal		46	
6	and channel irons to signal bridge			
	and cylinder bracket to base.	2	48	
7 8			30	
9	Bolt and Nut, I "x 334", for fastening pipe socket to base		14	
10	Mechanism Cover for a two-position signal	8	80	
108	Mechanism Cover for a three-position signal  Bolt, 7/8" x 1'-4", with nut and separator for securing eye bolt Fig. 14, to cross tree of bracket	14	30	
	signals		32	
12	Foundation Plate for I inch bolt		40	
12a	Foundation Plate for 1 1/2 inch bolt		52	
13	Bolt and Nut, I"x 3'-10", for signal foundation Bolt and Nut, I'z"x 9'-8", for signal foundation,		90	
13a	Bolt and Nut, 1½ "x 9-8", for signal foundation, with pedestal	5	00	
14	with pedestal Eye Bolt, I " x 8", for fastening signal base to cross tree of bracket signals		42	
15	Semaphore Bearing only, 60°, for one and two-arm signals, and the top and middle arms of a three-arm			
	signal	8	00	
15a	as above, 75°	8	00	
15b	Semaphore Bearing, 60°, complete, with hand hole plate, clamp for hand hole plate, shaft, crank,			
	journals, separator, tap bolt with lock nut, set	- 0		
	screws, and cotters		00	
15c 16	as above, 75°, complete	18	00	
	signal	8	80	
16a	Socket for five inch casing for a one or two-arm bridge or bracket signal		20	
17	Base Casting for a one or two-arm ground, bridge, or bracket signal, with shaft and pipe plugs	16	50	



MECHANICALLY LOCKED SEMAPHORE BEARINGS FOR ELECTRO-PNEUMATIC HIGH SIGNALS

# MECHANICALLY LOCKED SEMAPHORE BEARINGS FOR ELECTRO-PNEUMATIC HIGH SIGNALS


		List Frice
Fig.	7	
A	Mechanically Locked Semaphore Bearing, for a 90°, one or two-arm signal, complete, as shown	20 00
Aa	as above, for the bottom arm of a 90°, three- arm signal, complete	22 00
В	as above, for a 60° or 75°, one or two-arm sig- nal, complete, as shown	18 00
Ba	as above, for the bottom arm of a 60° or 75°,	21 00
	three-arm signal, complete	
I	Semaphore Bearing, for a 90°, one or two-arm signal.	8 80
Ia	as above, for the bottom arm of a 90°, three-	
14	arm signal	8 80
2	Semaphore Shaft, for a 60°, 75° or 90°, one or two-arm	
2	signal	I 22
2a	as above, for the bottom arm of a 60°, 75° or	
	90°, three-arm signal	I 22
7	Journal, for semaphore shaft for a 90°, one or two-	
3	arm signal	I 32
	as above, for the bottom arm of a 90° three-	
за	arm signal	<sub>9</sub> 2 IO
4	Pipe Plug for semaphore bearing	04

## MECHANICALLY LOCKED SEMAPHORE BEARINGS FOR ELECTRO-PNEUMATIC HIGH SIGNALS

		List   Price	
Fig.			-
5	Shaft for semaphore crank, for a one or two-arm		
	signal	10	
5a	as above, for the bottom arm of a three-arm		
	signal	08	
6	Separator for semaphore crank shaft, Fig. 5.	06	
6a	as above, for semaphore crank shaft Fig. 5a.	08	
7	Segment for semaphore shaft	1 60	
8	Segment for semaphore crank	1 50	
9	Pin, ½"x23/8", complete, with cotters for fastening		
	pawl to semaphore crank segment	14	
10	Pawl for semaphore crank segment	40	
II	Semaphore Crank	66	
12	Tap Bolt and Lock Nut, %"x 4", for adjusting sema-		
	phore	18	
13	Hand-hole Plate, for a 60°, 75° or 90°, one or two-arm		
120	signal	34	
13a	as above, for the bottom arm of a 60°, 75° or		
	90°, three-arm signal	68	
14	Clamp for hand-hole plate Fig. 13, for a one or two-		
*	arm signal	12	
14a	as above, for hand-hole plate Fig. 13a, for the		
	bottom arm of a three-arm signal	34	

## MECHANICALLY LOCKED SEMAPHORE BEARINGS FOR ELECTRO-PNEUMATIC HIGH SIGNALS

		List Price
Fig.	st c 1 -11-1lete Fig. 12 or 129	16
15	Handle for hand hole plate Fig. 13 or 13a Semaphore Bearing for a 60° or 75°, one or two-arm	
16	signal	7 50
16a	three-arm signal	11 00
17	Pawl for male half of semaphore crank	44
18	Pin, ½"x23/8", for fastening pawl to male half of	
10	semaphore crank	06
70	Female Half of semaphore crank	56
19	Bushing for female half of semaphore crank	2 10
21	Male Half of semaphore crank	1 10
22	Tap Bolt and Lock Nut, 3/"x31/4", for adjusting sema-	
22	phore	10
23	Journal for semaphore shaft for a 60° or 75°, one or two-arm signal	1 32
23a	as above, for the bottom arm of a 60° or 75°,	
-30	three-arm signal	2 10
24	Separator for semaphore shaft for a 60° or 75°, one or	
	two-arm signal	06
248	as above, for the bottom arm of a 60° or 75°,	
-400	three-arm signal	06



FITTINGS FOR ELECTRO-PNEUMATIC HIGH SIGNALS.

# FITTINGS FOR ELECTRO-PNEUMATIC HIGH SIGNALS


		List Price	
Fig.			
I	Ladder only, as shown. Specify length when ordering. Price per foot	32	
2	Ladder Foundation, complete, with bolts for fastening ladder to foundation	5 60	
3	Top Clamp, complete, as shown, for ladder, with bolts.	54	
4	Top Ladder Stay for a one-arm ground signal	76	
5	Middle Ladder Stay for a one-arm ground signal	88	
6	Bottom Ladder Stay for a one-arm ground signal	I 00	
7	Top Ladder Stay for a two-arm ground signal	76	
8	Second Ladder Stay for a two-arm ground signal	86	
9	Third Ladder Stay for a two-arm ground signal	1 00	
10	Bottom Ladder Stay for a two-arm ground signal	I IO	
II	Top Ladder Stay for a three-arm ground signal	76	
12	Second Ladder Stay for a three-arm ground signal	98	
13	Third Ladder Stay for a three-arm ground signal	I 00	
14	Fourth Ladder Stay for a three-arm ground signal	1 08	
15	Bottom Ladder Stay for a three-arm ground signal	1 18	
16	Ladder Stay for a two-arm bridge signal	82	
17	Top Ladder Stay for a three-arm bridge signal	76	
18	Bottom Ladder Stay for a three-arm bridge signal	88	
19	Top Ladder Stay for a bracket signal	90	
20	Middle Ladder Stay for a bracket signal	I I2	
21	Bottom Ladder Stay for a bracket signal	1 30	

# FITTINGS FOR ELECTRO-PNEUMATIC HIGH SIGNALS

		List Price	
Fig.			
22	Semaphore Shaft, complete, as shown, with journals and cotters, for a one or two-arm semaphore sig-		
228	nal	3 90	
23	signal	5 30	
	place of back spectacle	20	
24	Separator, as shown, for semaphore shaft for a one or two-arm semaphore signal	14	
248	as above, for the bottom arm of a three-arm signal.	24	
25	Semaphore Crank, as shown	1 00	
26	Cap Screw and Lock Nut, 3/4" x 41/2", as shown, for ad-		
	justing blade	24	
27	Outside Semaphore Stop, as shown, for the bottom arm		
	of a three-arm signal. Penna. R. R. Standard	78	
28	Nut Lock Plate, as shown, for above	12	
29	Outside Semaphore Stop, as shown, for a one or two-		
	arm signal. Penna. R. R. Standard	40	
30	Nut Lock Plate, as shown, for above.	06	
31	Lamp Bracket, as shown, used with pipe clamp Fig.		
	32, for a one or two-arm signal	52	
3Ia	as above, for the bottom arm of a three-arm		
	signal	60	

# FITTINGS FOR ELECTRO-PNEUMATIC HIGH SIGNALS

		List Price	
Fig. 32	Pipe Clamp, complete, as shown, with bolts for lamp bracket for a one or two-arm signal as above, for the bottom arm of a three-arm	I 00	
324	signal	94	
33	Lamp Bracket, as shown, for a one or two-arm signal.  Penna. R. R. Standard	5 20	
33a	as above, for the bottom arm of a three-arm signal	5 80	
34	Lever, as shown, for signal base. Penna. R. R. Stand-	I 54	
35	Lever, as shown, for signal base	1 10	
36	Shaft, as shown, for base of a one, two or three-arm	20	
	signal	30	
37 38	Pipe Plug for above	04	
	signal	14	
38a 38b	as above, for a two-arm signal	12	
300	signal	16	
39	Clamp with handle, as shown, for hand hole plate Fig. 40 for a one or two-arm signal	28	
40	Hand Hole Plate, as shown, for semaphore bearing for		
	a one or two-arm signal.  Clamp with Handle, as shown, for hand hole plate Fig.	3.4	
41	42 for the bottom arm of a three-arm signal	50	
42	Hand Hole Plate, as shown, for semaphore bearing for the bottom arm of a three-arm signal	68	




FRONT AND BACK SPECTACLES, AND SIGNAL BLADES

### FRONT AND BACK SPECTACLES AND SIGNAL BLADES

No glass included in this list.

Wood Blades are given one priming coat of white lead before shipment, unless otherwise specified.

		List Price
Fig.		
I	Three Light, 60° Spectacle, with rings and bolts, for 83%-inch glass. U. S. & S. Co's Standard	8 40
2	Four Light, 90° Spectacle, with rings and bolts, for 6½-inch glass. U. S. & S. Co's Standard	9 40
3	Three Light, 75° Spectacle, with rings and bolts, for 83%-inch glass. Penna. R. R. Standard	7 50
4	Three Light, 60° Spectacle, with rings and bolts, for 83%-inch glass. N. Y. C. & H. R. R. R. Standard.	9 00
5	Bolt and Nut, 3/8"x13/4", for fastening blade to spec-	3 00
6	tacle, used with blade plate. Price per hundred Carriage Bolt and Nut, 3/8"x11/2", for fastening blade	
,	to spectacle, Price per hundred	6 00
6a	as above, 3/8"x2". Price per hundred	7 00
7 8	Blade Plate for Figs. 12, 13 and 17	36
9	Standard Back Spectacle, with shield and bolts. Penna. R. R.	28
10	Standard. Counterweight, with shield and bolts. Penna. R. R.	2 00
	Standard	3 70
II	Rubber Dwarf Signal Blade, with plate and bolts	76
12 12a	Home Signal Blade, used with Figs. 1, 2 and 4 as above, complete, with bolts and nuts, (1-12,	2 20
12b	6-6, Plate 0905)	2 56
	nuts, and wood screw, (1-12, 1-7, 6-5, Plate 0905).	2 76
13 13a	Distant Signal Blade, used with Figs. 1, 2 and 4 as above, complete, with bolts and nuts, (1-13,	2 20
13b	6-6, Plate 0905)	2 56
14	nuts, and wood screw,(1-13, 1-7, 6-5, Plate 0905). Home Signal Blade, used with Fig. 3. Penna R. R.	2 76
14a	Standard as above, with blade plate, bolts, nuts, and	2 20
15	wood screw, (I-I4, I-8, 4-5, Plate 0905) Distant Signal Blade, used with Fig. 3. Penna R. R.	2 62
	Standard as above, with blade plate, bolts, nuts, and	2 20
15a	wood screw, (1-15, 1-8, 4-5, Plate 0905)	2 62
16	Route Signal Blade, used with Fig. 3. Penna. R. R. Standard.	2 00
16a	as above, with blade plate, bolts, nuts, and	2 12
	wood screw, (1-16, 1-8, 4-5 Plate 0905)	2 42
17	Route Signal Blade, used with Figs. 1, 2 and 4 as above, with bolts and nuts, (1-17, 6-6, Plate	2 00
17a	0905)	2 36
17b	as above, with blade plate, bolts, nuts, and wood screw, (1-17, 1-7, 6-5, Plate 0905)	2 56




FRONT AND BACK SPECTACLES FOR DWARF SIGNALS AND BACK SPECTACLES FOR HIGH SIGNALS

# FRONT AND BACK SPECTACLES FOR DWARF SIGNALS AND BACK SPECTACLES FOR HIGH SIGNALS

No glass included in this list.

			-
		List Price	
Fig.			
1	One Light, 60°, Spectacle, with ring and bolts, for 3½		
	inch glass	I 00	34
2	Three Light, 90°, Spectacle, with rings and bolts, for		
	53% inch glass	3 30	7
3	Two Light, 60°, Spectacle, with rings and bolts, for		
,	21/2 inch glass	I 40	
4	Two Light, 60°, Spectacle, (for suspended starting		
-	signal), with rings, bolts, stud, washer, and cot-		
	ter, for 5% inch glass	I 40	
5	Three Light, 90°, Spectacle, with rings and bolts, for		
3	3½ inch glass	2 00	
6	Two Light, 60°, Spectacle, with rings and bolts, for		
	53% inch glass	I 76	
P7	One Light, 60°, Spectacle (for suspended starting sig-		
7	nal), with ring, bolts, stud, washer, and cotter,		
	for 53% inch glass	I 00	
8	Two Light, 60°, Spectacle, with ring and bolts for		
0	glass No. 17	I 32	
	Two Light, 60°, Spectacle, with rings and bolts for 4		
9	inch glass	I 20	
**	Back Spectacle, 10 inch radius, with ring and bolts		
10	for 3 inch glass, used with spectacle Fig. 2,		
	Plate 0905	86	
	Back Spectacle, 5¼ inch radius, with ring and bolts,	March 1	
II	for 23% inch glass used with spectacles Figs. 5 and		
		60	
	9, Plate 0907 Back Spectacle, 6 inch radius, with ring and bolts,		
12	for 3 inch glass, used with spectacle Fig. 8,		
		84	
	Plate 9907		
. 13	bolts, for 23% inch glass, used with spectacles Figs.		
	1, 2, 3, and 6, Plate 9907	60	
	1, 2, 3, and 0, Flate 090/		
14	Back Spectacle, I foot 25% inch radius, with ring and		
	bolts, for 3 inch glass, used with spectacle Fig. 3,	I 70	
	Plate 0905		
15	Back Spectacle, I foot 5 inch radius, with ring and		
	bolts, for 3 inch glass, used with spectacle Fig. 1,	2 20	
	Plate 0905	2 20	



MOULDED SEMAPHORE GLASS


#### MOULDED SEMAPHORE GLASS

#### Made of Kopp Solid-Color Glass

All Kopp solid-color signal glass furnished by us is subject to photometric and spectroscopic tests within close limits.

The opposite plate represents the most commonly used moulded glass, which we can furnish of Kopp Solid-Color Glass on short notice.

No.	Moulded Semaphore Glass	Diam.	Red	Green	Yellow	Blue	Purple
1		23/8"	\$ 44	\$ 22	\$ 22	\$ 22	\$ 22
2		27/8"	54	28	28	28	28
3		3''	54	28	28	28	28
4.		3½"	. 66	32	32	32	32
5		3¾"	66	38	38	38	38
6		4"	66	38	38	38	38
7		43/8"	76	44	44	- 44	44
8		5"	82	54	54	54	54
9		53/8"	82	54	54	54	54
10		61/2"	1 36	76	76	76	76
11		67/8"	1 48	82	82	82	82
12		83/8"	2 04	1 36	1 36	1 36	I 36
13	P. R. R. Sema. Glass No. 3,045		I 76	76	76	76	76
14	P. R. R. Sema. Glass No. 3,047		2 16	1 08	1 08	1 08	1 08
15	N. Y. C. & H. R. R. R. Upper Sema Glass		4 06	2 04	2 04	2 04	2 04
16	N. Y. C. & H. R. R. R. Lower Sema. Glass		4 72	2 38	2 38	2 38	2 38
17	Dwarf Signal Glass		82	54	54	54	54




POLE CHANGERS AND CIRCUIT CONTROLLERS

### POLE CHANGERS AND CIRCUIT CONTROLLERS

Orders for repair parts of the instruments shown on the opposite plate should always be accompanied by samples of the parts required.

### Order by Plate, Figure and Instructions Given Above


**:		List Price	
Fig.	Combined Motion Plate Pole Changer and Circuit Controller, complete, as shown, for the Electro-Pneumatic slide signals shown in Plates o889 and o891, with motion plate to close one circuit in the clear, and one circuit in the danger position	14 50	
В	Combined Motion Plate Pole Changer and Circuit Controller, complete, as shown, for the Electro-Pneumatic dwarf slide signal shown on Plate 0893, with motion plate to close one circuit in the clear, and		
С	one circuit in the danger position	14 50	
DI	circuit closed in the danger position Combined Motion Plate Pole Changer and Circuit Controller, complete, as shown, U. S. & S. Co.'s standard, with motion plate to close one circuit in	9 40	
D2	the clear, and one circuit in the danger position.  Motion Plate Circuit Controller, complete, U. S. &	13 20	
Da	circuits in the clear, and one circuit in the danger position.	13 20	
D3	circuit in the clear, and two circuits in the danger position.  Combined Motion Plate Pole Changer and Circuit	13 20	600
D4	Combined Motion Plate Fole Changer and Changer and Controller, complete, U. S. & S. Co.'s standard, with motion plate to open circuit when signal starts to clear and operating pole changer in the		4
D5	clear position  as above, complete, for a three-position signal, U. S. & S. Co.'s standard, with motion plate to close one circuit in the clear, and one circuit in	13 20	
D6	the danger position.  as above, complete, for a two-position signal  11 S S Co's standard with motion plate	13 20	4.4
	operating circuit controller and pole changer when	13 20	
1 2	Motion Plate only for Fig. D1	90	
2 3 4 5 6	as above, for Fig. D4	90 90	
6	as above, for Fig. D6	1 90	1



HORIZONTAL ROTARY CIRCUIT CONTROLLER
(Emergency Hand Release)

# HORIZONTAL ROTARY CIRCUIT CONTROLLER (Emergency Hand Release)

		List Price	
Fig.	6-Way Horizontal Rotary Circuit Controller, complete,		
A	with padlock and cover	AY 00	
1.	4-Way, complete, as above	31 00	
Aa	Base for 4-way, as shown	25 50	
I	as above, for 6-way.	4 00	
Ia	Insulating Plate for 4-way, as shown	4 40	
2	as above, for 6-way	34	
2a	Bushing as shown, for wire openings in base.	44	
3	Cover for 4-way, as shown	04	
4		90	
5	Shaft for 4-way, as shown.	34	
5a	as above, for 6-way	44	
6	Bearing only, as shown	I 00	
7	Lever only.	90	
7a	as above, complete, with handle, screw and		
	pin	2 30	
8	Terminal Post, complete, with washers, insulating		
	bushing, and nuts	30	
9	Bolt, No. 10-32 x 3/4", with nut, washer, and insulating		
	bushing, for fastening contact spring to base	16	
10	Machine Screw, ¼" x 7/16", as shown, for fastening		
	bearing to base. Price per hundred	2 00	
II	Handle only, as shown, for lever Fig. 7	I 22	
12	Contact Spring, as shown	24	
13	Contact Band, as shown, for contact roller	16	
14	Contact Roller, as shown, for 4-way	I 44	
14a	as above, for 6-way	1 90	
15	Machine Screw, No. 6-32 x 7/16", as shown, for fasten-		
	ing contact roller to shaft. Price per hundred.	2 00	
17	Machine Screw, 5/16" x 19/16", as shown, for fast-		
	ening handle to lever. Price per hundred	8 00	
18	Spring, as shown, for fastening cover to base	22	
19	Machine Screw, No. 10-32 x 1/4", as shown, for fasten-		
	ing spring Fig. 18, to base. Price per hundred	2 00	
20	Cover for 6-way, as shown.	I 02	




HAND RELEASE CIRCUIT CONTROLLER (Wall Type)

# HAND RELEASE CIRCUIT CONTROLLER (Wall Type)

This hand release takes one minute to operate, and can be used either vertically, as shown, or horizontally.

		List Price	
Fig.	and the second s		
A	Hand Release Circuit Controller, complete, with lock	35	00
	and cover	3 7	
1	Base, as shown	3 /	
2	Tap Bolt, ¼" x 56", as shown, for fastening worm wheel bracket to base. Price per hundred	2 :	20
	Shaft, as shown, with dowel pin		50
3	Worm Wheel, as shown	5	
4	Contact Bracket, complete, with insulating plate, for		
5	worm wheel	1	84
6	Bolt, No. 10-32 x 1", complete, as shown, with nut		
0	and insulating bushing, for fastening contact		
	brackets to worm wheel		16
7	Worm Shaft, as shown	1	70
8	Wheel, complete, as shown, with handle and dowel		
0	pin	2 .	40
9	Worm Wheel Bracket, complete, as shown, with caps		
9	and screws	3	70
IO	Long Contact Spring, as shown		90
11	Worm, complete, as shown, with dowel pin.	4	50
12	Brake Wheel, complete, as shown, with dowel pin		80
13	Base only, as shown, for contact springs		44
14	Bolt, No. 10-32 x 1/8", complete, with nut, washer, in-		
	sulating bushing and washer, for fastening con-		
	tact springs, and base Fig. 13 to bracket Fig. 20.		16
15	Tap Bolt, ¼ x 5% ", as shown, for fastening bracket		
	Fig. 20 to base. Price per hundred		00
16	Short Contact Spring, as shown		90
17	Brake, complete, as shown, with spring and nuts		50
18	Machine Screw, No. 10-32 x 1/4", as shown, for		
	fastening brake to worm wheel bracket. Price		
	per hundred	100000000000000000000000000000000000000	00
19	Terminal Post, complete, with nuts, washers, insulat-		
	ing bushing and washers	10000	30
20	Bracket only, for contact springs, as shown		32
21	Cover, as shown	1	32




ELECTRO-PNEUMATIC WHISTLE AND VALVE.

### ELECTRO-PNEUMATIC WHISTLE AND VALVE

Magnets are usually wound to 16, 120 and 400 ohms resistance, as per table of resistances on page 171.


### Order by Plate, Figure, and Instructions Given Above

Fig.		List Price	
A	Whistle and Valve, complete, as shown, to sound		
	when magnet is energized. Specify resistance of		
	magnet	72 00	
Aa	as above, without whistle. Specify resistance	12 00	
	of magnet	64 00	
Ab	Whistle and Valve, complete, as shown, to sound	04 00	
	when magnet is de-energized. Specify resistance		
	of magnet.	72 00	
Ac	as above, without whistle. Specify resistance		1
	of magnet	64 00	
I	Valve Chamber, as shown, with nipple	14 50	
Ia	as above, complete, with nut, check valve,		
	spring, piston, and gaskets, (1-1, 1-7, 1-12, 1-5,		
	I-10, Plate 0917)	31 00	
2	Whistle, complete, as shown, for I inch pipe	7 50	
3	Magnet Cap, complete, as shown, with chain and plug.	I 68	
31	Magnet Cap only	I 28	
32	Chain only Plug only	40	
4	Yoke, complete, as shown, with tap bolt and lock nut,	7.	
	for fastening valve body to valve chamber		
5	Spring, as shown, for check valve	56	
6	Pin Valve and Spring, complete, as shown	46	
6I	Spring only	72	
62	Pin Valve only.	34 38	
7	Nut for valve chamber, as shown.	2 20	
8	Valve Body, as shown, with union	4 20	
8a	Valve Body and Magnet, complete, with pin valve and	4 20	
	spring, armature, spring for releasing armature.		
	and magnet cap. Specify resistance when order-		
	ing. (1-8, 1-13, 1-6, 1-9, 1-11, 1-3, Plate 0917)	30 00	
9	Armature, complete, as shown, with stem	3 00	
10	Piston, complete, as shown, with piston rings	6 60	
II	Spring for releasing armature, as shown	16	1
12	Check Valve, as shown	2 70	
13	Magnet only, as shown. Specify resistance when or-		
	dering	13 80	
13a	Magnet, complete, with armature, spring for releasing		
	armature, and cap. Specify resistance when order-	No you	
	ing. (1-13, 1-9, 1-11, 1-3, Plate 0917)	18 00	Vancous Vancou



# ELECTRO-PNEUMATIC AUTOMATIC TRAIN STOP Style "A"


I Counterweight Box only	10		
I Counterweight Box only  Ia as above, complete, with cylinder, cylinder heads, piston, piston rod, counterweight and			
as above, complete, with cylinder, cylinder heads, piston, piston rod, counterweight and			200
cover, (1-1, 1-3, 1-5, 1-6, 1-4, 1-8, 1-9, 1-2, Plate			
2 Cover, for above, complete, with hasp, hinge, pin and	40	00	
cotters	3	80	
3 Cylinder only	6	00	
4 Piston, for cylinder, complete, with cage for piston			
rings, piston rings and ring nuts	10	50	
head and cylinder to back cylinder head	2	10	
6 Back Cylinder Head, complete, with staple, gaskets,			
and bolts with nuts for fastening to box Fig. 1	3	10	
7 Guard for cylinder, complete, with lag screw and bolt.	2	32	
8 Piston Rod, complete, with screw jaw, nut, pin and			
cotter	I	90	
9 Counterweight only	13	00	
10 Shaft only	5	90	
as above, complete, with collar and set screw,			
stop arm, bearing, and bearing plate with lag			
screws	12	00	
Bearing for shaft, complete, with bolts, nuts and lock			
washers		50	
Bearing Plate, complete, with lag screws		10	有特点
Stop Arm, complete, with bolt and nuts		90	
and cotters; for operating a circuit controller	1	66	2000



ELECTRO-PNEUMATIC AUTOMATIC TRAIN STOP Style "B"

## ELECTRO-PNEUMATIC AUTOMATIC TRAIN STOP Style "B"

		List Price	
Fig.			
A	Train Stop, complete, with cover, counterweight and chain	108 00	
I	Case, as shown	9 70	
2	Cover, as shown.	5 00	
3	Cylinder only, as shown	6 00	
3a	Cylinder, complete, with heads, gaskets, piston and piston rod, and studs, (1-3, 1-5, 1-8, 1-6, 2-7, 1-4,	22.00	
4	4-9, Plate 0921) Piston and Piston Rod, complete, as shown, with cage	22 00	
41	for piston rings, piston rings, nuts, and screw jaw. Piston, only, with cage for piston rings, piston rings	9 50	
	and nuts	7 70	
42	Piston Rod only, with lock nut	I 32 80	
43 43a	Screw Jaw only	88	
5	Back Head for cylinder, complete, as shown, with oil		
6	Gasket for back cylinder head Fig. 5.	2 02	
7	Gasket for front cylinder head Fig. 8	22	
8	Front Head for cylinder	66	
9	Stud, 38" x 11", complete, as shown, with three nuts for fastening cylinder to case	14	
10	Stop Arm, as shown.	5 00	
II	Clutch, as shown.	66	
12	Shaft, as shown	2 10	Salar B
12a	Shaft, complete, with collars, bolt and rivet, (1-12, 2-15, 1-16, 1-17, Plate 0921)	3 30	
13	Spring for shaft, as shown	80	
14	Crank for shaft, complete, as shown, with dowel pin.	50	B. 30
141	Dowel pin, \(\frac{1}{4}\)" x 3\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	6 00	
15	Collar for shaft	1 00	
16	Bolt, 3\%" x 3\%", complete, as shown, with nuts, for fastening collar to shaft	06	
17	Button Head Rivet, 3/3" x 31/4", as shown, for fastening collar to shaft. Price per hundred	2 00	
18	Link only, as shown, for joining cranks, Figs. 14 and 21.	66	
18a	Link, complete, with pins and cotters, (1-18, 2-20, Plate 0921).	80	0 5
19	Pin and Cotters, 5/8" x 17/8", as shown, for screw jaw Fig. 43	08	
20	Fig. 43 Pin and Cotters, 5/8" x 2 3/16", as shown, for Figs. 18 and 24	08	
21	Crank, 12½" x 5", as shown	2 20	
22	Pin and Cotters, I" x 35%", for fastening crank Fig. 21		
23	to case	16	
	weight Fig. 24	80	
24	Counterweight, with pin Fig. 20	6 60	




RELEASE FOR ELECTRO-PNEUMATIC AUTOMATIC TRAIN STOP

# RELEASE FOR ELECTRO-PNEUMATIC AUTOMATIC TRAIN STOP

Magnets are usually wound to 16, 120 and 400 ohms resistance, as per table of resistances on page 171.

### Order by Plate, Figure, and Instructions Given Above

		List Price	
Fig.			
A	Release for Train Stop (pedestal type), complete, with door, hasp, and hinge. Specify resistance of magnet	50 00	
AI	Combined Pedestal and Case only	10 70	
В	Release for Train Stop (hanging type), complete, with door, hasp, and hinge. Specify resistance of		
	magnet	47 00 6 60	
BI	Case only	34	
I	Door, complete, as shown, with staple	1 70	
2	Staple for door.	1 450	
3	Hasp and Hinge, complete, as shown with rivet	08	
31	Hasp only	1 00	
.32	Rivet, ¼"x½". Price per nundred	18	
33	Nut only	66	
4	Stud and Nut, complete, as shown, for fastening yoke	00	
5		14	
,	Fig. 4 to case.  Magnet and Valve, complete, as shown. Specify re-	-4	
6	sistance when ordering	30 00	
61	Magnet Cap, complete, with nut, pin, and spring,		1
	(1-12, 1-10, 1-11, Plate 0923)	I 68	
62	Magnet only. Specify resistance when ordering	13 80	
63	Valve Body, with union	4 20	
7	Gasket for valve body	06	
8	Valve Base, as shown	I 32	
9	Yoke, complete, as shown, with tap bolt and lock nut,		8 7 8 3
	for fastening valve to valve base	56	
10	Pin, as shown, for emergency release	16	
11	Spring, as shown, for pin Fig. 10		0.5
12	Nut, as shown, for magnet cap.		
13	Strainer for valve union	06	
14	Machine Screw, 3/3" x3/4", as shown, for fastening valve		
	base to case. Price per hundred		
15	Key, as shown, for emergency release	1 10	
16	Cap Screw, ¼"x¾", as shown, for fastening key shaft		
	bracket to case. Price per hundred	2 00	To be your
17	Key Shaft Bracket, as shown	40	
18	Key Shaft, as shown	22	
19	Spring Support, complete, as shown, with spring	,	
	screw and rivet, for emergency release	1 10	A CONTRACTOR OF THE PARTY OF TH
20	Bushing for key shaft	. 16	



TOOLS FOR ELECTRO-PNEUMATIC CYLINDERS, VALVES, AND MAGNETS

# TOOLS FOR ELECTRO-PNEUMATIC CYLINDERS, VALVES, AND MAGNETS

Fig.		List Price	
A	Hardwood Case containing all the tools shown on the		
	opposite plate, complete	74 00	
I	Spanner Wrench for piston of switch cylinder	50	
2	Socket Wrench, with long shank, for 1/2 inch tap bolt.	70	
3	Socket Wrench for 3/8 inch tap bolt	50	
4	Wrench for removing magnet socket	5 10	
5	Spanner Wrench for stuffing box nuts of switch cylin-		
	der, and lock cylinder of switch valve	60	
6	Socket Wrench, with short shank, for ½ inch tap bolt.	50	
7	Pin Wrench for removing ring nut that fastens piston		
	rod to signal cylinder piston	3 00	
8	Eye Bolt for removing piston of switch valve	60	
9	Reseating Tool for armature stem, complete.	29 00	
10	"T" Head Screw Driver	2 10	
II	"S" Wrench for oil plug and ¼ inch hex. nut	50	
12	Angle Screw Driver	I 30	
13	"S" Wrench for oil plugs	40	17/57
14	Wrench for valve body union and magnet cap	80	
15	Wrench for piston lock nut in switch cylinder, and		
	1¼ inch hex nut	I 30	
16	Wrench for ½ inch tap bolt and nut	50	
17	Pin Wrench for packing nut of switch valve.	60	
18	Wrench for armature stem nut, and pin valve guide in		
	switch valve	50	
19	Wrench for 3/8 inch cap screw and nut	50	
20	Wrench for piston lock nut in signal cylinder	50	

# STANDARD RESISTANCES AND OPERATING VOLTAGES OF MAGNETS FOR ELECTROPNEUMATIC APPLIANCES

	APPLIANCES	Standard Resistance	Normal Operating E. M. F.	Mini- mum Operat'g E. M. F.
		OHMS	VOLTS	VOLTS
(1)	Magnets for signals usually automatic or semi-automatic.	16.	2.25	1.37
(2)	Magnets for signals usually semi-automatic or non-automatic	120.	5.65	3.75
(3)	Magnets for signals, similar to No. 2	400,	11.	7.2
(4)	Indication and lock magnets for Electro-Pneumatic machines	120.	8.	5-3
(5)	Switch valve magnets for interlocking plants.	120.	5.65	3.75
(6)	Switch valve magnets for push button plants	400.	11.	7.2

NOTE:—An external resistance of 120 ohms is inserted in the controlling circuits of all single switches at interlocking plants, to equal the total resistance of cross-over circuits where two 120-ohm operating magnets are connected in series.

Where two switches are operated from one push button, they are connected in multiple.

# INDEX

	PLATE	PAGE
Bearings, Bases, etc., for High Signals	0899	138
Bearings, Mechanically Locked; for High Signals	0901	140
Blades, Signal	0905	148
Circuit Controllers for Signals	0911	154
Circuit Controller, Hand Release	0915	158
Circuit Controller, Horizontal Rotary	0913	156
Connections, Hose	0853	80
Counterweight with shield for High Signals	0905	148
Covers for High Signal Mechanisms	0899	138
Covers for Switch Cylinders, and Switch and Lock Movements	0851	78
Cylinders, Switch; complete and in detail	0841	62
Cylinder, Switch; with valve applied to back cylinder head .	0843	68
Cylinder, Direct Acting Switch	0845	70
Fittings for High Signals	0903	144
Glass, Moulded Semaphore	0909	152
Joints, Expansion	0855	82
Layouts—		
Frogs, Movable Point, with detector bars connected in		
multiple	0819	36
Frogs, Movable Point, with detector bars connected in		
tandem	0821	38
Frogs, Movable Point, and one end of a Single Slip		
Crossing	0823	40
Slip Crossing, Double	0825	42
Slip Crossing, Single	0827	44
Switch, Single, with one detector bar.	0815	32
Switch, Single, with two detector bars.	0817	34
Switch, Single, with direct acting movement	0829	46
Switch, Single, with one detector bar and motion plate		
switch and lock movement	0831	48
Switch, Single, with two detector bars and motion plate		
switch and lock movement.	0833	50
Machine, Interlocking—		
Horizontal Roller Type	0801	4
Vertical Roller Type	0809	24
Horizontal Roller Type, Details	0803	6
Vertical Roller Type, Details.	0811	26
Horizontal or Vertical Roller Type, Details	0805	12
Locking Dogs, Track Model Details, etc	0807	18
Machine, Push Button.	0813	30
Mechanism for Dwarf Slide Signal	0895	132
Mechanisms for High Signals	0897	
Movement, Motion Plate Switch and Lock; complete and in	0097	134
detail	0839	58
Movements, Switch and Lock; with Cylinders, complete	0835	52
Movements, Switch and Lock; complete and in detail	0837	54
Pole Changers	0911	154
Release for Automatic Train Stop	0923	166
Reservoirs	0853	80

### INDEX—Continued

Signals—	PLATE	PAGE
	1 0867	98
Bracket	. 6860	100
Bridge		98
	60897	134
	0899	138
D. H. (1711.0)	0901	140
Details of High Signals.	0903	144
	0905	148
	0907	150
Di	(08==	84
Diagrams of	10859	88
	(0875	106
Dwarf, I-arm	. 1 0879	112
	(0883	118
	(0877	IIO
Dwarf, 2-arm	. 0881	114
	10885	120
Ground, I-arm	. 0861	92
Ground. 2-arm	. 0863	94
Ground, 3-arm	. 0865	96
Pot, Rotary		122
Route, Suspended	. 0871	102
Slide, Double		128
Slide, Dwarf	. 0893	130
Slide, Single		126
Starting, Suspended		104
Sockets, Pipe, for high signals	. 0899	138
Spectacles, Back; for Dwarf and High Signals	. 0907	150
Spectacle, Back; with shield for High Signals		148
Spectacles, Front; for Dwarf Signals		150
Spectacles, Front; for High Signals		148
Stop, Automatic Train; Style "A"	. 0919	162
Stop, Automatic Train; Style "B"		164
Tools for Cylinders, Valves and Magnets		168
Unions, Flange		82
Valve, Switch; complete and in detail		74
Valve, Switch; Circuit Controller and Case		72
Whistle and Valve	. 0917	160

